



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2007558  
INV Date 11/11/2020  
Reference CC4/LPC19010443/Kea3q2  
Code LPC2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SKX 8824E  
Insured Veh. GBE 1742K  
Claim No. 18/19/19/VC05/021838  
Policy No. Z18VCD5000647  
Accident Date 22/05/2019  
Inspection Date 11/06/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19010443/Kea3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 11-11-2020



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBE 1742K	<b>Veh. Inspected</b>	SKX 8824E
<b>Policy No.</b>	Z18VCD5000647	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	18/19/19/VC05/021838	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ONG LI LI	<b>Assign Date</b>	11/06/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	SUBARU FORESTER (A)	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	JF1SJGK85FG061891	<b>Colour</b>	METALLIC SILVER
<b>Odometer</b>	079411	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/55 R18	BRIDGESTONE	5 mm
<b>L/H Front Tyre</b>	225/55 R18	BRIDGESTONE	5 mm
<b>R/H Rear Tyre</b>	225/55 R18	BRIDGESTONE	5 mm
<b>L/H Rear Tyre</b>	225/55 R18	BRIDGESTONE	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	22/05/2019	<b>Inspection Date</b>	11/06/2019
<b>Survey held at</b>	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>14 Working Days</b>
-------------------------------------	------------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 8824E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	GLASS - REAR GATE	BENT	799.20	799.20
1	RUBBER - REAR GATE	NECESSARY	12.60	12.60
2	DAM RUBBER - REAR GATE GLASS	NECESSARY	14.40	14.40
1	MUD GUARD, REAR RIGHT	SERVICEABLE	57.60	-
1	MUD GUARD, REAR LEFT	SERVICEABLE	57.60	-
1	PANEL - REAR GATE	BENT	1,072.80	1,072.80
1	WEATHER STRIP - REAR GATE	DISTORTED	111.60	111.60
1	LATCH & ACTUATOR - REAR GATE	DENTED	504.00	504.00
1	STRIKER - REAR GATE	SERVICEABLE	21.60	-
1	BACK BEAM COMPLETE - REAR	BENT	288.00	288.00
1	BRACKET - REAR BUMPER SIDE, RIGHT	SERVICEABLE	14.40	-
1	BRACKET - REAR BUMPER SIDE, LEFT	SERVICEABLE	14.40	-
1	BRACKET - REAR BUMPER CORNER, RIGHT	SERVICEABLE	18.00	-
1	BRACKET - REAR BUMPER CORNER, LEFT	SERVICEABLE	18.00	-
1	COVER - REAR BUMPER	SERVICEABLE	12.60	-
1	FLOOR PAN COMPLETE - REAR, REAR	BENT	432.00	432.00
1	SKIRT COMPLETE - REAR	BENT	288.00	288.00
1	LENS & BODY - REAR COMBINATION LAMP RIGHT	SERVICEABLE	388.80	-
1	LENS & BODY - REAR COMBINATION LAMP LEFT	SERVICEABLE	388.80	-
1	REFLEX REFLECTOR ASSEMBLY - RIGHT	SERVICEABLE	20.40	-
1	REFLEX REFLECTOR ASSEMBLY - LEFT	SERVICEABLE	20.40	-
1	GARNISH ASSEMBLY - REAR GATE, B	SERVICEABLE	144.00	-
2	PROTECTOR - REAR GARNISH	SERVICEABLE	21.60	-
1	ORNAMENT	NECESSARY	79.20	79.20
1	LETTER MARK - REAR	NECESSARY	64.80	64.80
1	LETTER MARK - REAR	NECESSARY	64.80	64.80
1	EXHAUST PIPE ASSEMBLY - REAR	BENT	792.00	792.00
1	MUFFLER ASSEMBLY - RIGHT	BENT	601.20	601.20
1	MUFFLER ASSEMBLY - LEFT	BENT	601.20	601.20
2	TAIL PIPE CUTTER	SERVICEABLE	288.00	-

Report Ref No. CC4/LPC19010443/Kea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER FACE - REAR (ADDITIONAL)	BUCKLED / CRACKED	540.00	540.00
1	COVER - TANK (ADDITIONAL)	DENTED	108.00	108.00
1	SUPPORT SUB FRAME (ADDITIONAL)	BENT	144.00	144.00
1	TRIM PANEL REAR APRON CENTRE (ADDITIONAL)	DISTORTED	216.00	216.00
	LESS 20% DISCOUNT		-	-1,346.76
			8,220.00	5,387.04
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NUMBER PLATE (SN)	DENTED	45.00	45.00
1	REVERSE SENSOR - 2 EYE (SN)	DENTED	300.00	300.00
1	REAR WINDSCREEN TINTED FILM (SN)	NECESSARY	145.00	145.00
1	SUNDRIES	NECESSARY	100.00	50.00
			590.00	540.00
	<b><u>LABOUR</u></b>			
	REPAIR / REPLACE REAR BUMPER, END PANEL, TAILGATE & FLOOR PAN.		3,360.00	2,800.00
	RESPRAY REAR BUMPER, END PANEL, TAILGATE & FLOOR PAN.		2,520.00	2,100.00
	DISMANTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIR.		900.00	800.00
	REMOVE & REFIX EXHAUST.		150.00	150.00
	TRANSFER TAILGATE MECHANISM.		150.00	150.00
1	WHEEL ALIGNMENT.		200.00	200.00
	REMOVE & REFIX CARPET, SEATS TO FACILITATE REPAIRS.		400.00	280.00
	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR.		150.00	150.00
	FAULT DIAGNOSTIC.	NOT NECESSARY	235.00	-
	REMOVE & INSTALL REAR WINDSCREEN.		300.00	300.00
	TO REMOVE & REFIX FUEL TANK.		200.00	200.00
	TO CONDUCT REAR LIGHTING TEST.		50.00	50.00
	TO CONDUCT PROTECTANT COATING.	NOT NECESSARY	1,500.00	-
	TO CONDUCT ANTI RUST COATING.		580.00	290.00
			10,695.00	7,470.00

Report Ref No. CC4/LPC19010443/Kea3q2



GRAND TOTAL		19,505.00	13,397.04
RECOMMENDED COST OF REPAIRS			13,397.04

Report Ref No. CC4/LPC19010443/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 8824E

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 8824E

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 8824E

RE-INSPECTION

