

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19010447/ABA3Q2

**Date:** 16/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800156150

**Claimant**  
**Vehicle No :** SLX7962J **Insured Vehicle No :** SMG9594C

Date of Loss: 03/06/2019 Nature of Claim: TP Claim No: 5702588414SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX7962J**  
 Make & Model: OPEL INSIGNIA GRANDSPORT B15XHT, 1.5 (A) Engine No: B1172908HAKX0246  
 Reg. Date: 12/04/2018 (Man. Year: 2017) Chassis No: W0VZT6EB9J1071744  
 Colour: Black Odometer: 22988 km  
 Engine Capacity: 1490 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18  
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 8,564.80          | 5,038.90          | 3,525.90          | 41.17         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 2,110.00          | 1,030.00          | 1,080.00          | 51.18         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b>                        | <b>10,674.80</b>  | <b>6,068.90</b>   | <b>4,605.90</b>   | <b>43.15</b>  |
| <b>+ Loss of Use (4.0 x S\$70.00/day) (S\$)</b> |                   | 280.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>6,356.35</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>6,350.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 11/06/2019

Date Inspected: 11/06/2019 Inspected At:

Ace Auto Solution (kaki Bukit) (HQ)  
 23 KAKI BUKIT AVE 4, #04-01  
 (SOUTH WING)  
 Singapore 415933

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                 | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1   | 1   |          | *BOOTLID WEATHERSTRIP                       | Cut           | 190.00 FL   | *190.00 FL   |
| 2   | 1   |          | *BOOTLID LATCH                              | Not Necessary | 152.00 FL   | *- FL        |
| 3   | 1   |          | *BOOTLID STRIKER                            | Not Necessary | 53.00 FL    | *- FL        |
| 4   | 1   |          | *REAR BUMPER UPPER                          | Deformed      | 1,588.00 FL | *1,588.00 FL |
| 5   | 1   |          | *REAR BUMPER LOWER MOULDING                 | Deformed      | 450.00 FL   | *450.00 FL   |
| 6   | 1   |          | *REAR BUMPER TOWING COVER                   | Not Necessary | 102.00 FL   | *- FL        |
| 7   | 1   |          | *REAR BUMPER LH REFLECTOR                   | Cracked       | 54.00 FL    | *54.00 FL    |
| 8   | 1   |          | *REAR BUMPER RH REFLECTOR                   | Cracked       | 54.00 FL    | *54.00 FL    |
| 9   | 2   |          | *NUMBER PLATE LAMP                          | Cracked       | 62.00 FL    | *62.00 FL    |
| 10  | 1   |          | *LHR TAILLAMP                               | Not Necessary | 793.00 FL   | *- FL        |
| 11  | 1   |          | *RHR TAILLAMP                               | Not Necessary | 793.00 FL   | *- FL        |
| 12  | 1   |          | *LHR BUMPER BRACKET ,GUIDE                  | Necessary     | 90.00 FL    | *90.00 FL    |
| 13  | 1   |          | *RHR BUMPER BRACKET ,GUIDE                  | Necessary     | 90.00 FL    | *90.00 FL    |
| 14  | 1   |          | *LHR BUMPER BRACKET                         | Necessary     | 55.00 FL    | *55.00 FL    |
| 15  | 1   |          | *RHR BUMPER BRACKET                         | Necessary     | 55.00 FL    | *55.00 FL    |
| 16  | 1   |          | *REAR CENTRE BUMPER BRACKET                 | Cracked       | 65.00 FL    | *65.00 FL    |
| 17  | 1   |          | *REVERSE SENSOR WIRE HARNESS                | Not Necessary | 450.00 FL   | *- FL        |
| 18  | 1   |          | *RH REAR BUMPER ABSORBER                    | Not Necessary | 69.00 FL    | *- FL        |
| 19  | 1   |          | *LH REAR BUMPER ABSORBER                    | Not Necessary | 69.00 FL    | *- FL        |
| 20  | 1   |          | *REAR BUMPER REINFORCEMENT BAR              | Bent          | 670.00 FL   | *670.00 FL   |
| 21  | 1   |          | *REAR END PANEL                             | Repair        | 545.00 FL   | *- FL        |
| 22  | 1   |          | *REAR END PANEL TRIM                        | Not Necessary | 280.00 FL   | *- FL        |
| 23  | 1   |          | *LHR BUMPER AIR VENTILATOR                  | Not Necessary | 80.00 FL    | *- FL        |
| 24  | 1   |          | *RHR BUMPER AIR VENTILATOR                  | Not Necessary | 80.00 FL    | *- FL        |
| 25  | 1   |          | *LHR BUMPER BLIND SPOT ACTIVE SENSOR MODULE | Cracked       | 724.00 FL   | *724.00 FL   |
| 26  | 1   |          | *RHR BUMPER BLIND SPOT ACTIVE SENSOR MODULE | Cracked       | 724.00 FL   | *724.00 FL   |
| 27  | 1   |          | *REAR NUMBER PLATE                          | Cracked       | 45.00 FS    | *45.00 FS    |
| 28  | 10  |          | *REAR BUMPER CLIP                           | Necessary     | 65.00 FS    | *30.00 FS    |
| 29  | 6   |          | *REAR FENDER LINER CLIP                     | Not Necessary | 39.00 FS    | *- FS        |
| 30  | 5   |          | *REAR END PANEL TRIM CLIP                   | Not Necessary | 32.50 FS    | *- FS        |
| 31  | 4   |          | *REVERSE SENSOR                             | Damaged       | 320.00 FS   | *200.00 FS   |
| 32  | 1   |          | *REVERSE CAMERA                             | Damaged       | 480.00 FS   | *380.00 FS   |
| 33  | 1   |          | *REAR END PANEL INSULATION SEAL             | Not Necessary | 80.00 FS    | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 9,398.50 5,526.00  
**- List Item Discount on L Items 10.00/10.00% (\$\$)** 833.70 487.10

**Total Parts (\$\$)** 8,564.80 5,038.90

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars  | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |  |          |                 |                 |
| 1                              | TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS | New      | 1,000.00        | 500.00          |
| 2                              | CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA   | New      | 800.00          | 400.00          |
| 3                              | TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT   | New      | 120.00          | 0.00            |
| 4                              | TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR         | New      | 30.00           | 30.00           |
| 5                              | TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST  | New      | 80.00           | 50.00           |
| 6                              | TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST  | New      | 80.00           | 50.00           |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>2,110.00</b> | <b>1,030.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >