'-'	ASS. REC. BY:	Konnuh	ASS	IGNMEN'I	(Office)			
		Thelma chol	of _	2.0			13.52 p.m	
	Estimated Cost				Il to:			
		TP RES / OD RI		Insu	red: SLP 6758Z			
	at Workshop in	n mug prv	for Man ce	Tel: 67532112				
	Policy No. DI9M1Removo119				Claim No: CMTD 19 62824			
	Sum Insured:				Excess:			
	Make of Veh: (Client's Record) CA / REV / REP. / REV 24 HRS				D.O.A. 11-6-209 14-6-2019 H.O.D. Endorsement:			
	Date/Time: 13	(1) 225	m Person Co	ontacted:	Carmen	Vehicle IN OUT	1184	
	Date/Fime	Action/Instruction		stimate.				
		SLP 60315 -						
	P16/19-	Revised vi	a with	m IA.				

Date/Time, File Pass to?

Date/Time, File Return to?

2)

Add Fee: Site Insp (\$

S+RS, SI Interview (\$ Photos Tech. Invs (\$ Others Weekend (\$

450 11

Report Format : Lump Sum / 1.B.): (\$

TOTAL

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

LKK Auto Consultants Pte Ltd From:

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn:

Thelma Choo

Date:

17 Jun 2019

Preliminary Advice

Insured Vehicle No : SLP6252Z

TP Vehicle No

: SLG6031S

Accident Date

: 11/06/2019

Make

: TOYOTA PRIUS HYBRID

Assignment Date

: 13/06/2019

Date of Inspection

: 14/06/2019

Est. Duration of Repair

: 10.00

Inspection At

: ESTEEM PERFORMANCE PTE LTD - SIN MING (HQ)

385 SIN MING DRIVE

SINGAPORE 575718

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,850.18
Revised Amount	:S\$	6,316.88
Check Items (Estimated)	:S\$	4,078.73
Total	:S\$	10,395.61

Lump Sum Repair

:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

have your authorisation.	ly let us

)	The vehicle is uneconomical to be repaired	 you are advised to invite tender for the wreck
---	--	--

Other comments: Survey on WP

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	12 Jun 2019		13 Jun 2019 13:52 Assign				New Assign Cancel Cas	AND THE RESERVE
	Main	Ref	erence	Clai	m Details	Documer	nts	Show All
CLAIM S	UBFOLDER DE	TAILS				[Cre	ated by insu	rer]
Insured:			GROUP LTD, Co					
Main Clair		101000000	RENTALS PTE LTE		Control of Control of the Control of	4 4 101	(2010 20:00	-50
Vehicle R	eg. No.:	SLG60	SLG6031S		te of Loss:		11/06/2019 20:00 - :59	
Claim Typ	oe:	TP / C	TP / CMTD1902824		icy/Cover Note No.:		D19MTRENT000119 (Third Party Only)	
Vehicle R	eg. No. (Insured)	SLP62	SLP6252Z		icy No. (Claimant):	2.57	X	
Tanaca registros (1100 augs)				Excess:				
Repairer:					ing (HQ) 385 Sin M			
Handling	Insurer:	Sompo 4681]	Insurance Singa	spore Pte. Lt	d. (HQ) - Tel: 6461	6555 [Handled	by Thelma Ch	oo - 6322
Adjuster:		LKK AL	ito Consultants P	te Ltd (HQ)	- Tel: 6256-3561	[Final Rpt due	24/06/2019]
Driver/Cu	stodian (Insured				D, Tel: +65855090	077 Email:		
Adj Asg.	Remarks:	WS: JE	NNY 6566 2112 / 6	5753 2112				
ASSOCI	ATED MAIL REG	CEIVED				View All	Compos	se Case Mail
There are	no mail for this	case.						
⊟	SOCIATED TAS	ve			View All Searc	n Tasks Cres	ate New Task	Complete
Due Da	ate Priority	Type Task 6	roup Subject	Handler	Assigned By	Completed On	Created	On Done

MBHH19076763 / Ajax Mars Pte Ltd - Bukit Merah ENTRY DATE & TIME: 12/06/2019 16:17 SUBMITTED BY: Elizabeth Lee

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACC	DEN	T STA	TEN	ENT
				AND CAPER

12/06/2019 16:17 Date Of Report 11/06/2019 20:10 Date Of Accident

ALONG WOODLANDS AVE 2 TOWARDS RIVERSIDE RD Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SLG6031S Vehicle Registration Number

Insured/Policyholder

GRAB RENTALS PTE LTD Name Of Registered Owner

201617200G Co Reg No NOEMAIL Email Address

Mobile Phone No

OFFICE-66550005 Alternative Phone No.

Vehicle Particulars

TOYOTA Manufacturer

PRIUS HYBRID 1.8 CVT Model

Exact Purpose for which vehicle was being used at HIRE & REWARD

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

YES

Policy Number

A29114756MKF

Cover Note Number

Driver

Name of Driver

WONG BOON LEONG

S7204672B NRIC No 10/02/1972 Date Of Birth OUTDOOR Occupation 19/10/1996 Date Of Driving Pass

22 YEARS AND 7 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-94775484 Mobile Number

Fax Number Contact Number

NOEMAIL EMail Address

Address

NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

3

involved in the accident

Was any body injured in the Accident? Was any injured conveyed to hospital by YES

YES

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: PASSENGER 1

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

JURONG WEST NPC

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Refer to Police Report Ref: T/20190612/2000 lodged at Jurong West NPC. Brief Details: On 11/06/2019 at about 2010hrs, I was driving my vehicle (SLG6031S) along Woodlands Ave 2 towards Riverside Rd opposite of Innova JC. I came to a stop as there is a traffic light ahead. Suddenly I felt a strong vibration and momentum caused my car moved forward. My vehicle's head eventually hit onto vehicle (SJW5066M) which was stationary and 2 meters away from my vehicle. I then made a check and discovered that there was a vehicle (SLP6252Z) had collided onto my vehicle rear bumper with his vehicle's front bumper. My passenger was conveyed to hospital. Traffic police at scene. There is only front in-car camera in my vehicle. I will be going to see doctor later as I feel pain on my neck and shoulder area. My in-car camera's SD car was taken by traffic police.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

Remarks/ Reasons:

RETRIEVING

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLP6252Z

Vehicle Make/Model/Colour

TOYOTA COROLLA ALTIS 1.6 CVT / SILVER

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TAN HANG HWA

NRIC/Passport Number

S1373159D

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

3

Passenger 1

NAME:

: PASSENGER 1

GENDER:

Passenger 2

NAME:

: PASSENGER 2

GENDER:

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJW5066M

Vehicle Make/Model/Colour

SUZUKI APV 7-SEATER 1.6 5DR GLX AT ABS D/AIRBAG / BLUE

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MUHAMMAD SYAHID BIN SAPIUNA

NRIC/Passport Number

S8530423B

Contact Number

98551285

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

5

Passenger 1

NAME:

: PASSENGER 1

GENDER:

Passenger 2

NAME:

: PASSENGER 2

GENDER:

Passenger 3

NAME:

: PASSENGER 3

GENDER:

Passenger 4

NAME:

: PASSENGER 4

GENDER:

DETAILS OF INJURED PERSON 1

Name

WONG BOON LEONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLG6031S

Were seat belts worn?

YES

Was this injured conveyed to hospital by

NO

ambulance?

Address Postcode

DETAILS OF INJURED PERSON 2

Name

PASSENGER 1

Approximate Age Injuries Sustain

Page 3 of 23

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?


Address

Postcode

SLG6031S

YES

YES



\$ 6





T/20190612/2000

1 of 4

Report No. T/20190612/2000

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/06/2019 00:17			Vide Report No.: L/20190611/0152	Station Diary No. 2			
Informa	nt's Partici	ulars					
Name of Informant: WONG BOON LEONG			Address: APT BLK 449 JURONG WEST STREET 42 #05-210 SINGAPORE 640449				
ID Type / ID No.: NRIC NO / S7204672B			Contact No.: Home/Office: Mobile: 94775484				
Nationality: SINGAPORE CITIZEN			Email:				
Sex: Age: Date of Birth: Male 47 10/02/1972			Type of Informant: Driver				
Race: Chinese			Language: Chinese	Institution / School Name:			
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B 3 4 5 Date of Expiry:				

Type of Accident: Injury Attended by Police		Drink Drive:	Date/Time of Accident:	Type of Location Straight Road
		No	11/06/2019 20:10	
Location: Along Road 1 WOODLAND: TOWARDS R Weather:	S AVENUE 2	SITE OF INNOVA Road Surface:		
Clear		Dry		Road Speed Limit:
Clear				
Traffic Flow: One Way Type of Collis		Traffic Control: Traffic Light - Wo	PARAMETER STATE OF THE STATE OF	raffic Volume:

Vehicle No.	Туре	Make	Model	Color	Condition	No co
SJW5066M	Car	SUZUKI	APV 7- SEATER 1.6 5DR GLX AT ABS D/AIRBAG	Blue	Slightly Damaged	No of Passenger
SLG6031S	Car	ТОУОТА	PRIUS HYBRID 1.8 CVT	White	Seriously Damaged	1





2 of 4

Report No. T/20190612/2000

Police Station Of Origin:
Jurong West N.P.C

Details of Vehicle Involved

Date Treatment NIL

No. of Days granted Medical Leave

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

CONTINUATION OF REPORT

Vehicle No.	Тур	a mivolvec	Make	Model		Color Cor		ondition No of Passen		
SLP6252Z	Car		ТОУОТА	COROL ALTIS CVT		Silve	r	15 25 56 15	eriously amaged	2
Details of P	ersor	n Involved								
Any Pedestr								_	NIA	
No. of Pedes	strian	s Injured:	NIL		Use	of Ped	estrian	Cross	ing: NA	AND DESCRIPTION OF STREET
Driver			ENSEMBLE	ALCOHOL:	Sele		ID N	1000000	S85304	122B
Name		Muhammad Syahid Bin Sapiuna				ID No.		585304	236	
Related Vehicle SJW5066M (Car)						Conta	ct No.	985512	85	
Hospital/Clinic		NIL					Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL	
Date Treatment N		NIL Date D			Disch	arge	NIL	Sauce Park		
No. of Days			al Leave	NIL			Injury	NIL	In A.	
Driver	gram	ed Wiedle	Name of the last o			SH 550		MARIE .		
Name		WONG E	BOON LEONG				ID No		S72046	372B
Related Veh	nicle	e SLG6031S (Car)				Contact No.		94775484		
Hospital/Clir	linic NIL				Class of Driving Licence & Expiry Date		F - 125 125 125 125 125 125 125 125 125 125	2B,3,4,5 f Expiry: NIL		
Date Treatment		NIL		IXE DU LE	Date	e Discl	narge	NIL		Security of the second
No. of Days gran					Deg	Degree of Injury NIL				
Driver	grani	STATE OF THE PARTY			SECTION			REP.IR		
Name		Tan Han	Tan Hang Hwa				ID No.		S1373	159D
Related Veh	nicle	SLP6252Z (Car)					Contact No.		NIL	
Hospital/Clir	nic	NIL					Class Drivin Licen Expir	g		NIL f Expiry: NIL

NIL

Date Discharge

Degree of Injury | NIL

NIL





3 of 4

Report No. T/20190612/2000

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999

Brief Details.

On 11/06/2019 at about 2010hrs, I was driving my vehicle (SLG6031S) along Woodlands Ave 2 towards Riverside Rd opposite of Innova JC. I came to a stop as there is a traffic light ahead. Suddenly I felt a strong vibration and momentum caused my car moved forward. My vehicle's head eventually hit onto vehicle(SJW5066M) which was stationery and 2meteres away from my vehicle. I then made a check and discovered that there was a vehicle(SLP6252Z) had collided onto my vehicle rear bumper with his vehicle's front bumper.

CONTINUATION OF REPORT

My passenger was conveyed to hospital. Traffic police at scene. There is only front in-car camera in my vehicle. I will be going to see doctor later as I feel pain on my neck and shoulder area. My in-car camera's SD card was taken by traffic police.





4 of 4

Report No. T/20190612/2000

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 CONTINUATION OF REPORT

Tel No: 1800-2689999

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 3 SUFYANRAFIE BIN SUKAIME Light Chair Wan (I'm	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 12/06/2019 00:17
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR HIDAYU BINTE ABDUL	Classification Of Case:
SAMAD Contact No.: 65476423 Authentication Stamp	SN 126

Singapore Police Force



Scarpo:

ESTEEM PERFORMANCE PTE LTD

Repair Estimates	SLO	G 6031 S	1001 Nothers
rts (a) Cost / List Price Items	\$	19,026.90	Not Nothers Burny B&p9 & 6646.05
Plus/Less25%_	\$	4,756.73	8/14/2-
Total of Cost / List	\$	14,270.18	0070.05
(b) Nett Price Items			the Repairer of the following:
Less			To display damping and spirit painting
Total of Nett Item	-		Parts priors are subject to the manager Third party surface or a subject or Monitogui modules are a subject or control basin
(c) Special Nett Items	\$	340.00	Supplementary or the resulting and its subject to final approval from insurance a subject to final approval from insurance a subject to final approval.
tal Parts Cost	\$	14,610.18	Acknowledged by Remainer Signature:
bour	\$	4,240.00	Dela:
bour			
tal e above total will be subjected to	\$ 7% G.S.T.	18,850.18	
tal	\$ 7% G.S.T.		Kennerh
tal e above total will be subjected to	\$ 7% G.S.T.	<i>/-</i>	Kennerh
tal e above total will be subjected to Name of Surveyor	\$ 7% G.S.T.	<i>/-</i>	Kenneth LKK 18118 at
tal e above total will be subjected to Name of Surveyor Company	\$ 7% G.S.T.	<i>/-</i>	11.0
tal e above total will be subjected to Name of Surveyor Company Survey conducted on		18,	/6/19 at
tal e above total will be subjected to Name of Surveyor Company Survey conducted on Remarks By Surveyor	: authorized / i	18,	/6/19 atat
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is	authorized / i	/ \$/ is not authorized until fu	urther notice.
e above total will be subjected to Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is	authorized / i	is not authorized until fu	urther notice.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : Make & Model : Chassis No : **SLG 6031 S**

TOYOTA PRIUS JTDKB3FU503535886 Submit By

Year Manufacture : Engine No. : Carmen Lim

2016

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	Rd 1	\$200.00	S.N	
2	Rear number plate	Sn 1	\$45.00	S.N	X
3	Rear bumper	cn1 1	\$497.50		
4	Rear bumper clip	Mc 10	\$40.00		
5	Rear bumper side retainer LH	Ju 1	\$112.70		×
6	Rear bumper side retainer RH	Jan 1	\$112.70		X
7	Rear bumper sponge	1	N/A	•	
8	Rear bumper reinforcement	Ry 1	\$398.90		2
9	Rear bumper lower centre garnish	R 1	\$582.60		
10	Rear bumper lower garnish LH	ng cm 1	\$149.70		
11	Rear bumper lower garnish RH	J_ 1	\$149.70		Х
12	Rear bumper tow cover	P1 1	\$31.70		
13	Rear bumper under cover	Ju 1	\$355.20		X
14	Tail door	By 1	\$1,122.50		~
15	Tail door lock	Del 1	\$487.70		
16	Tail door emblem	M 1	\$61.70		
17	Wording "PRIUS"	Me 1	\$51.90		_
18	Wording "HYBRID"	m 1	\$55.47		_
19	Tail door Hinge LH	R 1	\$87.60		×
20	Tail Door Hinge RH	N 1	\$87.60		X
21	Tail door plate garnish	Su 1	\$782.50		X
22	Tail door glass sealant	Mer 1	\$50.00	S.N	4012
23	Tail end panel	1 1	\$596.60		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.

Spare Parts

Vehicle No.	1		SLC
		_	

G 6031 S TOYOTA PRIUS

Submit By Year Manufacture Carmen Lim 2016

Make & Model: Chassis No :

JTDKB3FU503535886

Engine No.

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish	1'm	1	\$151.60		X
25	Tail end panel garnish clip	in	10	\$35.00		Z
26	Boot weatherstrip	Sn	1	\$353.10		X
27	Tail lamp LH - UPPER	Sa	1	\$498.75		*
28	Tail lamp RH - UPPER	Ju	1	\$498.75		*
29	Tail lamp LH - LOWER	JAC	1	\$511.60		×
30	Tail lamp RH - LOWER	14	1	\$511.60		X
31	Front number plate	2,	1	\$45.00	S.N	
32	Front number plate garnish	cm	1	\$129.00		
33	Bonnet	B	1	\$812.40		<u></u>
34	Bonnet lock	n	1	\$130.00		χ
35	Bonnet hinge LH	R	1	\$57.80		×
36	Bonnet hinge RH	1	1	\$57.80		X
37	Bonnet heat insulator	Su	1	\$440.12		×
38	Bonnet heat insulator clip	n	10	\$35.00		X
39	Headlamp LH	Sin	1	\$2,531.60		7
40	Headlamp RH	Sin	1	\$2,531.60		Z Z
41	Headlamp clip	ne	10	\$40.00		X
42	Front bumper	Bu	1	\$450.80		<u> </u>
43	Front bumper clip	m	10	\$40.00		
44	Front bumper reinforcement	n	1	\$711.50		X
45	Front bumper side retainer LH	pix	1	\$107.20		
46	Front bumper side retainer RH	Sin	1	\$107.20		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :

Chassis No :

SLG 6031 S Make & Model:

TOYOTA PRIUS JTDKB3FU503535886

Submit By

Year Manufacture : Engine No. : Carmen Lim 2016

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
47	Front bumper upper grille	cm	1	\$321.90		
48	Front bumper lower grille	In	1	\$148.60		Z
49	Front bumper emblem	na	10	\$87.10		<u> </u>
50	Front bumper tow cover RH	54	1	\$25.70		X
51	Front bumper tow cover LH	5-	1	\$25.70		X
52	Front bumper sponge	su	1	\$89.81		X
53	Fog Lamp LH	Sin	1	\$910.70		X
54	Fog Lamp RH	Sn	1	\$910.70		X
55			1			
56			1			
57			1			
58			1			
59			1			
60			1			
61			1			
62			1			
63			1			
64			1			
65			1			
66			1			
67			1			
68			1			
69			1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	:	SLG 6031 S	Submit By :_	Carmen Lim
Make & Model	:	TOYOTA PRIUS	Year of Manufacture :	2016

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL,	\$1,600.00	700 - 8
	FRONT BUMPER,BONNET AND SUPPORT PANEL)		
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL,	\$1,600.00	11001
	FRONT BUMPER, BONNET AND SUPPORT PANEL)		- 6
3	To check wiring	\$50.00	401
4	To remove & refit reverse sensor	\$120.00	501
5	To tuff coat.	\$150.00	301
6	To remove & refit spare tyre, spare tyre board, carpet trim	\$150.00	601
	to assist work load.		
	Tayou		
7	To transfer door mechanism & components	\$150.00	601
8	To conduct water leakage tests to ensure proper air and	\$120.00	201
	sealing		
9	To remove & refit rear windscreen.	\$120.00	~
10	Towing fee	\$60.00	501
11	To remove & refit rear windscreen. / ow pkn	\$120.00	601

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D19MTRENT000119

Engine No:

Odometer:

Chassis No:

CS/SMO19010480/KTD3N2

2ZRR954499

231535 km

JTDKB3FU503535886

Date:

09/07/2019

REFERENCE

Handling Insurer:

Sompo Insurance Singapore Pte.

Claimant Vehicle No:

Date of Loss:

SLG6031S

11/06/2019

Insured Vehicle

No:

Policy No:

SLP6252Z

TP

Nature of Claim:

Claim No:

CMTD1902824

DESCRIPTION & IDENTIFICATION OF VEHICLE

Rea No:

SLG6031S

Make & Model:

TOYOTA PRIUS HYBRID, 1.8 CVT (A)

06/10/2016 (Man. Year: 2016)

Reg. Date: Colour:

Metallic Pearl White

1798 cc

Engine Capacity:

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

195/65R15

Yokohama 8 mm

Rear Tyre Size: Rear Left Side: 195/65R15

Front Left Side: Front Right Side:

Yokohama 8 mm

Rear Right Side:

Yokohama 9 mm Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 14.610.17	Adjuster's 4,356.05	Difference 10,254.12	Diff % 70.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	2,290.00	1,950.00	45.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,850.17	6,646.05	12,204.12	64.74
+ GST 7.00/7.00% (S\$)	1,319.51	465.22	854.29	64.74
Nett Amount (S\$)	20,169.68	7,111.27	13,058.41	64.74

INSPECTION

Date of Assignment:

13/06/2019

Date Inspected:

14/06/2019 Inspected At:

Esteem Performance Pte Ltd - Sin Ming

385 Sin Ming Drive Singapore 575718

Estimated Period of Repair:

8.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 09 Jul 2019) Part Source: MRM-SG

TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0) 144 Parts:

(Price-denominated Standard List) Repairer's Labour:

(Unsubmitted, no print-code for SLG6031S) Print Code: These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	497.50 FL	*497.50 FL
2	10		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*-FL
4	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*-FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	398.90 FL	*398.90 FL
6	1		*REAR BUMPER LOWER CENTRE GARNISH	Bent	582.60 FL	*582.60 FL
7	1		*REAR BUMPER LOWER GARNISH LH	Mtg Cracked	149.70 FL	*149.70 FL
8	1		*REAR BUMPER LOWER GARNISH RH	Serviceable	149.70 FL	*-FL
9	1		*REAR BUMPER TOW COVER	Dented	31.70 FL	*31.70 FL
10	1		*REAR BUMPER UNDER COVER	Serviceable	355.20 FL	*-FL
11	1		*TAIL DOOR	Bent		*1,122.50 FL
12	1		*TAIL DOOR LOCK	Dented	487.70 FL	*487.70 FL
13	1		*TAIL DOOR EMBLEM	Necessary	61.70 FL	*61.70 FL
14	1		*WORDING PRIUS	Necessary	51.90 FL	*51.90 FL
15	1		*WORDING HYBRID	Necessary	55.47 FL	*55.47 FL
16	1		*TAIL DOOR HINGE LH	Repair	87.60 FL	*-FL
17	1		*TAIL DOOR HINGE RH	Repair	87.60 FL	*-FL
18	1		*TAIL DOOR PLATE GARNISH	Serviceable	782.50 FL	*-FL
19	1		*TAIL END PANEL	Repair	596.60 FL	*-FL
20	1		*TAIL END PANEL GARNISH	Serviceable	151.60 FL	*-FL
21	10		*TAIL END PANEL GARNISH CLIP	Not Necessary	35.00 FL	*-FL
22	1		*BOOT WEATHERSTRIP	Serviceable	353.10 FL	*-FL
23	1		*TAIL LAMP LH-UPPER	Serviceable	498.75 FL	*-FL
24	1		*TAIL LAMP RH-UPPER	Serviceable	498.75 FL	*-FL
25	1		*TAIL LAMP LH-LOWER	Serviceable	511.60 FL	*- FL
26	1		*TAIL LAMP RH-LOWER	Serviceable	511.60 FL	*-FL
27	1		*FRONT NUMBER PLATE GARNISH	Cracked	129.00 FL	*129.00 FL *812.40 FL
28	1		*BONNET	Bent	812.40 FL	*-FL
29	1		*BONNET LOCK	Repair	130.00 FL 57.80 FL	*-FL
30	1		*BONNET HINGE LH	Repair	57.80 FL	*-FL
31	1		*BONNET HINGE RH	Repair	440.12 FL	*-FL
32	1		*BONNET HEAT INSULATOR	Serviceable	35.00 FL	*-FL
33	10		*BONNET HEAT INSULATOR CLIP	Not Necessary Serviceable	2,531.60 FL	*-FL
34	1	-	*HEADLAMP LH	Serviceable	2,531.60 FL	*-FL
35	1		*HEADLAMP RH	Not Necessary	40.00 FL	*-FL
36	10		*HEADLAMP CLIP	Buckled	450.80 FL	
37	1		*FRONT BUMPER CLIP		40.00 FL	
38	10		*FRONT BUMPER CLIP	Necessary	711.50 FL	
39	1		*FRONT BUMPER REINFORCEMENT	Repair Distorted	107.20 FL	
40	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	107.20 FL	
41	1		*FRONT BUMPER SIDE RETAINER RH *FRONT BUMPER UPPER GRILLE	Cracked	321.90 FL	
42	1		and the second s	Serviceable	148.60 FL	100
43 44	1		*FRONT BUMPER LOWER GRILLE *FRONT BUMPER EMBLEM	Necessary	87.10 FL	
44	10		*FRONT BUMPER EMBLEM	Necessary	87.10 FL	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
 45	1		*FRONT BUMPER TOW COVER RH	Serviceable	25.70 FL	*-FL
46	1		*FRONT BUMPER TOW COVER LH	Serviceable	25.70 FL	*-FL
47	1		*FRONT BUMPER SPONGE	Serviceable	89.81 FL	*-FL
48	4		*FOG LAMP LH	Serviceable	910.70 FL	*-FL
49	1		*FOG LAMP RH	Serviceable	910.70 FL	*-FL
50	1		*REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
51	4		*REAR NUMBER PLATE	Serviceable	45.00 FS	*-FS
52	1		*TAIL DOOR GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
53	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
	nchise	part. S=Spch	lett. L=ListItemDisc.	9		
				Sub Total (S\$)	19,366.90	5,713.07
			- List Item Discount on L Ite		4,756.73	1,357.02
				Total Parts (S\$)	14,610.17	4,356.05
			Report was unsubmitted durin	ng this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Red	commended Labour			Amount
No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items		00000	=00.00
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,TAIL DOOR,END PANEL,FRONT BUMPER,BONNET AND SUPPORT PANEL)	New	1,600.00	700.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, FRONT BUMPER, BONNET AND SUPPORT PANEL)	New	1,600.00	1,100.00
3	TO CHECK WIRING	New	50.00	40.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
5	TO TUFF COAT	New	150.00	30.00
6	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD	New	150.00	60.00
7	TO TRANSFER TAILGATE MECHANISM & COMPONENTS	New	150.00	60.00
8	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	20.00
9	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
10	TOWING FEE	New	60.00	50.00
11	TO REMOVE & REFIT REAR LOWER GLASS	New	120.00	60.00
	Gross Labou	r Cost (S\$)	4,240.00	2,290.00
	Report was unsubmitted during	ng this print-out.		

< END OF ESTIMATES >