

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 4816E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	692.70	-
10	REAR BUMPER CLIP (CONSISTENT)	NOT NECESSARY	40.00	-
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	SERVICEABLE	145.07	-
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	SERVICEABLE	145.07	-
1	REAR BUMPER BRACKET LH (CONSISTENT)	TO REPAIR SEE LABOUR	127.61	-
1	REAR BUMPER BRACKET RH (CONSISTENT)	TO REPAIR SEE LABOUR	127.61	-
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	68.70	-
	LESS 25% DISCOUNT		-336.69	-
			1,010.07	-
	SPECIAL NETT ITEMS			
2	REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	200.00	-
			200.00	-
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER ,LHR FENDER).	NOT NECESSARY	600.00	-
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,LHR FENDER).		600.00	220.00
	TO CHECK WIRING .	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT REVERSE SENSOR TO ASSIST WORK LOAD.	NOT NECESSARY	120.00	-
			1,370.00	220.00
	GRAND TOTAL		2,580.07	220.00
	RECOMMENDED COST OF REPAIRS			220.00

RECOMMENDED COST OF REPAIRS		220.00

Report Ref No. CC4/ASM19010502/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser