KAK Commen.

Repair Estimates

(b) Recommended Days of Repair

Resurvey

(e) Signature of surveyor

(d) Excess



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

day(s)

Date: 25/6/19

arts (a) Cost / List Price Items	\$	1,346.76	/Whait
arts (a) Cost / List Price Items	Ψ		Merry After Pa
Plus/Less25%	\$	336.69	Atte Pa
Total of Cost / List	\$	1,010.07	Date
(b) Nett Price Items	1		LKK Auto Consultants hence notify the Repairer of the following:
Less			To display damaged after spray nointing
Total of Nett Item			Third party c.
(c) Special Nett Items	\$	200.00	No illegal in ordination(s) is allow it.     Supplementary item(s usine resurveyed and is subject to final approve from Insurance Compa.
otal Parts Cost	\$	1,210.07	Acknowledged by Repairer Signature:
abour	\$	1,370.00	Date:
otal	\$	2,580.07	
The above total will be subjected to	7% G.S.T.		
			Kenney
Name of Surveyor	2		1 011474
Name of Surveyor Company			Kennery
	:		CKK 25/6/19 at

Required / Not Required

:\$

SMJ 4816 E



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

0			Pai	-
-	na	rΩ	-21	TC.
u	υa		l a	LO

Vehicle No.	:
Make & Model	:
Chassis No	:

SMJ 4816 E

TOYOTA NOAH ZWR800355258

Submit By

Year Manufacture Engine No.

Carmen Lim

2018

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	Sz	2	\$200.00	S.N	X
2	Rear bumper	n	1	\$692.70		×
3	Rear bumper clip	NA	10	\$40.00		X
4	Rear bumper side retainer LH	Sh	1	\$145.07		X
5	Rear bumper side retainer RH	Sa	1	\$145.07		X
6	Rear bumper bracket LH	n	1	\$127.61		*
7	Rear bumper bracket RH	N	1	\$127.61		×
8	Rear bumper reflector LH	Sh	1	\$68.70		X
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

	1-	_		
1 2	n	$\sim$		m
-a	u	u	···	

Vehicle No.	:	SMJ 4816 E	Submit By :	Carmen Lim
Make & Model	. –	TOYOTA NOAH	Year of Manufacture:	2018

		Price	Adjusted Price
TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT			
REPAIR AREA. (REAR BUMPER,LHR FENDER)	nr	\$600.00	X
TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT			00
REPAIR AREA. (REAR BUMPER,LHR FENDER)		\$600.00	2201
To check wiring	nn	\$50.00	X
To remove & refit reverse sensor to assist work load	m	\$120.00	×
-	REPAIR AREA. (REAR BUMPER,LHR FENDER)  TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,LHR FENDER)  To check wiring	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,LHR FENDER)  To check wiring	REPAIR AREA. (REAR BUMPER,LHR FENDER)  TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,LHR FENDER)  To check wiring  \$50.00

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.