

ASS. REC. BY:

REF:

CS/SPF 19010509/RH1302

Special Instruction:

Surveyor: RahulASSIGNMENT (Office)From (Person): Perry HE

of

SPF

Date/Time:

13/6/19 @ 9.42am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QX 4991K

Insured:

at Workshop m/s

Indeco

Tel:

9191 5725

of

39 Defu Lane 12

Policy No:

Claim No:

MH ASPF0300000113

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/6/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

401pm @ 13/6/19

Person Contacted:

PerryVehicle IN/OUT

Date/Time	Action/Instruction
	<u>Mike @ 9787 7084</u>
	<u>QX 4991K - X</u>
	<u>Submit report</u>
	<u>Part by part → 4722.24</u>
	<u>Check item \$28</u>

ASS. REC. BY:

ORI

REF:

SPF

ASSIGNMENT

From:

Date:

14/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

QX 4991K

at Workshop m/s

Indeco

of

39 Defu June 12

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

QX 4991K

Yr Regn:

2002

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan

C.C

2953

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

-

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM/H4 462520700679

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15C

R:

-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14/06/19

Survey held at

Indeco

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

kwkwok@sg.indeco.cwt.limited.com (mike)

RECEIVED 23 JUL 2019

Date/Time, File Pass to?



Preli. Report

12/7/19



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

180

180

Report Format:

OD

Lump Sum / L&L: (\$)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Nivitha (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Thursday, 13 June 2019 9:42 AM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Denise Tay (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - QX4991K

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO, with new contract rate.

Ref: MHASPF0300000113

Vehicle: QX4991K

PARTS

- 1.1 TAILGATE
- 1.2 TAILGATE HINGE RH
- 1.3 TAILGATE HINGE LH
- 1.4 TAILGATE LOCK
- 1.5 TAILGATE LOCK CATCH
- 1.6 TAILGATE TRIM BOARD
- 1.7 TAILGATE DAMPER RH
- 1.8 TAILGATE DAMPER LH
- 1.9 TAILLAMP LH
- 1.10 TAILLAMP PANEL LH
- 1.11 TAILGATE WEATHER STRIP
- 1.12 REAR BUMPER
- 1.13 REAR BUMPER CENTER BRACKET
- 1.14 REAR BUMPER CLIP 85071-01N00
- 1.15 REAR BUMPER CLIP 01553-10721
- 1.16 REAR BUMPER CLIP 85099-VW000
- 1.17 REAR BUMPER CLIP 85221-VW000
- 1.18 REAR PILLAR LOWER GARNISH LH 76939-VW110
- 1.19 REAR WINDSCREEN MOULDING (NO USE)
- 1.20 SEALANT
- 1.21 REAR END PANEL ASSY
- 1.22 REVERSE SENSOR
- 1.23 REAR WINDSCREEN WIRE MESH

Labour

TO REPLACE AND RESPRAY TAILGATE	4
TO REMOVE AND REFIX REAR WINDSCREEN	6
TO REPLACE AND RESPRAY REAR END PANEL	6
TO APPLY TUFF KOTE ON END PANEL	1
TO REMOVE AND REFIX UPHOISTERY TO ASSIST WORK	2
TO REMOVE AND REFIX REAR SEATS TO ASSIST WORK	2
TO REPAIR AND RESPRAY LHR BODY PANEL	8
TO REPLACE AND RESPRAY REAR BUMPER	5

Thanks.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Scope Of Work Home Team Agency

SCOPE OF WORK

1 to provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :		UNIT :	PROCOM	Reference No. MHA/SPF/2019/06-0027 1100025979
VEH NO :	QX4991K	MB		REPAIR TYPE:	ACCIDENT	
VEH MAKE/MODEL	NISSAN URVAN			Mileage:	115666	

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	TAILGATE <i>bwc ✓</i>	900.00	1	20%	1080.00	1080.00
1.2	TAILGATE HINGE RH <i>X nn</i>	45.00	1	20%	54.00	54.00
1.3	TAILGATE HINGE LH <i>X nn</i>	45.00	1	20%	54.00	54.00
1.4	TAILGATE LOCK <i>bt ✓</i>	230.00	1	20%	276.00	276.00
1.5	TAILGATE LOCK CATCH <i>bt ✓</i>	30.00	1	20%	36.00	36.00
1.6	TAILGATE TRIM BOARD <i>de ✓</i>	152.50	1	20%	183.00	183.00
1.7	TAILGATE DAMPER RH <i>X nn</i>	110.00	1	20%	132.00	132.00
1.8	TAILGATE DAMPER LH <i>X nn</i>	110.00	1	20%	132.00	132.00
1.9	TAILLAMP LH <i>R/Ro ✓</i>	90.00	1	20%	108.00	108.00
1.10	TAILLAMP PANEL LH <i>repair ✓</i>	280.00	1	20%	336.00	336.00
1.11	TAILGATE WEATHER STRIP <i>int ✓</i>	105.00	1	20%	126.00	126.00
1.12	REAR BUMPER <i>de ✓</i>	280.00	1	20%	336.00	336.00
1.13	REAR BUMPER CENTER BRACKET <i>✓</i>	90.00	1	20%	108.00	108.00
1.14	REAR BUMPER CLIP 85071-01N00 <i>rec ✓</i>	5.00	2	20%	6.00	12.00
1.15	REAR BUMPER CLIP 01553-10721 <i>rec ✓</i>	2.00	6	20%	2.40	14.40
1.16	REAR BUMPER CLIP 85099-VW000 <i>rec ✓</i>	8.00	2	20%	9.60	19.20
1.17	REAR BUMPER CLIP 85221-VW000 <i>rec ✓</i>	10.00	4	20%	12.00	48.00
1.18	REAR PILLAR LOWER GARNISH LH 76939-VW110 <i>den ✓</i>	304.70	1	20%	365.64	365.64
1.19	REAR WINDSCREEN MOULDING (NO USE) <i>X nn ✓</i>	0.00	0	0%	0.00	0.00
1.20	SEALANT <i>re ✓</i>	40.00	2	20%	48.00	96.00
1.21	REAR END PANEL ASSY <i>bt ✓</i>	135.00	1	20%	162.00	162.00
1.22	REVERSE SENSOR <i>re ✓</i>	100.00	1	20%	120.00	120.00
1.23	REAR WINDSCREEN WIRE MESH <i>repair bt ✓</i>	1450.00	1	20%	1740.00	1740.00
Additional Services						
Remarks:		SUBJECT TO PARTS AVAILABILTY * BY AIR 2 TO 3 WEEKS			Parts Total:	\$ 5,538.24

Registration No. QX 4991K

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Tailgate	1	Bucket	\$1,080.00	\$1,080.00	
1.2	Tailgate Hinge RH	1	Not Necessary	\$54.00		
1.3	Tailgate Hunge LH	1	Not Necessary	\$54.00		
1.4	Tailgate Lock	1	Bent	\$276.00	\$276.00	
1.5	Tailgate Lock Catch	1	Bent	\$36.00	\$36.00	
1.6	Tailgate Trim Board	1	Deformed	\$183.00	\$183.00	
1.7	Tailgate Damper RH	1	Not Necessary	\$132.00		
1.8	Tailgate Damper LH	1	Not Necessary	\$132.00		
1.9	Taillamp LH	1	Broken	\$108.00	\$108.00	
1.10	Taillamp Panel LH	1	Repair	\$336.00		
1.11	Tailgate Weather Strip	1	Cut	\$126.00	\$126.00	
1.12	Rear Bumper	1	Deformed	\$336.00	\$336.00	
1.13	Rear Bumper Center Bracket	1	Unconfirm	\$108.00	\$108.00	
1.14	Rear Bumper Clip 85071-01N00	2	Necessary	\$6.00	\$12.00	
1.15	Rear Bumper Clip 01553-10721	6	Necessary	\$2.40	\$14.40	
1.16	Rear Bumper Clip 85099-VW000	2	Necessary	\$9.60	\$19.20	
1.17	Rear Bumper Clip 85221-VW000	4	Necessary	\$12.00	\$48.00	
1.18	Rear Pillar Lower Garnish LH 76939-VW110	1	Deformed	\$365.64	\$365.64	
1.19	Rear Windscreen Moulding (NO USE)	0	Not Necessary	\$0.00		
1.20	Sealant	2	Necessary	\$48.00	\$96.00	
1.21	Rear End Panel Assy	1	Bent	\$162.00	\$162.00	
1.22	Reverse Sensor	1	Necessary	\$120.00	\$120.00	

1.23	Rear Windscreen Wire Mesh	1	Dent	\$1,740.00	\$1,740.00	
2	LABOUR DESCRIPTION					
1.1	To replace and respray tailgate					4
1.2	To remove and refix rear windscreen					6
1.3	To replace and respray rear end panel					6
1.4	To apply tuff kote on end panel					1
1.5	To remove and feix uphoistery to assist work					2
1.6	To remove and refix rear seats to assist work					2
1.7	To repair and respray LHR body Panel					8
1.8	To replace and respray rear bumper					5
0.9	To refix sensor and drill sensor hole on new bumper					0.5
COSTING			TOTAL PARTS COST		\$4,830.24	
			TOTAL MAN-HOUR			34.5



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19010509/R1td3e2		
CONTRACT MANAGEMENT SECTION(SPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 29-07-2019		
ATTN : PERRY HE		Code : SPF3		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected QX 4991K		
Policy No.		Coverage (\$) 0.00		
Claim No. MHASPF0300000113		Excess (\$) 0.00		
Assign From PERRY HE		Assign Date 13/06/2019		
2. Vehicle Particulars & Condition				
Make & Model NISSAN URVAN		c.c 2953		
Engine No. HIDDEN		Year of Reg. 2002		
Chassis No. JN1HG4E25Z0700679		Colour BLUE		
Odometer -		Steering IN ORDER		
Brakes IN ORDER		Modification NIL		
General FAIR				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date		Inspection Date 14/06/2019		
Survey held at INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139				
5a. Remarks				

Registration No. QX 4991K

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Tailgate	1	Buckled	\$1,080.00	\$1,080.00	
1.2	Tailgate Hinge RH	1	Not Necessary	\$54.00		
1.3	Tailgate Hunge LH	1	Not Necessary	\$54.00		
1.4	Tailgate Lock	1	Bent	\$276.00	\$276.00	
1.5	Tailgate Lock Catch	1	Bent	\$36.00	\$36.00	
1.6	Tailgate Trim Board	1	Deformed	\$183.00	\$183.00	
1.7	Tailgate Damper RH	1	Not Necessary	\$132.00		
1.8	Tailgate Damper LH	1	Not Necessary	\$132.00		
1.9	Taillamp LH	1	Broken	\$108.00	\$108.00	
1.10	Taillamp Panel LH	1	Repair	\$336.00		
1.11	Tailgate Weather Strip	1	Cut	\$126.00	\$126.00	
1.12	Rear Bumper	1	Deformed	\$336.00	\$336.00	
1.13	Rear Bumper Center Bracket	1	Unconfirm	\$108.00	\$108.00	
1.14	Rear Bumper Clip 85071-01N00	2	Necessary	\$6.00	\$12.00	
1.15	Rear Bumper Clip 01553-10721	6	Necessary	\$2.40	\$14.40	
1.16	Rear Bumper Clip 85099-VW000	2	Necessary	\$9.60	\$19.20	
1.17	Rear Bumper Clip 85221-VW000	4	Necessary	\$12.00	\$48.00	
1.18	Rear Pillar Lower Garnish LH 76939-VW110	1	Deformed	\$365.64	\$365.64	
1.19	Rear Windscreen Moulding (NO USE)	0	Not Necessary	\$0.00		
1.20	Sealant	2	Necessary	\$48.00	\$96.00	
1.21	Rear End Panel Assy	1	Bent	\$162.00	\$162.00	
1.22	Reverse Sensor	1	Not Working	\$120.00	\$120.00	
1.23	Rear Windscreen Wire Mesh	1	Dented	\$1,740.00	\$1,740.00	

2	LABOUR DESCRIPTION					
1.1	To replace and respray tailgate					4
1.2	To remove and refix rear windscreen					6
1.3	To replace and respray rear end panel					6
1.4	To apply tuff kote on end panel					1
1.5	To remove and feix uphoistery to assist work					2
1.6	To remove and refix rear seats to assist work					2
1.7	To repair and resparry LHR body Panel					8
1.8	To replace and respray rear bumper					5
0.9	To refix sensor and drill sensor hole on new bumper					0.5
COSTING		TOTAL PARTS COST			\$4,830.24	
		TOTAL MAN-HOUR				34.5

Registration No. QX 4991K

Vehicle Inspected By

MOHD. RASUL BIN MOHD YUNUS
 AMSOE,AMIRTE,AMSAE-A,M.MATAI
 Automotive Assessor

ADRIAN LING WAI PING
 B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
 Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.