






























Report No: 0156-19-N51

25 March 2019

ACCIDENT VEHICLE SURVEY REPORT

Vision One Pte Ltd
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

<i>Vehicle Reg No</i>	SJY2916U	<i>Odometer</i>	132572km
<i>Make & Model</i>	Toyota Lexus IS250	<i>Colour</i>	White
<i>Chassis number</i>	JTHBK262702014133	<i>Date of accident</i>	11/09/2018
<i>Year of Regn</i>	25/08/2006	<i>Date inspected</i>	13/09/2018
<i>Repairer at</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair)</i>	18/09/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.





