

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Elaine Chung of CTI

Date/Time: 14.6.19 14:14 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 72594

Insured: GBB 75615

at Workshop m/s: Chang Hoi Motor
of BIK 1019 # 01-374/382 Yishun

Tel: 6755 6142

Policy No: DMCRSA 50098219000

Claim No: SNM 1911202474

Sum Insured:

Excess:

Make of Veh:

D.O.A. 1.6.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.6.19 2.23 p.m

Person Contacted: Sida

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 72594 - X
	GBB 75615 - CS/CTI 19009693 / EVD3 DOA - 02/05/2019
25/7/19	@ 3:19pm ESpeeda will check
5/8/19	Final fig \$ 2091.11 confirmed by email (Ref 84, 49)

ASS. REC. BY:

REF: 072 /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1-B4 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 72594 Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 7m Axiom c.c. 1496

Colour: B. Pike A/C: Insured / Std / NI / NA

Sp. Reading: 5197 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NRE 161. 0038506

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: Habilar 195/60R15

R: Yokco

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 1/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

25/08/19 cool checked

RECEIVED 06 AUG 2019

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Memorandum

Lump Sum / I.B.I. (\$)

2091.11

2) 6/8 - typist

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jun 2019 Sendback Est	14 Jun 2019 11:18 S\$2,175.11	14 Jun 2019 14:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	THREE60 SYSTEM PTE LTD, Co. Reg. No.: 201708114K								
Main Claimant:	PECK CHIN HUAT, ID: S01965401								
Vehicle Reg. No.:	SLU7259Y	Date of Loss:	01/06/2019 09:00 - :59 [17 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202478-CHEONGML	Policy/Cover Note No.:	DMCVSN30098219000						
Vehicle Reg. No. (Insured):	G8B7561S	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/06/2019]								
Driver/Custodian (Insured):	ARUMUGAM CHELLAIAH (/ Male) , NRIC: G2304838N Email:								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/06/2019 10:10
Date Of Accident	01/06/2019 09:20
Exact Location Of Accident	WOODLANDS AVE 9
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU7259Y
Insured/Policyholder	
Name Of Registered Owner	PECK CHIN HUAT
NRIC No	S0196540I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97304050
Alternative Phone No	OFFICE-97304050

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	DRIVING TUITION
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR


Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096392063-01
Cover Note Number	EXP 11/12/19

Driver

Name of Driver	KANNA
NRIC No	S2718263A
Date Of Birth	07/12/1956
Occupation	INDOOR
Date Of Driving Pass	01/06/2019
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98436263
Fax Number	
Contact Number	
EMail Address	NOEMAIL

SKETCH PLAN



A: SLU759Y
B: GBB7561S
ARUMUGAM
CHELLAIAN
G2306838N

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Accident occurred on 1/6/19 @ 9:20am along Woodlands Area 9. I was having driving tuition and my instructor Mr. Pich was sitting besides me. A motor car in front of me stopped and I follow to stop. When that car start to move on and before I follow to move, m/lorry GBB7561S hit me from behind.

No one was injured

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature Date & Time:	 Driver's Signature (If driver is not the policyholder) Date & Time:	 Reporting Centre Personnel's Signature Name: (S) NRIC/FIN No.:
---	--	---

GIARMC SketchPlanForm_V3 () Claim Own Policy () Claim Third Party () Reporting Only () Claim OD/TP at other workshop ()

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6540I
Vehicle Details	
Vehicle No.:	SLU7259Y
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2NR8807638
Chassis No.:	NRE1610038506
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,938.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,938.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2027
PARF Rebate Amount:	\$4,453.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$44,002.00
COE Rebate Amount:	\$37,360.00
Total Rebate Amount:	\$41,813.00

The information contained herein is correct as at 14 Jun 2019

OK

THREE60
— System Pte Ltd —
Tel: 6665 6360
Website: www.three60.sg

THREE60 SYSTEM PTE LTD
8, LUNDA ROAD, #04-01, LUNDA
MALL, SINGAPORE 109399
TEL: 6665 6360
FAX: 6665 6361
E-MAIL: info@three60.sg



SLU 7259Y
TP/china

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA
Assessment number: A0027
Version: 1810
Date calculated: 14/06/2019 10:02 AM

Full Report
Registration: SLU7259Y
Printed: 14/06/2019 10:05 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	CHENG HOE	Currency:	SGD
Claim Reference:	TP/CHINA	Date of Incident:	01/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA
Sub Model:	ALTIS CLASSIC
Model Sheet Number:	70 EW 20
Registration:	SLU7259Y
VIN number:	NRE1610038506
Odometer:	

*Not Notified
Primary Repair
4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0027

Version: 1810

Date calculated: 14/06/2019 10:02 AM

Full Report

Registration: SLU7259Y

Printed: 14/06/2019 10:05 AM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☒
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B360	RENEW BOOTLID INCLUDES: BOOTLID, TRIM BOOTLID, BOTH INN TAILLAMPS, BOTH NUMBER PLATE LAMP, LOCK BOOTLID AND REQUIRED ATTACHED PARTS R + R		11.0	46.20
B420	RENEW REAR BUMPER INCLUDES: BUMPER AND ALL REQUIRED ATTACHED PARTS R + R		6.0	25.20
B407	R + R L/OUTER REAR LAMP INCLUDES: REQUIRED TRIMS REMOVE AND REFIT.		2.0	8.40
B407	R + R R/OUTER REAR LAMP INCLUDES: REQUIRED TRIMS REMOVE AND REFIT.		2.0	8.40
1001	REVERSE CAMERA REMOVE&REFIT		5 10.0 *	✓ 42.00

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0027

Version: 1810

Date calculated: 14/06/2019 10:02 AM

Full Report

Registration: SLU7259Y

Printed: 14/06/2019 10:05 AM

Code	Description		WU	Price SGD
2711	REAR PANEL REPAIR	20	25.0*	105.00
3571	L/TAILLAMP PANEL REPAIR	5	10.0*	42.00
3572	R/TAILLAMP PANEL REPAIR	5	10.0*	42.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		7.60	76.0	319.20
Total of Labour				319.20

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h
Code	Description		WU Price SGD
	BOOTLID NEW PART PAINTING		16.0
	REAR BUMPER NEW PART PAINT K1R		12.0
	REAR PANEL REPAIR PAINTING >50%		18.0
	L/TAILLAMP PANEL SURFACE PAINT		4.0
	R/TAILLAMP PANEL SURFACE PAINT		4.0
	REAR FLOOR PANEL SURFACE PAINT		10.0

Paint Material Per Part

Code	Description	Price SGD
2931	BOOTLID NEW PART PAINTING	38.69
2581	REAR BUMPER NEW PART PAINT K1R	53.05
2711	REAR PANEL REPAIR PAINTING >50%	17.98
3571	L/TAILLAMP PANEL SURFACE PAINT	1.06
3572	R/TAILLAMP PANEL SURFACE PAINT	1.06
3901	REAR FLOOR PANEL SURFACE PAINT	25.17

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		64.0	
Preparation Main Work Metal	1.70	17.0	71.40
Preparation Comp. Work Plastic	0.30	3.0	12.60
Total	10 WU/h	84.0	352.80

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0027

Version: 1810

Date calculated: 14/06/2019 10:02 AM

Full Report

Registration: SLU7259Y

Printed: 14/06/2019 10:05 AM

Material Cost - Paint

New Part Painting
 New Part Painting - Plastic K1R
 Repair Painting
 Surface-/Blend Paint
 Material-constant Metal
 Material-constant Plastic
Total

Price SGD
 38.69
 53.05
 17.98
 27.29
 18.10
 9.00
 164.11

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Supplier	Price SGD	
2581	REAR BUMPER	52159 0Z904		Bu 220.00	✓
2931	BOOTLID	64401 02B61		Bu 340.00	✓
2944	BOOTLID SEAL	64461 02220		Gr 90.00	✓
2977	BOOTLID LOCK	64600 02080		Bu 48.00	✓
3015	REAR MANUFACT BADGE	75431 02090		Ne 25.00	✓
3017	BADGE MODEL	75442 02320		Ne 28.00	✓
3022	VERSION BADGE	75442 02340		Ne 28.00	✓
3288	R/R OUTER LAMP	81551 02780		Sp/IT 230.00	7✓
f: OEM Parts				Savings	0.00
n: Non-OEM Parts				Subtotal	1,009.00
u: Used parts				Fixed Sundry Parts Price	100.00
Total					1,109.00

Extras

Code	Description	Price SGD	
1002	REVERSE SENSOR	Short 200.00*	✓
1003	RUSTPROOFING	30.00*	✓
Total Extras		230.00	

Cheng Hoe Motor Pte Ltd
#01-374/382,Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA
 Assessment number: A0027
 Version: 1810
 Date calculated: 14/06/2019 10:02 AM

Full Report
 Registration: SLU7259Y
 Printed: 14/06/2019 10:05 AM

Final Calculation

	SGD	SGD
Parts	1,009.00	
Fixed Sundry Parts Price	100.00	
Total Parts		1,109.00
Labour Time Base 10 WU/h		
Total 76.0 WU X 42.00 SGD/h	319.20	235.20
Total of Labour		319.20
Total Of Extras		230.00
Paint Work Time Base 10 WU/h		
Labour Cost 84.0 WU X 42.00 SGD/h	352.80	
Material Cost	164.11	
Total Paint Including Material		516.91
Repair Cost Excludes GST		2,175.11
GST (+7.00%)		152.26
Repair Cost Included GST		2,327.37

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Cheng Hoe Motor Pte Ltd
#01-374/382,Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA
Assessment number: A0027
Version: 1810
Date calculated: 02/08/2019 3:10 PM

Full Report
Registration: SLU7259Y
Printed: 02/08/2019 3:11 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	CHENG HOE	Currency:	SGD
Claim Reference:	TP/CHINA	Date of Incident:	01/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA
Sub Model:	ALTIS CLASSIC
Model Sheet Number:	70 EW 20
Registration:	SLU7259Y
VIN number:	NRE1610038506
Odometer:	

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0027

Version: 1810

Date calculated: 02/08/2019 3:10 PM

Full Report
Registration: SLU7259Y
Printed: 02/08/2019 3:11 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☒
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B360	RENEW BOOTLID INCLUDES: BOOTLID, TRIM BOOTLID, BOTH INN TAILLAMPS, BOTH NUMBER PLATE LAMP, LOCK BOOTLID AND REQUIRED ATTACHED PARTS R + R		11.0	46.20
B420	RENEW REAR BUMPER INCLUDES: BUMPER AND ALL REQUIRED ATTACHED PARTS R + R		6.0	25.20
B407	R + R L/OUTER REAR LAMP INCLUDES: REQUIRED TRIMS REMOVE AND REFIT.		2.0	8.40
B407	R + R R/OUTER REAR LAMP INCLUDES: REQUIRED TRIMS REMOVE AND REFIT.		2.0	8.40
1001	REVERSE CAMERA REMOVE&REFIT		5.0*	21.00

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0027

Version: 1810

Date calculated: 02/08/2019 3:10 PM

Full Report

Registration: SLU7259Y

Printed: 02/08/2019 3:11 PM

Code	Description	WU	Price SGD
2711	REAR PANEL REPAIR	20.0*	84.00
3571	L/TAILLAMP PANEL REPAIR	5.0*	21.00
3572	R/TAILLAMP PANEL REPAIR	5.0*	21.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		5.60	56.0
Total of Labour			235.20

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU	Price SGD
	BOOTLID NEW PART PAINTING	16.0	
	REAR BUMPER NEW PART PAINT K1R	12.0	
	REAR PANEL REPAIR PAINTING >50%	18.0	
	L/TAILLAMP PANEL SURFACE PAINT	4.0	
	R/TAILLAMP PANEL SURFACE PAINT	4.0	
	REAR FLOOR PANEL SURFACE PAINT	10.0	

Paint Material Per Part

Code	Description	Price SGD
2931	BOOTLID NEW PART PAINTING	38.69
2581	REAR BUMPER NEW PART PAINT K1R	53.05
2711	REAR PANEL REPAIR PAINTING >50%	17.98
3571	L/TAILLAMP PANEL SURFACE PAINT	1.06
3572	R/TAILLAMP PANEL SURFACE PAINT	1.06
3901	REAR FLOOR PANEL SURFACE PAINT	25.17

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor		64.0	
Time Paint		17.0	71.40
Preparation Main Work Metal	1.70	3.0	12.60
Preparation Comp. Work Plastic	0.30	3.0	12.60
Total	10 WU/h	8.40	352.80

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA
 Assessment number: A0027
 Version: 1810
 Date calculated: 02/08/2019 3:10 PM

Full Report
 Registration: SLU7259Y
 Printed: 02/08/2019 3:11 PM

Material Cost - Paint	Price SGD
New Part Painting	38.69
New Part Painting - Plastic K1R	53.05
Repair Painting	17.98
Surface-/Blend Paint	27.29
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	164.11

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2581	REAR BUMPER	52159 0Z904		220.00
2931	BOOTLID	64401 02B61		340.00
2944	BOOTLID SEAL	64461 02220		90.00
2977	BOOTLID LOCK	64600 02080		48.00
3015	REAR MANUFACT BADGE	75431 02090		25.00
3017	BADGE MODEL	75442 02320		28.00
3022	VERSION BADGE	75442 02340		28.00
3288	R/R OUTER LAMP	81551 02780		230.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,009.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			1,109.00

Extras

Code	Description	Price SGD
1002	REVERSE SENSOR	200.00*
1003	RUSTPROOFING	30.00*
	Total Extras	230.00

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA
 Assessment number: A0027
 Version: 1810
 Date calculated: 02/08/2019 3:10 PM

Full Report
 Registration: SLU7259Y
 Printed: 02/08/2019 3:11 PM

Final Calculation

	SGD	SGD
Parts	1,009.00	
Fixed Sundry Parts Price	100.00	
Total Parts		1,109.00
Labour Time Base 10 WU/h		
Total 56.0 WU X 42.00 SGD/h	235.20	
Total of Labour		235.20
Total Of Extras		230.00
Paint Work Time Base 10 WU/h		
Labour Cost 84.0 WU X 42.00 SGD/h	352.80	
Material Cost	164.11	
Total Paint Including Material		516.91
Repair Cost Excludes GST		2,091.11
GST (+7.00%)		146.38
Repair Cost Included GST		2,237.49

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Finalise

Claim Reference: TP/CHINA
Assessment number: A0027
Version: 1810
Date calculated: 05/08/2019 8:47 AM

Full Report
Registration: SLU7259Y
Printed: 05/08/2019 8:52 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	TP/CHINA	Date of Incident:	01/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA
Sub Model:	ALTIS CLASSIC
Model Sheet Number:	70 EW 20
Registration:	SLU7259Y
VIN number:	NRE1610038506
Odometer:	

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP/CHINA
Assessment number: A0027
Version: 1810
Date calculated: 05/08/2019 8:47 AM

Full Report
Registration: SLU7259Y
Printed: 05/08/2019 8:52 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☒
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B360	RENEW BOOTLID INCLUDES: BOOTLID, TRIM BOOTLID, BOTH INN TAILLAMPS, BOTH NUMBER PLATE LAMP, LOCK BOOTLID AND REQUIRED ATTACHED PARTS R + R		11.0	46.20
B420	RENEW REAR BUMPER INCLUDES: BUMPER AND ALL REQUIRED ATTACHED PARTS R + R		6.0	25.20
B407	R + R L/OUTER REAR LAMP INCLUDES:REQUIRED TRIMS REMOVE AND REFIT.		2.0	8.40
B407	R + R R/OUTER REAR LAMP INCLUDES:REQUIRED TRIMS REMOVE AND REFIT.		2.0	8.40
1001	REVERSE CAMERA REMOVE&REFIT		5.0*	21.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP/CHINA

Assessment number: A0027

Version: 1810

Date calculated: 05/08/2019 8:47 AM

Full Report

Registration: SLU7259Y

Printed: 05/08/2019 8:52 AM

Code	Description	WU	Price SGD
2711	REAR PANEL REPAIR	20.0*	84.00
3571	L/TAILLAMP PANEL REPAIR	5.0*	21.00
3572	R/TAILLAMP PANEL REPAIR	5.0*	21.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		5.60	56.0
			235.20
Total of Labour			235.20

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU	Price SGD
	BOOTLID NEW PART PAINTING	16.0	
	REAR BUMPER NEW PART PAINT K1R	12.0	
	REAR PANEL REPAIR PAINTING >50%	18.0	
	L/TAILLAMP PANEL SURFACE PAINT	4.0	
	R/TAILLAMP PANEL SURFACE PAINT	4.0	
	REAR FLOOR PANEL SURFACE PAINT	10.0	

Paint Material Per Part

Code	Description	Price SGD
2931	BOOTLID NEW PART PAINTING	38.69
2581	REAR BUMPER NEW PART PAINT K1R	53.05
2711	REAR PANEL REPAIR PAINTING >50%	17.98
3571	L/TAILLAMP PANEL SURFACE PAINT	1.06
3572	R/TAILLAMP PANEL SURFACE PAINT	1.06
3901	REAR FLOOR PANEL SURFACE PAINT	25.17

Labour Cost - Paint		Hrs	WU	Price SGD
Factor		42.00 SGD/h		
Time Paint			64.0	
Preparation Main Work Metal		1.70	17.0	71.40
Preparation Comp. Work Plastic		0.30	3.0	12.60
Total		10 WU/h	8.40	352.80

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP/CHINA
 Assessment number: A0027
 Version: 1810
 Date calculated: 05/08/2019 8:47 AM

Full Report
 Registration: SLU7259Y
 Printed: 05/08/2019 8:52 AM

Material Cost - Paint	Price SGD
New Part Painting	38.69
New Part Painting - Plastic K1R	53.05
Repair Painting	17.98
Surface-/Blend Paint	27.29
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	164.11

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2581	REAR BUMPER	52159 0Z904		220.00
2931	BOOTLID	64401 02B61		340.00
2944	BOOTLID SEAL	64461 02220		90.00
2977	BOOTLID LOCK	64600 02080		48.00
3015	REAR MANUFACT BADGE	75431 02090		25.00
3017	BADGE MODEL	75442 02320		28.00
3022	VERSION BADGE	75442 02340		28.00
3288	R/R OUTER LAMP	81551 02780		230.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,009.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			1,109.00

Extras

Code	Description	Price SGD
1002	REVERSE SENSOR	200.00*
1003	RUSTPROOFING	30.00*
	Total Extras	230.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP/CHINA

Assessment number: A0027

Version: 1810

Date calculated: 05/08/2019 8:47 AM

Full Report

Registration: SLU7259Y

Printed: 05/08/2019 8:52 AM

Final Calculation

	SGD	SGD
Parts	1,009.00	
Fixed Sundry Parts Price	100.00	
Total Parts		1,109.00
Labour Time Base 10 WU/h		
Total 56.0 WU X 42.00 SGD/h	235.20	
Total of Labour		235.20
Total Of Extras		230.00
Paint Work Time Base 10 WU/h		
Labour Cost 84.0 WU X 42.00 SGD/h	352.80	
Material Cost	164.11	
Total Paint Including Material		516.91
Repair Cost Excludes GST		2,091.11
GST (+7.00%)		146.38
Repair Cost Included GST		2,237.49

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 5 August 2019 8:59 AM
To: Kenneth Kong (LKKAUTO); Efeeda (Cheng Hoe -Yishun); SUR
Subject: RE: SLU7259Y DOA :01/06/2019 TP/CHINA (EMAIL 2/2)

Dear Efeeda,

WITHOUT PREJUDICE

Confirmed S\$2091.11 / 4 DAYS

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 2 August 2019 3:41 PM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Subject: FW: SLU7259Y DOA :01/06/2019 TP/CHINA (EMAIL 2/2)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Efeeda (Cheng Hoe -Yishun) <chmotor@singnet.com.sg>
Sent: Friday, 2 August 2019 3:32 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: SLU7259Y DOA :01/06/2019 TP/CHINA (EMAIL 2/2)

EMAIL 2/2

Thank you

Rgds
Efeeda
Cheng Hoe Motor Pte Ltd

Tel :67556142
Fax : 67557719

From: Efeeda (Cheng Hoe -Yishun)
Sent: Friday, August 02, 2019 3:31 PM
To: Veron Chen (LKKAuto)
Subject: SLU7259Y DOA :01/06/2019 TP/CHINA (EMAIL 1/2)

Hi Veron,

Attached please find the photos and finalization list submit for your reference.

Kindly let us have your confirmation on the final sum – **S\$2091.11 / 4 DAYS** via email.

We look forward to receiving your early confirmation.

Thanks & Rdgs
Efeeda
Cheng Hoe Motor Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jun 2019 Sendback Est	14 Jun 2019 11:18 S\$2,175.11	14 Jun 2019 14:14 Edit Adj Rpt	S\$2,091.11 Edit Estimates	S\$2,091.11 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	THREE60 SYSTEM PTE LTD , Co. Reg. No.: 201708114K		
Main Claimant:	PECK CHIN HUAT , ID: S0196540I		
Vehicle Reg. No.:	SLU7259Y	Date of Loss:	01/06/2019 09:00 - :59 [17 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202478-CHEONGML	Policy/Cover Note No.:	DMCVSN30098219000
Vehicle Reg. No. (Insured):	GBB7561S	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/06/2019]		
Driver/Custodian (Insured):	ARUMUGAM CHELLIAH (/ Male) , NRIC: G2304838N Email:		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SLU7259Y (SNM19D202478-CHEONGML)
[GBB7561S]
TP
PECK CHIN HUAT
Jun 1 2019 9:00AM
[THREE60 SYSTEM PTE LTD]
Cheng Hoe Motor Pte Ltd

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=833510&extid=307082&corole=4&... 1/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19010566/KVD3S2

Date: 07/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30098219000
Claimant Vehicle No :	SLU7259Y	Insured Vehicle No :	GBB7561S
Date of Loss:	01/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D202478-CHEONGML

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU7259Y	Engine No:	2NR8807638
Make & Model:	TOYOTA COROLLA AXIO, 1.5 X (A)	Chassis No:	NRE1610038506
Reg. Date:	12/12/2017 (Man. Year: 2017)	Odometer:	51971 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Habilead 9 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Habilead 9 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,009.00	1,009.00	0.00	0.00
Miscellaneous Items	330.00	300.00	30.00	9.09
Labour	836.11	782.11	54.00	6.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,175.11	2,091.11	84.00	3.86
+ GST 7.00/7.00% (S\$)	152.26	146.38	5.88	3.86
Nett Amount (S\$)	2,327.37	2,237.49	89.88	3.86

INSPECTION

Date of Assignment:	14/06/2019	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
			Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	14/06/2019	Inspected At:	Blk 1019 #01-374/382, Yishun Industrial Park A
			Singapore 768761
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Aug 2019)
Parts:	143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU7259Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		1,009.00 F	-
2	1		*REAR BUMPER	Buckled	-	*220.00 F
3	1		*BOOTLID	Bent	-	*340.00 F
4	1		*BOOTLID SEAL	Cut	-	*90.00 F
5	1		*BOOTLID LOCK	Dented	-	*48.00 F
6	1		*REAR MANUFACT BADGE	Necessary	-	*25.00 F
7	1		*BADGE MODEL	Necessary	-	*28.00 F
8	1		*VERSION BADGE	Necessary	-	*28.00 F
9	1		*R/R OUTER LAMP	Split	-	*230.00 F
					Total Parts (S\$)	1,009.00
						1,009.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REVERSE SENSOR (Shorted)	-	200.00
2	1	S/NETT	230.00	-
3	1	SUNDRY	100.00	100.00
Sub Total (\$\$)			330.00	300.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	319.20	235.20
2	SPRAY PAINTING	New	516.91	-
3	RUSTPROOFING.	New	-	30.00
4	PAINT WORK: LABOUR COST.	New	-	352.80
5	PAINT WORK: MATERIAL COST.	New	-	164.11
Gross Labour Cost (\$\$)			836.11	782.11

Report was unsubmitted during this print-out.

< END OF ESTIMATES >