

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG19010593/KSF3S2**Date:** 04/11/2019REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29092674

Claimant Vehicle No : XD8255Z**Insured Vehicle No :** GBG8079K

Date of Loss: 14/05/2019

Nature of Claim: TP

Claim No: 593643

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **XD8255Z**

Make & Model: SCANIA P400LA, 12.7 D 4X2 MSZ (M)

Engine No: 6793750

Reg. Date: 27/12/2013 (Man. Year: 2013)

Chassis No: YS2P4X20002092644

Colour: Blue

Odometer: 393266 km

Engine Capacity: 12742 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 12 R22.5

Rear Tyre Size: 12 R22.5 (D/D/D)

Front Left Side: Linglong 7/6 mm

Rear Left Side: Linglong 6/66/66/6 mm

Front Right Side: Linglong 7/6 mm

Rear Right Side: Linglong 6/66/66/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,361.60	1,090.40	271.20	19.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	370.00	230.00	38.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,961.60	1,460.40	501.20	25.55
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	1,961.60	1,150.00	811.60	41.37
+ GST 7.00/7.00% (S\$)	137.31	80.50	56.81	41.37
Nett Amount (S\$)	2,098.91	1,230.50	868.41	41.37

INSPECTION

Date of Assignment: 14/06/2019

Date Inspected: 19/10/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Nov 2019)	
Parts:	N/A	SCANIA P400LA 12.7 D 4X2 MSZ (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD8255Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER LH	Buckled / Dented	1,113.00 FL	*1,113.00 FL
2	1		*FRONT BUMPER LH SIDE PAD	Cut	112.00 FL	*112.00 FL
3	1		*LH SIDE LAMP	Mtg Cracked	138.00 FL	*138.00 FL
4	1		*FRONT LH STEP TRAY	Serviceable	339.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,702.00	1,363.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	340.40	272.60
Total Parts (\$\$)	1,361.60	1,090.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT LH BUMPER, SIDE LAMP, STEP TRAY, KNOCK & REPAIR FRT BUMPER REINFORCEMENT & REALIGN THE SAME.	New	400.00	250.00
2	PUTTY & RESPRAY ON FRT BUMPER.	New	200.00	120.00
Gross Labour Cost (S\$)			600.00	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >