

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: TWK/AR/1127.18/ntuc/ml/pd

Date: 02nd July 2019

Our Ref: CS1/LAW19010599/Utd3s2

M/s Tan Kok Quan Partnership

1 Wallich Street #07-02 Guoco Tower Singapore 078881

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJL 6357A INSURED VEHICLE: XD 7027Y ACCIDENT DATE: 03/02/2018

We thank you for your instruction on 13/06/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJL 6357A from M/s AJAX Inspection Services Pte Ltd.
- b) Survey report by MC-COY Appraiser Pte Ltd with colour photographs.
- c) Final Repair Bill of SJL 6357A from M/s Bluwel Automotive Service Pte Ltd.
- d) Singapore Accident Statement of Vehicles SJL 6357A and XD 7027Y.
- e) Colour damaged vehicle photographs of SJL 6357A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJL 6357A Make & Model : Honda Jazz Year of Registration : 2008

Chassis Number : JHMGE88509S201590

Engine Capacity : 1497 cc

- We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.