

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: MN.IG.B1.1812223

Date: 19th June 2019

Our Ref: CS1/LAW19010599/Utd3s2

M/s M Nedumaran & Co

No. 11 Sin Ming Road #B2-09 (Unit 2), Thomson V Two Singapore 575629

Dear Sir / Madam.

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJL 6357A INSURED VEHICLE: XD 7027Y ACCIDENT DATE: 03/02/2018

We thank you for your instruction on 13/06/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJL 6357A from M/s AJAX Inspection Services Pte Ltd.
- Survey report by MC-COY Appraiser Pte Ltd with colour photographs.
- c) Final Repair Bill of SJL 6357A from M/s Bluwel Automotive Service Pte Ltd.
- d) Singapore Accident Statement of Vehicles SJL 6357A and XD 7027Y.
- e) Colour damaged vehicle photographs of SJL 6357A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SJL 6357A

Make & Model

: Honda Jazz

Year of Registration

: 2008

Chassis Number

: JHMGE88509S201590

Engine Capacity

: 1497 cc

- We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.