

















# AJAX

Inspection Services Pte Ltd



Date : 13 March 2018

To : **NTUC Income Insurance Co-operative Limited**  
73 Bras Basah Road #05-01  
NTUC Trade Union House  
Singapore 189556

Attn : Mr Marcus Xiao

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road

#08-08, Cendex Centre

Singapore 169208

Tel: +65 6255 0808

Fax: +65 6849 9155

[info@ajaxinspection.com](mailto:info@ajaxinspection.com)

**Invoice No – AV13642**

Company Reg No -201318067R

GST Reg No - 201318067R

## TAX INVOICE

**YOUR REF / CLAIM NUMBER** : MT/0981104-002  
**OUR REF** : AVS2018-14409/WH  
**TP VEHICLE NO** : SJL6357A  
**CLAIM TYPE** : PRE-REPAIR SURVEY  
**DATE OF SURVEY** : 07 February 2018

No.	Description	Amount (\$\$)
1	Professional fee	50.00

Subtotal 50.00  
GST 7.00% 3.50  
**Total 53.50**

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: [accounts@ajaxadjusters.com](mailto:accounts@ajaxadjusters.com)

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: [info@ajaxinspection.com](mailto:info@ajaxinspection.com) Website: [www.ajaxadjusters.com](http://www.ajaxadjusters.com) Co. Reg. No.: 201318067R





Inspection Services Pte Ltd

### PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Marcus Xiao

Assign Date:	07/02/2018	Survey Date:	07/02/2018	TP Report Date:	05/02/2018
Accident Date:	03/02/2018	TP Policy No:	5074824977-02	Our Ref:	AVS2018-14409/WH
Place of Survey:	Bluwel Automotive Service Pte Ltd 1 Kaki Bukit Avenue 6 #01-55 Autobay @ Kaki Bukit Singapore 417883			Your Ref:	MT/0981104-002
				Claim Type:	Third Party
				Claimant:	Rent & Go 2 Car Rental Pte Ltd

#### Description of Vehicle:

Veh. No:	SJL6357A	Make/Model:	Honda Jazz 1.5L AT ABS D/AB HID 2WD 5DR		
Colour:	White	Engine No:	L15A71001903	Sum Insured (S\$):	Market Value
Engine Capacity:	1,497cc	Chassis No:	IHMGE88509S201590	Mkt Value (S\$):	\$16,000.00
Odometer:	91966	Reg. Date:	05/12/2008	Excess (S\$):	NA

#### Condition of Vehicle:

General:	Good	Modification:	No	Steering:	NA
Handbrake:	NA	Footbrake:	NA	Paint work:	Good
Tyre Make:	Yokohama				
Front Tyre Size:	185/55/R16	Front Left Side:	6mm	Front Right Side:	6mm
Rear Tyre Size:	185/55/R16	Rear Left Side:	6mm	Rear Right Side:	6mm

#### Description of Damage:

The vehicle sustained damage on the right portion.

The right front door, right wing mirror, right rear door, right rear fender, rear bumper and right rear rim were among the items affected.

#### Remarks:

Based on visual survey of the vehicle without any repair estimate provided, we viewed that the repair cost should not be more than S\$4,500.00 and could take approximately six (6) working days to complete. However, please kindly take note that the economical repair value is about S\$4,000.00.

All the stated damage are subject to consistency of the mentioned accident.



COMPLETED

Adjuster: Lee Wee Ho  
Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R



# AJAX

Inspection Services Pte Ltd

Date : 27 March 2018

To : NTUC Income Insurance Co-operative Limited  
73 Bras Basah Road #05-01  
NTUC Trade Union House  
Singapore 189556

Attn : Mr Marcus Xiao

AJAX Inspection Services Pte Ltd  
120 Lower Delta Road  
#08-08, Cendex Centre  
Singapore 169208  
Tel: +65 6255 0808  
Fax: +65 6849 9155  
[info@ajaxinspection.com](mailto:info@ajaxinspection.com)

Invoice No – AV13857  
Company Reg No -201318067R  
GST Reg No - 201318067R

## TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/0981104-002  
OUR REF : AV52018-14409/WH  
TP VEHICLE NO : SJL6357A  
CLAIM TYPE : PRE-REPAIR SURVEY  
DATE OF SURVEY : 07 February 2018

No.	Description	Amount (\$\$)
1	Professional fee	100.00

Subtotal	100.00
GST 7.00%	7.00
<b>Total</b>	<b>107.00</b>

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: [accounts@ajaxadjusters.com](mailto:accounts@ajaxadjusters.com)

## AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: [info@ajaxinspection.com](mailto:info@ajaxinspection.com) Website: [www.ajaxadjusters.com](http://www.ajaxadjusters.com) Co. Reg. No.: 201318067R





Inspection Services Pte Ltd

### PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Marcus Xiao

<b>Assign Date:</b>	07/02/2018	<b>Survey Date:</b>	07/02/2018	<b>TP Report Date:</b>	05/02/2018
<b>Accident Date:</b>	03/02/2018	<b>TP Policy No:</b>	5074824977 02	<b>Our Ref:</b>	AV52018-14409/WH
<b>Place of Survey:</b>	Bluwel Automotive Service Pte Ltd 1 Kaki Bukit Avenue 6 #01-55 Autobay @ Kaki Bukit Singapore 417883			<b>Your Ref:</b>	MT/0981104-002
				<b>Claim Type:</b>	Third Party
				<b>Claimant:</b>	Rent & Go 2 Car Rental Pte Ltd

#### Description of Vehicle:

<b>Veh. No:</b>	SJL6357A	<b>Make/Model:</b>	Honda Jazz 1.5L AT ABS D/AB HID 2WD 5DR		
<b>Colour:</b>	White	<b>Engine No:</b>	L15A71001903	<b>Sum Insured (S\$):</b>	Market Value
<b>Engine Capacity:</b>	1,497cc	<b>Chassis No:</b>	JHMGF88509S201590	<b>Mkt Value (S\$):</b>	\$16,000.00
<b>Odometer:</b>	91966	<b>Reg. Date:</b>	05/12/2008	<b>Excess (S\$):</b>	NA

#### Condition of Vehicle:

<b>General:</b>	Good	<b>Modification:</b>	No	<b>Steering:</b>	NA
<b>Handbrake:</b>	NA	<b>Footbrake:</b>	NA	<b>Paint work:</b>	Good
<b>Tyre Make:</b>	Yokohama				
<b>Front Tyre Size:</b>	185/55/R16	<b>Front Left Side:</b>	6mm	<b>Front Right Side:</b>	6mm
<b>Rear Tyre Size:</b>	185/55/R16	<b>Rear Left Side:</b>	6mm	<b>Rear Right Side:</b>	6mm

#### Description of Damage:

The vehicle sustained damage on the right portion.

The right front door, right wing mirror, right rear door, right rear fender, rear bumper and right rear rim were among the items affected.

#### Remarks:

Our recommended amount for the cost of contract lumpsum repair is S\$3,500.00 with approximately six (6) working days to complete. Please kindly take note that the economical repair value is about S\$4,000.00. However, no finalisation was agreed with the repairer.

All the stated damage are subject to consistency of the mentioned accident.

COMPLETED 23 MAR 2018

Adjuster:

Lee Wee Ho  
Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R





## Inspection Services Pte Ltd

**Adjustment of Repair Cost for Vehicle:****SJL6357A****Our Ref:** AVS2018-14409/WH

No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
<b>List Items</b>					
1	1	Front o/s door	Bent	806.50	806.50
2	1	Front o/s door lock	Not necessary	198.80	--
3	1	Front o/s door outer handle	Grazed	93.20	93.20
4	1	Front o/s door protector	Deformed	89.60	89.60
5	1	Front o/s door regulator c/w motor	Damaged	368.40	368.40
6	1	Front o/s door rubber	Necessary	112.60	112.60
7	1	Front o/s door side mirror	Cracked	472.00	472.00
8	1	Rear o/s door	Bent	787.50	787.50
9	1	Rear o/s door lock	Not necessary	162.80	--
10	1	Rear o/s door regulator c/w motor	Not necessary	368.40	--
11	1	Rear bumper	Repair	490.80	--
12	1	Rear bumper side retainer	Not necessary	18.60	--
13	1	Rear o/s fender	Repair	614.40	--
<b>Sub Total:</b>				<b>4,583.60</b>	<b>2,729.80</b>
<b>Discount (less 20% ):</b>				<b>916.72</b>	<b>545.96</b>
				<b>3,666.88</b>	<b>2,183.84</b>

**Special Nett Items**

1	1	Door visior (1 set)	Necessary	160.00	100.00
2	1	O/s rocker panel side skirt	Repair	450.00	--
3	1	Rear o/s fender quarter glass sealant	Not necessary	50.00	--
<b>Sub Total:</b>				<b>660.00</b>	<b>100.00</b>
<b>Total Parts Price:</b>				<b>4,326.88</b>	<b>2,283.84</b>

*Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.*

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R



# AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle: <u>SJL6357A</u>				Our Ref: AVS2018-14409/WH	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
<b>Labour Cost</b>					
1		To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.		40.00	30.00
2		To remove and refit rear cushion seats, radio speaker board, interior upholstery to upholstery to facilitate the repairs.		120.00	--
3		To remove and refit rear bumper sensor.		80.00	--
4		To remove and refit the door lock mechanism, regulator gear, window glass, handle, inner board, hinges, channel to facilitate the repairs.		120.00	100.00
5		To remove and replace the above damage parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.		1,320.00	800.00
6		To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.		1,320.00	1,000.00
7		To apply undercoating on the repaired and replaced panels for rust protection.		120.00	120.00
<b>Sub Total:</b>				3,120.00	2,050.00
<b>Grand Total:</b>				7,446.88	4,333.84

*Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.*

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

# AJAX

Inspection Services Pte Ltd

Our Ref: AVS2018-14409/WH  
Your Ref: MT/0981104-002

Pre-repair survey - 07/02/2018



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: [info@ajaxinspection.com](mailto:info@ajaxinspection.com) Website: [www.ajaxadjusters.com](http://www.ajaxadjusters.com) Co. Reg. No.: 201318067R




# AJAX

Inspection Services Pte Ltd

Our Ref: AVS2018-14409/WH

Your Ref: MT/0981104-002

## Pre-repair survey



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: [info@ajaxinspection.com](mailto:info@ajaxinspection.com) Website: [www.ajaxadjusters.com](http://www.ajaxadjusters.com) Co. Reg. No.: 201318067R

# AJAX

Inspection Services Pte Ltd

Our Ref: AVS2018-14409/WH  
Your Ref: MT/0981104-002

## Pre-repair survey



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: [info@ajaxinspection.com](mailto:info@ajaxinspection.com) Website: [www.ajaxadjusters.com](http://www.ajaxadjusters.com) Co. Reg. No.: 201318067R



# AJAX

Inspection Services Pte Ltd

Our Ref: AVS2018-14409/WH  
Your Ref: MT/0981104 002

## Pre-repair survey



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

## **AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: [info@ajaxinspection.com](mailto:info@ajaxinspection.com) Website: [www.ajaxadjusters.com](http://www.ajaxadjusters.com) Co. Reg. No.: 201318067R



# AJAX

Inspection Services Pte Ltd

Our Ref: AVS2018-14409/WH

Your Ref: MT/0981104-002

Re-survey items - 08/02/2018



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: [info@ajaxinspection.com](mailto:info@ajaxinspection.com) Website: [www.ajaxadjusters.com](http://www.ajaxadjusters.com) Co. Reg. No.: 201318067R



# AJAX

Inspection Services Pte Ltd

Our Ref: AVS2018-14409/WH  
Your Ref: MT/0981104-002

## Re-survey items

Post repair survey - 09/02/2018



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: [info@ajaxinspection.com](mailto:info@ajaxinspection.com) Website: [www.ajaxadjusters.com](http://www.ajaxadjusters.com) Co. Reg. No.: 201318067R