AJAX Inspection Services Pte Ltd

MOTOR CLAUM

Date

: 27 March 2018

To

Attn

: NTUC Income Insurance Co-operative Limited

73 Bras Basah Road #05-01 NTUC Trade Union House

: Mr Marcus Xiao

Singapore 189556

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08, Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 6849 9155

info@ajaxinspection.com

Invoice No - AV13857

Company Reg No -201318067R GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER

: MT/0981104-002

OUR REF

: AVS2018-14409/WH

TP VECHILE NO

: SJL6357A

CLAIM TYPE

: PRE-REPAIR SURVEY

DATE OF SURVEY

: 07 February 2018

No.

Description

Amount (S\$)

1

Professional fee

100.00

Subtotal 100.00 GST 7.00% 7.00 Total 107.00

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com



PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Marcus Xiao

Assign Date:

07/02/2018

Survey Date:

07/02/2018

TP Report Date:

05/02/2018

Accident Date:

03/02/2018

TP Policy No:

5074824977-02

Our Ref:

AVS2018-14409/WH

Place of Survey:

Bluwel Automotive Service Pte Ltd

Your Ref:

MT/0981104-002

Singapore

1 Kaki Bukit Avenue 6 #01-55 Autobay @ Kaki Bukit 417883

Claim Type: Claimant:

Third Party Rent & Go 2 Car Rental

Pte Ltd

Description of Vehicle:

Veh. No: Colour:

SJL6357A White

Make/Model:

Honda Jazz 1.5L AT ABS D/AB HID 2WD 5DR L15A71001903

Engine Capacity:

1,497cc

Engine No: Chassis No:

JHMGE88509S201590

Mkt Value (S\$):

Sum Insured (S\$): Market Value \$16,000.00

Odometer:

91966

Reg. Date:

05/12/2008

Excess (S\$):

NA

Condition of Vehicle:

Modification:

No

Steering:

NA

Handbrake:

General:

Good NA

Footbrake:

NA

Paint work:

Good

Tyre Make:

Yokohama 185/55/R16

Front Left Side:

6mm

Front Right Side:

6mm

Front Tyre Size: Rear Tyre Size:

185/55/R16

Rear Left Side:

6mm

Rear Right Side:

6mm

Description of Damage:

The vehicle sustained damage on the right portion.

The right front door, right wing mirror, right rear door, right rear fender, rear bumper and right rear rim were among the items affected.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is \$\$3,500.00 with approximately six (6) working days to complete. Please kindly take note that the economical repair value is about \$\$4,000.00. However, no finalisation was agreed with the repairer.

All the stated damage are subject to consistency of the mentioned accident.

Adjuster:

Lee Wee Ho

Motor Appraiser

COMPLETED 2.3 MAR 2018

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



No.	Qty	Description of Parts	Condition	Repairer's Estimate	Our Recommendation S\$
ist Iten	<u>ns</u>				
1	1	Front o/s door	Bent	806.50	806.50
2	1	Front o/s door lock	Not necessary	198.80	
3	1	Front o/s door outer handle	Grazed	93.20	93.20
4	1	Front o/s door protector	Deformed	89.60	89.60
5	1	Front o/s door regulator c/w motor	Damaged	368.40	368.40
6	1	Front o/s door rubber	Necessary	112.60	112.60
7	1	Front o/s door side mirror	Cracked	472.00	472.00
8	1	Rear o/s door	Bent	787.50	787.50
9	1	Rear o/s door lock	Not necessary	162.80	
10	1	Rear o/s door regulator c/w motor	Not necessary	368.40	**
11	1	Rear bumper	Repair	490.80	122
12	1	Rear bumper side retainer	Not necessary	18.60	250
13	1	Rear o/s fender	Repair	614.40	**
		de	Sub Total:	4,583.60	2,729.80
			Discount (less 20%):	916.72	545.96
				3,666.88	2,183.84

1	Door visior (1 set)	Necessary	160.00	100.00
1	O/s rocker panel side skirt	Repair	450.00	7.22
1	Rear o/s fender quarter glass sealant	Not necessary	50.00	-
		Sub Total:	660.00	100.00
		Total Parts Price:	4,326.88	2,283.84

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



Adjustment of Repair Cost for Vehicle:			SJL6357A	Our Ref: AVS2018-14409/WH	
No.	Qty	Description of Parts	Condition	Repairer's Estimate	Our Recommendation S\$
Labou	r Cost				
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.			40.00	30.00
2	To remove and refit rear cushion seats, radio speaker board, interior upholestery to upholestery to facilitate the repairs.			120.00	200
3	To remove and refit rear bumper sensor.			80.00	
4	To remove and refit the door lock mechanism, regulator gear, window glass, handle, inner board, hinges, channel to facilitate the repairs.			120.00	100.00
5	To remove and replace the above damage parts, straighten, knock out, realigh and repair including cut and wield body panels. To re-adjust to the original position using power tools.			1,320.00	800.00
6	masking ta	aint on the replaced and repaired parts, pe the unaffected areas with paper, cle nal polishing and waxing are also availa	1,320.00	1,000.00	
7	To apply ur protection.	ndercoating on the repaired and replace	ed panels for rust	120.00	120.00
			Sub Total:	3,120.00	2,050.00
			Grand Total:	7,446.88	4,333.84

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.