


Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7931041G



Name
TAN WEI TECK
(CHEN WEIDE)
陳偉德

Race
CHINESE

Date of birth
26-09-1979

Sex
M

Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7931041G

Name
TAN WEI TECK
(CHEN WEIDE)

Birth Date: 26 Sep 1979

Issue Date: 06 Oct 2011



002006307D



FORM NO. **S7931041G**



Date of review
31-01-2013

References

APT BLK 337 BUKIT BATOK STREET 34
#05-1B
SINGAPORE 650337

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES):

EFFECTIVE DATE

Class 2B Motorcycles ≤ 200 cc

26 Juni 2006

Class 3 Motor Cars ≤ 3500 kg with ≤ 7 passengers, exclusive of the driver, and other motor vehicles ≤ 2500 kg

24 Sept 2004

117-125A



























REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7931041G



Name
TAN WEI TECK
(CHEN WEIDE)

Race
陈伟德

CHINESE

Date of birth
26-09-1979

Sex
M

Country of birth
SINGAPORE

S7931041G

REPUBLIC OF SINGAPORE DRIVING LICENCE



TAN WEI TECK
(CHEN WEIDE)

Issue Date 26 Sep 1979
Valid Until 06 Oct 2011



0020063072D



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
COMLAW LLC*		Ref : CS/LAW19010611/Utd3e2	
64 CECIL ST #06-01 IOB BLDG SINGAPORE 049711		Date : 11-07-2019	
		Code : L050	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SJM 3513E	Veh. Inspected	SJM 3500S
Policy No.		Coverage (\$)	0.00
Claim No.	MC/MC 6355/2019	Excess (\$)	0.00
Assign From	CHARLENE CHEE	Assign Date	13/06/2019
2. Vehicle Particulars & Condition			
Make & Model	DONGFENG EQ6380 (M)	c.c	1310
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	LGK132K7689139812	Colour	MAROON
Odometer	140676	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	165/70 R14	FALKEN	5 mm
L/H Front Tyre	165/70 R14	FALKEN	5 mm
R/H Rear Tyre	165/70 R14	FALKEN	5 mm
L/H Rear Tyre	165/70 R14	FALKEN	5 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.			
REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	11/06/2018	Inspection Date	05/07/2019
Survey held at	50 BUKIT BATOK ST 23		
Repairer	FASTECH AUTO PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.			
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 3500S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAIL GATE	REPLACED	1,652.30	1,652.30 ✓
1	REAR TAIL GATE LOCK	REPLACED	268.30	268.30 ✓
1	REAR TAIL GATE LOCK CATCH	NOT NECESSARY	112.30	-
1	REAR TAIL GATE RUBBER	REPLACED	212.30	212.30 ✓
2	REAR TAIL GATE ABSORBER @\$258.00	NOT NECESSARY	516.00	-
1	REAR TAIL GATE INNER BOARD	NOT NECESSARY	236.30	-
1	REAR TAIL GATE CENTRE GARNISH	REPLACED	295.60	295.60 ✓
1	REAR TAIL GATE EMBLEM (MINI)	REPLACED	47.20	47.20 ✓
1	REAR TAIL GATE EMBLEM (1.3)	REPLACED	40.10	40.10 ✓
1	REAR TAIL GATE WINDSCREEN MLDG	REPLACED	125.00	125.00 ✓
1	REAR END PANEL	REPAIRED SEE LABOUR	845.20	-
1	REAR BUMPER	REPLACED	1,230.20	1,230.20 ✓
2	REAR BUMPER REFLECTOR L/R @\$72.10	N/S REPLACED	144.20	72.10 ✓
1	REAR TAIL GATE CENTRE REFLECTOR	NOT NECESSARY	268.70	-
	LESS 10% DISCOUNT		-	-394.31 ✓
			5,993.70	3,548.79 ✓
<u>SPECIAL NETT ITEMS</u>				
6	REAR TAIL GATE INNER BOARD CLIPS @\$5.00 (SN)	REPLACED	30.00	30.00 ✓
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	REAR TAIL GATE WINDSCREEN SEALANT (SN)	REPLACED	100.00	40.00 ✓
1	SET REAR REVERSE SENSOR (SN)	REPLACED	350.00	200.00 ✓
			525.00	270.00 ✓
<u>LABOUR</u>				
	TO CHECK WIRING.		150.00	30.00 ✓
	TUFF KOTE.		150.00	40.00 ✓
	REMOVE & REPLACE REVERSE SENSOR.		150.00	40.00 ✓
	REMOVE & REFIX TAIL GATE WINDSCREEN.		150.00	100.00 ✓
	TO REMOVE & REPLACE SPARE PART & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,500.00	400.00 ✓

Report Ref No. CS/LAW19010611/Utd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING & ETC.		1,400.00	600.00
			3,500.00	1,210.00
	GRAND TOTAL		10,018.70	5,028.79
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CS/LAW19010611/Utd3e2

BASE ON PLAINTIFF'S VEHICLE (SJM 3500S) RENEWAL THE VEHICLE IS ECONOMICAL TO REPAIR.

CHUA KANG SENG

Licensed Appraiser

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

MODEL YEAR	MODEL MONTH	ADVT. DATE	MAKE/MODEL	S\$ '000
2008	AUG	04.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	05.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	06.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	07.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	08.06.18	PROTON SAGA 1.3A	26.7
2008	JUL	14.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	15.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	18.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	19.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	20.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUN	18.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	19.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	20.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	21.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	22.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	01.06.18	TOYOTA RUSH 1.5A	31.8
2008	JUN	04.06.18	TOYOTA RUSH 1.5A	31.8
2008	NOV	01.06.18	TOYOTA VIOS 1.5A	11.8
2008	JUN	25.06.18	TOYOTA AXIO 1.5A	29.9
2008	JUN	26.06.18	TOYOTA AXIO 1.5A	29.9
2008	JUN	27.06.18	TOYOTA AXIO 1.5A	29.9
2008	JUN	28.06.18	TOYOTA AXIO 1.5A	29.9
2008	JUN	29.06.18	TOYOTA AXIO 1.5A	29.9

total?

Average Value^{Total} as at June 2018:

508,600/-

MODEL YEAR	MODEL MONTH	ADVT. DATE	MAKE/MODEL	S\$ '000
2008	AUG	04.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	05.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	06.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	07.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	08.06.18	PROTON SAGA 1.3A	26.7
2008	JUL	14.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	15.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	18.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	19.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	20.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUN	18.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	19.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	20.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	21.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	22.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	01.06.18	TOYOTA RUSH 1.5A	31.8
2008	JUN	04.06.18	TOYOTA RUSH 1.5A	31.8

Average Value Total: \$508,600 / 17

As at June 2018 \$29,917



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 3500S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAIL GATE	REPLACED	1,652.30	1,652.30
1	REAR TAIL GATE LOCK	REPLACED	268.30	268.30
1	REAR TAIL GATE LOCK CATCH	NOT NECESSARY	112.30	-
1	REAR TAIL GATE RUBBER	REPLACED	212.30	212.30
2	REAR TAIL GATE ABSORBER @\$258.00	NOT NECESSARY	516.00	-
1	REAR TAIL GATE INNER BOARD	NOT NECESSARY	236.30	-
1	REAR TAIL GATE CENTRE GARNISH	REPLACED	295.60	295.60
1	REAR TAIL GATE EMBLEM (MINI)	REPLACED	47.20	47.20
1	REAR TAIL GATE EMBLEM (1.3)	REPLACED	40.10	40.10
1	REAR TAIL GATE WINDSCREEN MLDG	REPLACED	125.00	125.00
1	REAR END PANEL	REPAIRED SEE LABOUR	845.20	-
1	REAR BUMPER	REPLACED	1,230.20	1,230.20
2	REAR BUMPER REFLECTOR L/R @\$72.10	N/S REPLACED	144.20	72.10
1	REAR TAIL GATE CENTRE REFLECTOR	NOT NECESSARY	268.70	-
	LESS 10% DISCOUNT		-	-394.31
			5,993.70	3,548.79
SPECIAL NETT ITEMS				
6	REAR TAIL GATE INNER BOARD CLIPS @\$5.00 (SN)	REPLACED	30.00	30.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	REAR TAIL GATE WINDSCREEN SEALANT (SN)	REPLACED	100.00	40.00
1	SET REAR REVERSE SENSOR (SN)	REPLACED	350.00	200.00
			525.00	270.00
LABOUR				
	TO CHECK WIRING.		150.00	30.00
	TUFF KOTE.		150.00	40.00
	REMOVE & REPLACE REVERSE SENSOR.		150.00	40.00
	REMOVE & REFIX TAIL GATE WINDSCREEN.		150.00	100.00
	TO REMOVE & REPLACE SPARE PART & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,500.00	400.00
	TO SPRAY PAINTING & ETC.		1,400.00	600.00
			3,500.00	1,210.00



GRAND TOTAL		10,018.70	5,028.79
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CS/LAW19010611/Utd3e2

We have checked this model Dongfeng EQ 6380, at the time of accident is VERY RARE MODEL.
From our searches, as at June 2018, based on advertisement in local press, manufactured for a similar make and model of the same year, we computed as follow: in the attachment.

For vehicle average value model (similar make) in Nov 2008, as at accident date June 2018 average value is \$29,917/-

The nett value of the said vehicle, based on the average value of the said model is:

Average Value: \$29,917.00
LTA Rebate : \$4,101.00
Nett Value : \$25,816.00 (Estimate)

The cost of repair of \$3800 is economical to repair.

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.

it's value at the time of
accident as follows: —

Depreciated value : \$2500

\$3628

PART

Body value

~~\$2000~~ 1800

8128 7928

4101.00

Less Rebate

4027.327

Thus the cost of
repi of \$3800, is
economical to repi

At the time balance of
 approx 5 months, estimated
 market value computed as depreciated
 value of \$500 per month, thus

$$\$500 \times 5 = \$2500, (D.V.)$$

The value ^{is} since ~~subject~~ eligible
 for cost renewal, ~~its~~ value



$$\begin{array}{r} \text{MV} \quad 2500 \\ + 3628 \\ \hline \text{Sal} + 1500 \\ \hline \end{array}$$

~~20K~~ 20K - ~~FF~~ PART-

- 20
- PART
- 14835

DOA June 2018

Model . Don. L. 3

11 / 08
~~18~~

1.3. Lit

D. V

To: Joeann; assignments; Admin-D (LKKAUTO); SUR
Cc: Igene Lim; Charles Phua
Subject: RE: SINGLE JOINT EXPERT FOR MOTOR VEHICLE NO. GR 8969A // YOUR REF : MN.IG.B1.1611246 // COMLAW'S REF : PCS.2017.214577.aviva

Dear Joeann,

We have checked this model Daihatsu S200RV-SMLK, at the time of accident is a VERY RARE MODEL. We thus used balance market practice value, ~~and is entitled to renew COE.~~ *→ At the time of accident.*

Since Mrs vehicle
Deprecation Value
\$500 (per month) x 5 (balance 5 month)=\$2500
Body value \$2500
Total=\$5000

From our searches, as at Oct 2016, bases on advertisement in local press, manufactured for a similar make & model of the same year, we computed as follow : *in the attachment.*

MODEL YEAR	MODEL MONTH	ADVT. DATE	MAKE/MODEL	MODEL DESCRIPTIONS	S\$ '000
1999		29.07.16	TOYOTA LITEACE	VAN COE 3/2017	4.5
1999		30.07.16	TOYOTA LITEACE	VAN COE 3/2107	4.5
1999		31.07.16	TOYOTA LITEACE	VAN COE 3/2107	4.5
1999		01.08.16	TOYOTA LITEACE	VAN COE 3/2017	4.5
1999		02.08.16	TOYOTA LITEACE	VAN COE 3/2017	4.5
1999		04.08.16	TOYOTA LITEACE	VAN	4.5
				Average	4.5
2001	JUL	24.10.16	TOYOTA LITEACE	VAN COE 7/2021	35.8
2001	JUL	25.10.16	TOYOTA LITEACE	VAN COE 7/2021	35.8
2001	JUL	26.10.16	TOYOTA LITEACE	VAN COE 7/2021	35.8
2001	JUL	27.10.16	TOYOTA LITEACE	VAN COE 7/2021	35.8
2001	JUL	28.10.16	TOYOTA LITEACE	VAN COE 7/2021	35.8
				Average	35.8

We have for registered 1999 the average price is \$4.5K, whereas for 2001 average price is \$35.8, append ion per month in 24 months

From registration 1999 to 2001

$$\frac{\$35.8 - \$4.5}{24} = \$1.3K \text{ per month}$$

For vehicle in Oct average
$$\$4.5K + 10 \times \$1.3K = \$5.5K$$

12

*from statistical information,
vehicle registered in 1999.*

~~price~~ due to lack of information on model ²⁰⁰⁰,
 average price ^{changed} appreciation per month in
 24 months is as follows: -

$$(\$35,800 - \$4,500) \div 24 \text{ months}$$

is \$1,300 per month.

For vehicle ²⁰⁰⁸ ~~is~~ average value ^{June 2018} in ~~2000~~ ²⁰¹⁸,
 (similar value)

as at ~~Oct~~ accident date

^{June 2018} ~~Oct 2016~~ as follows. - average
 value is \$

$$\$4,500 + \frac{6}{12} \times \$1,300$$

$$= \underline{\underline{\$5,150.00}}$$

The ~~average~~ net value of the said
 vehicle, based on the average
~~retail~~ value of the said
 model, is.

Average value - UTA Rebate

$$\$5,150.00 - \$3.50$$

$$= \$5,147.00 \text{ (estimation)}$$

MODEL YEAR	MODEL MONTH	ADVT. DATE	MAKE/MODEL	S\$ '000
2008	AUG	04.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	05.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	06.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	07.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	08.06.18	PROTON SAGA 1.3A	26.7
2008	JUL	14.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	15.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	18.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	19.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	20.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUN	18.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	19.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	20.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	21.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	22.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	01.06.18	TOYOTA RUSH 1.5A	31.8
2008	JUN	04.06.18	TOYOTA RUSH 1.5A	31.8

Average Value Total: \$508,600/- 17

As at June 2018

\$30,000(EST)

153500
154000
152500
total 63600
all these
and divide

300000 29917 (est) 17

The answer is wrong

Your Ref no.: MC/MC6355/2019

Vehicle no. SJM 35005

LKK Ref no.: CS/LAW19010611/Utd3e2

MODEL YEAR	MODEL MONTH	ADVT. DATE	MAKE/MODEL	S\$ '000
2008	JUN	25.06.18	TOYOTA AXIO 1.5A	29.9
2008	JUN	26.06.18	TOYOTA AXIO 1.5A	29.9
2008	JUN	27.06.18	TOYOTA AXIO 1.5A	29.9
2008	JUN	28.06.18	TOYOTA AXIO 1.5A	29.9
2008	JUN	29.06.18	TOYOTA AXIO 1.5A	29.9
2008	JUN	18.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	19.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	20.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	21.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	22.06.18	TOYOTA RUSH 1.5A	31.5
2008	JUN	01.06.18	TOYOTA RUSH 1.5A	31.8
2008	JUN	04.06.18	TOYOTA RUSH 1.5A	31.8
2008	JUL	14.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	15.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	18.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	19.06.18	TOYOTA FIELDER 1.5A	30.8
2008	JUL	20.06.18	TOYOTA FIELDER 1.5A	30.8
2008	AUG	04.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	05.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	06.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	07.06.18	PROTON SAGA 1.3A	26.7
2008	AUG	08.06.18	PROTON SAGA 1.3A	26.7

Average Value Total
as at June 2018

\$658,100 / 22
29,913.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 3500S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAIL GATE	REPLACED	1,652.30	1,652.30
1	REAR TAIL GATE LOCK	REPLACED	268.30	268.30
1	REAR TAIL GATE LOCK CATCH	NOT NECESSARY	112.30	-
1	REAR TAIL GATE RUBBER	REPLACED	212.30	212.30
2	REAR TAIL GATE ABSORBER @\$258.00	NOT NECESSARY	516.00	-
1	REAR TAIL GATE INNER BOARD	NOT NECESSARY	236.30	-
1	REAR TAIL GATE CENTRE GARNISH	REPLACED	295.60	295.60
1	REAR TAIL GATE EMBLEM (MINI)	REPLACED	47.20	47.20
1	REAR TAIL GATE EMBLEM (1.3)	REPLACED	40.10	40.10
1	REAR TAIL GATE WINDSCREEN MLDG	REPLACED	125.00	125.00
1	REAR END PANEL	REPAIRED SEE LABOUR	845.20	-
1	REAR BUMPER	REPLACED	1,230.20	1,230.20
2	REAR BUMPER REFLECTOR L/R @\$72.10	N/S REPLACED	144.20	72.10
1	REAR TAIL GATE CENTRE REFLECTOR	NOT NECESSARY	268.70	-
	LESS 10% DISCOUNT		-	-394.31
			5,993.70	3,548.79
SPECIAL NETT ITEMS				
6	REAR TAIL GATE INNER BOARD CLIPS @\$5.00 (SN)	REPLACED	30.00	30.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	REAR TAIL GATE WINDSCREEN SEALANT (SN)	REPLACED	100.00	40.00
1	SET REAR REVERSE SENSOR (SN)	REPLACED	350.00	200.00
			525.00	270.00
LABOUR				
	TO CHECK WIRING.		150.00	30.00
	TUFF KOTE.		150.00	40.00
	REMOVE & REPLACE REVERSE SENSOR.		150.00	40.00
	REMOVE & REFIX TAIL GATE WINDSCREEN.		150.00	100.00
	TO REMOVE & REPLACE SPARE PART & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,500.00	400.00

Report Ref No. CS/LAW19010611/Utd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING & ETC.		1,400.00	600.00
			3,500.00	1,210.00
	GRAND TOTAL		10,018.70	5,028.79
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS/LAW19010611/Utd3e2

We have checked this model Dongfeng EQ 6380, at the time of accident is VERY RARE MODEL. From our searches, as at June 2018, based on advertisement in local press, manufactured for a similar make and model of the same year, we computed as follow: in the attachment.

For vehicle average value model (similar make) in Nov 2008, as at accident date June 2018 average value is \$29,913/-

The nett value of the said vehicle, based on the average value of the said model is:

Average Value: \$29,913.00
LTA Rebate : \$4,101.00
Nett Value : \$25,812.00

The cost of repair of \$3800 is economical to repair.

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.