

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8372Z

DATE : 12.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Indigo (ORL)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille <i>crack mandy</i>			\$ 1,227.50
	Unit Assy-SMART CRU (Radar Sensor) <i>mandy crack</i>			\$ 2,910.90
	Front Bumper Cover <i>distorted / crack</i>			\$ 418.30
	Front Bumper Sponge <i>trim</i>			\$ 86.90
	Front Bumper Reinforcement <i>HW</i>			\$ 1,075.10
	Front Bumper Towing Cover <i>distorted</i>			\$ 29.00
	Front Bumper Centre Moulding <i>mandy crack</i>			\$ 188.00
	Front Bumper Bracket Top (LH/RH) <i>HW</i>	\$	35.00	\$ 70.00
	Front Bumper Bracket (LH/RH) <i>HW</i>	\$	28.00	\$ 56.00
	Front Bumper Clips 10 pcs <i>NW</i>			\$ 22.00
	Headlamp Support Panel Assy <i>mandy crack HW</i>			\$ 949.30
	Headlamp (LH/RH) <i>mandy crack</i>	\$	1,198.80	\$ 2,397.60
	Radiator <i>HW</i>			\$ 510.50
	Radiator Shroud <i>HW</i>			\$ 275.50
	Radiator Air Guard (LH/RH) <i>HW</i>	\$	26.40	\$ 52.80
	Radiator Air Guard, Upr (LH/RH) <i>HW</i>	\$	27.50	\$ 55.00
	Aircon Condenser <i>HW</i>			\$ 663.60
				SUB TOTAL
				\$ 10,988.00
				LESS 20%
				\$ 2,197.60
				DISCOUNTED TOTAL
				\$ 8,790.40
	Labour Charge			
	Panel Beating			\$ 1,000.00 500/-
	Spray Painting Charge			\$ 250.00 200/-
	Wiring			\$ 50.00 30/-
	Towing Charge			\$ 60.00 HW
	Remove/Refix Aircon & Refill Gas			\$ 150.00 HW
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 150/-
				TOTAL LABOUR
				\$ 1,990.00

SHA 8372Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>HN</i>			\$ 2,480.40
	Boot Lid Rubber <i>HL</i>			\$ 127.40
	Boot Lid Lock Upper <i>HN</i>			\$ 224.00
	Boot Lid Key Lock <i>HN</i>			\$ 141.00
	Boot Lid 'H' Emblem <i>HN</i>			\$ 28.00
	Emblem -Hybrid <i>HN</i>			\$ 24.30
	Emblem -Ioniq <i>HN</i>			\$ 31.30
	Wiring Harness BWS Ext <i>HN</i>			\$ 988.90
	Boot Lid Glass, Lower <i>HN</i>			\$ 384.90
	Boot Lid Lamp (LH/RH) <i>CRK</i>	\$	794.40	\$ 1,588.80
	Boot Lid Trimboard <i>HN</i>			\$ 159.70
	Boot Lid Trimboard Clips (10pcs) <i>HN</i>			\$ 11.00
	Boot Lid Trimboard ,Centre <i>HN</i>			\$ 69.60
	Rear Bumper <i>distorted</i>			\$ 459.40
	Rear Bumper Reinforcement <i>CRK</i>			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) <i>broken</i>	\$	138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy <i>distorted</i>			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy <i>HN</i>			\$ 47.50
	Rear Bumper Stay <i>HN</i>			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) <i>HN</i>	\$	33.10	\$ 66.20
	Tail Lamp (LH/RH) <i>CRK</i>	\$	870.40	\$ 1,740.80
	Rear Panel <i>Distorted</i>			\$ 532.00
	Rear Panel Garnish <i>HN</i>			\$ 155.00
	Rear Panel Lower Panel <i>Distorted</i>	\$	39.40	\$ 78.80
	Spare Tyre Panel <i>Distorted</i>			\$ 892.50
	Spare Tyre Panel Cushion <i>HN</i>			\$ 309.50
	Rear Towing Hook <i>HN</i>			\$ 94.60
	Spare Tyre Flip Board <i>HN</i>			\$ 338.80
	Exhaust Pipe Insulator <i>HN</i>			\$ 35.00
	Exhaust Silencer <i>broken</i>			\$ 943.50
	Exhaust Pipe Hanger <i>HN</i>			\$ 29.20
	Rear Windscreen Glass <i>HN</i>			\$ 607.20
	Rear Windscreen Moulding <i>HN</i>			\$ 28.20
				SUB TOTAL
				\$ 13,777.85
				LESS 20%
				\$ 2,755.57
				DISCOUNTED TOTAL
				\$ 11,022.28
	Boot Lid Comfort Logo & Tel No.Sticker <i>HN</i>			\$ 30.00
	Rear No.Plates <i>CRK</i>			\$ 25.00
	Rear No.Plates Trim Cover <i>distorted / broken</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>Down</i>			\$ 135.70
	Rear Bumper Reserve Sensor <i>HN</i>			\$ 135.70
	Rear Bumper Reserve Light <i>broken</i>			\$ 140.00
	Rear Bumper Rubber Mat <i>HL</i>			\$ 50.00
	Rear Windscreen Sealant <i>HN</i>			\$ 46.00
				\$ 592.40

SHA 8372Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 800/-
	Spray Painting Charge			\$ 1,000.00 700/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 40/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Exhaust Pipe			\$ 150.00 60/-
	TOTAL LABOUR			\$ 3,140.00
	ESTIMATE TOTAL			\$ 25,535.08
<p>14/06/2019 @ 1500m not actual 2/3rds 10 days ? 'yan 2KK Auto</p> 				
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8372Z (Supplementary)

DATE : 14.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Keyless Antenna <i>broken</i>			\$ 638.00 ✓
	SUB TOTAL			\$ 638.00
	LESS 20%			\$ 127.60
	DISCOUNTED TOTAL			\$ 510.40
				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				