

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19010702/T1KA3Q2**Date:** 02/11/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant**Vehicle No :** SMK6459J**Insured Vehicle No :** SLZ1325C

Date of Loss: 23/04/2019

Nature of Claim: TP

Claim No: 5548737769SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMK6459J**

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FGKU112460

Reg. Date: 18/04/2019 (Man. Year: 2019)

Chassis No: KMHD841CMKU880859

Colour: Blue

Odometer: 3445 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Kumho 6 mm

Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side: Kumho 6 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,145.44	1,247.48	1,897.96	60.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	610.00	1,860.00	75.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,615.44	1,857.48	3,757.96	66.92
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	5,615.44	1,500.00	4,115.44	73.29
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		1,829.00		
Global Sum Settlement (S\$)		1,800.00		

INSPECTION

Date of Assignment: 17/06/2019

Date Inspected: 24/06/2019 Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22
Autobay
Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,853.70 FL	*- FL
2	1		*REAR BUMPER	Deformed	654.30 FL	*654.30 FL
3	1		*REAR BUMPER LOWER (GLOSS BLACK)	Cut	496.30 FL	*359.80 FL
4	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	171.80 FL	*- FL
5	1		*REAR BUMPER REFLECTOR RH	Cut	305.70 FL	*201.50 FL
6	1		*SET REAR NUMBER PLATE WITH CASING	Necessary	50.00 FS	*45.00 FS
7	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
8	1		*SET REAR SENSORS	Not Working	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,841.80	1,490.60
- List Item Discount on L Items 20.00/20.00% (\$)	696.36	243.12
Total Parts (\$)	3,145.44	1,247.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE	New	1,000.00	250.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	300.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	0.00
4	TO REMOVE/REFIT WIRING CHECKS	New	120.00	30.00
5	TO REMOVE/REPLACE REVERSE SENSORS AND DISTANCE SETTLING	New	150.00	30.00
Gross Labour Cost (\$\$)			2,470.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >