



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2003608  
INV Date 04/05/2020  
Reference CC6/CTI19010718/Aka3q2  
Code CTI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SMH 1356X  
Insured Veh. GBH 8962E  
Claim No. SNM19D202794  
Policy No. DMCVSN3069001800  
Accident Date 11/06/2019  
Inspection Date 13/06/2019

Description	Total
Third Party Express Settlement	400.00
Registered Mail Fee	2.37
<b>Subtotal</b>	<b>402.37</b>
<b>GST (7%)</b>	<b>28.17</b>
<b>Grand Total</b>	<b>430.54</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19010718/Aka3q2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 04-05-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 8962E	Veh. Inspected	SMH 1356X
Policy No.	DMCVSN3069001800	Coverage (\$)	0.00
Claim No.	SNM19D202794	Excess (\$)	0.00
Assign From		Assign Date	13/06/2019

### 2. Vehicle Particulars & Condition

Make & Model	B.M.W. 320I	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WBAPG56040NL22056	Colour	WHITE
Odometer	202224	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	ANTARES	6 mm
L/H Front Tyre	215/55 R17	ANTARES	6 mm
R/H Rear Tyre	215/55 R17	ANTARES	6 mm
L/H Rear Tyre	215/55 R17	ANTARES	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	11/06/2019	Inspection Date	13/06/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 1356X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DISTORTED	1,530.00	1,250.00
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	115.30	115.30
1	REAR BUMPER SENSOR	DAMAGED	320.00	250.00
1	REAR BUMPER SENSOR RUBBER	NECESSARY	12.00	12.00
1	REAR BUMPER SENSOR HOLDER	NOT NECESSARY	42.00	-
1	REAR BUMPER BEAM	NOT NECESSARY	277.00	-
1	REAR BUMPER REINFORCEMENT	BENT	569.00	569.00
1	TAILLAMP LH	CRACKED	420.00	420.00
1	TAILLAMP LOWER BRACKET LH	CRACKED	90.00	90.00
1	REAR END PANEL	NOT NECESSARY	890.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	255.60	-
	LESS 5% DISCOUNT		-226.05	-135.32
			4,294.85	2,570.98
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	22.00	22.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-
			162.00	22.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING ,REMOVING AND REPLACING PARTS.		1,000.00	300.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	250.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK .		150.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	50.00
			2,520.00	630.00
	<b>GRAND TOTAL</b>		<b>6,976.85</b>	<b>3,222.98</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,500.00</b>

Report Ref No. CC6/CTI19010718/Aka3q2



Report Ref No. CC6/CTI19010718/Aka3q2

A handwritten signature in black ink, appearing to read 'A.L.P.' or similar, enclosed in a light gray rectangular box.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 1356X

INSPECTION





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 1356X

RE-INSPECTION





## **LKK Auto Consultants Pte Ltd**

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

