

22/02/2012

ASS. REC. BY:

REF: CS/MSG 19010731/KV01312

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chhin Nyuc Pui

of MS19

Date/Time: 18.6.19 9.09A.M

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC 4018C

Insured: GBH 52803

at Workshop m/s Wei Lee Motor

Tel: 6456 9830

of Block 9 Sin Ming Industrial Estate #01-32

Policy No: 29087305 MKC

Claim No: 596619

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 18.6.19 9.27A.M

Person Contacted:

Karen

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SKC 4018C - NBA/LIP 1801079514	D.O.A - 05/10/2018
	GBH 52803-X	
19/6/19	Send preli revised via merimen	
24/6	LT Lim @ 840501 email & confirm (Ref 2590.29, 399)	

REF: MS14

## ASSIGNMENT

From:

Date: 18/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKC 4018C

at Workshop n/s

Wei Lee Motor

of Blk 9 Sin Ming Ind. Est #01-32

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKC 4018C

Yr Regn:

08/11

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tay Air

C.C

1598

Colour

M. Gold

A/C: Insured / Std / NI / NA

Sp. Reading

-

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053REE104120688

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Yoko

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

13/6/19

D.O.I.

18/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Barry Day

RECEIVED 25 JUN 2019

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2) 25/6 - typist

Report Format:

MRimen

Lump Sum / L&amp;L:

4050/2

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

3 + RS. \$

Photos:

Others:

TOTAL

150

11

161

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Chhia Nyuk Pui	Date: 19 Jun 2019

**Preliminary Advice**

Insured Vehicle No	: GBH5280J	Accident Date	: 13/06/2019
TP Vehicle No	: SKC4018C	Assignment Date	: 18/06/2019
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 6
Date of Inspection	: 18/6/2019		
Inspection At	: WEI LEE MOTOR WORKS		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,640.29
Revised Amount	:S\$	5,090.68
Check Items (Estimated)	:S\$	109.05
Total	:S\$	5,199.73
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jun 2019		18 Jun 2019 09:09 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>		<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	--	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:

Main Claimant:

Vehicle Reg. No.:

Claim Type:

Vehicle Reg. No. (Insured):

Repairer:

Handling Insurer:

Adjuster:

Adj Asg. Remarks:

CFI TRANSPORT PTE LTD, Co. Reg. No.: 201806390H

KH LEASING PTE. LTD., Co. Reg. No.: 201611813C

SKC4018C

TP / 596619

GBH5280J

Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/06/2019]

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/06/2019]

on WP. (manual assigned) Liab: dispute (OI NR) TP agree on SJE - assign LKK . Contact: Karen Seah @ 6456 9830 Manually assigned to LKK via email on 17/06/2019

Date of Loss:

Policy/Cover Note No.:

Policy No. (Claimant):

Excess:

13/06/2019 00:00 - :59  
[93 Months and 22 Days From LTA Reg Date (Man Yr)]

29087305MKC (Comprehensive)  
Coverage: 30/06/2018 - 29/06/2019

[Created by insurer]

View All

Compose Case Mail

**ASSOCIATED MAIL RECEIVED**

There are no mail for this case.

**ALL ASSOCIATED TASKS**

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Sent:** Monday, 17 June 2019 4:58 PM  
**To:** assignments@lkkauto.com; admin-d@lkkauto.com  
**Cc:** Ong Zi Hui  
**Subject:** Survey Request - Manual Assigned  
**Attachments:** doc03050920190615101530.pdf

### TP survey for vehicle no: SKC4018C DOA: 13/06/19 GBH5280J (MSIG)

#### Manual Assigned

Dear LKK

Refer to the email below and attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Nabilah Rasol

**Sent:** Monday, 17 June, 2019 4:26 PM

**To:** Ong Zi Hui <zihui\_ong@sg.msig-asia.com>; Crystal Lee <crystal\_lee@sg.msig-asia.com>

**Subject:** FW: TP survey for vehicle no: SKC4018C DOA: 13/06/19 GBH5280J (MSIG)

**From:** Nabilah Rasol

**Sent:** Monday, 17 June, 2019 4:25 PM

**To:** 'karen Seah' <[weileemotorworks@gmail.com](mailto:weileemotorworks@gmail.com)>

**Cc:** Chhia Nyuk Pui <[NyukPui\\_Chhia@sg.msig-asia.com](mailto:NyukPui_Chhia@sg.msig-asia.com)>

**Subject:** RE: TP survey for vehicle no: SKC4018C DOA: 13/06/19 GBH5280J (MSIG)

Dear Sirs,

Thank you for your selection.

We will proceed to assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

**Nabilah Rasol (Ms)**

Admin Officer, Claims Services (Motor)

Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** karen Seah [<mailto:weileemotorworks@gmail.com>]

**Sent:** Monday, 17 June, 2019 12:14 PM

**To:** Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>

**Subject:** Re: TP survey for vehicle no: SKC4018C DOA: 13/06/19 GBH5280J (MSIG)

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Vehicle No: SKC4018C/GBH5280J

Dear Nabilah Rasol

Please arrange LKK Auto Consultants to survey our vehicle No: SKC4018C.

Thank you.

On Mon, Jun 17, 2019 at 11:47 AM Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)> wrote:

Hi Karen,

We refer to your email dated 15/06/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd

5) MSIG In-House Surveyors (appointment full on 17.06.2019)

\*This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor\*

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Frankie Pang
2) Kenneth Kong	7) Ng You Han
3) Marcus Chua	8) Gary Soon
4) Henry Ng	9) Chow Bo Xiong
5) Lau Kwok Kwong	10) Axel Lee

NB:

(a) \*Fast lane settlement is not applicable for cases that liability is in dispute\*

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: [motorsurvey@sg.msg-asia.com](mailto:motorsurvey@sg.msg-asia.com)

Have a great week ahead!

Nabilah Rasol (Ms)

Admin Officer, Claims Services (Motor)

Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msg-asia.com](mailto:nabilah_rasol@sg.msg-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** karen Seah [<mailto:weileemotorworks@gmail.com>]  
**Sent:** Saturday, June 15, 2019 10:15 AM  
**To:** Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>  
**Subject:** TP survey for vehicle no: SKC4018C

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Your insured vehicle no: GBH5280J

Accident involving vehicle no: SKC4018C/GBH5280J

DOA:13/06/2019 AT Along Macritchie Viaduct twds Upp Thomson

Dear officer incharge

I refer to the above, attached with the accident report.

Kindly arrange to survey the vehicle ASAP.

Thank you.

--

Best Regards,

Karen Seah

-----



Wei Lee Motor Works

Block 9 Sin Ming Industrial Estate

#01-32 Singapore 575644

Tel: 6456 9830

Fax: 6458 0128

Company registration: 269436/00J

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately; delete the email and do not copy, distribute or disclose its contents.

--

Best Regards,

Karen Seah

-----  
Wei Lee Motor Works

Block 9 Sin Ming Industrial Estate

#01-32 Singapore 575644

Tel: 6456 9830

Fax: 6458 0128

Company registration: 269436/00J

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	1813C
<b>Vehicle Details</b>	
Vehicle No.:	SKC4018C
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Beige
Manufacturing Year:	2011
Engine No.:	1ZRX111681
Chassis No.:	MR053REE104120664
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$15,263.00
Original Registration Date:	22 Aug 2011
First Registration Date:	22 Aug 2011
Transfer Count:	1
Actual ARF Paid:	\$15,263.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Aug 2021
PARF Rebate Amount:	\$9,157.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$50,244.00
COE Rebate Amount:	\$10,913.00
<b>Total Rebate Amount:</b>	<b>\$20,070.00</b>

The information contained herein is correct as at 19 Jun 2019

OK

威利摩哆

21/8/2011

# WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

*Signature*  
19/8/11

*Not Wharke*  
*61 Sng 8?*  
*Resurvey After Paint*

15, JUNE 2019

MSIG Insurance (S) PL  
4 Shenton Way #21-01  
SGX Centre 2  
S 068807

Attn: motor claim dept-3<sup>rd</sup> party claim

Claiming against your insured vehicle no: GBH5280J

Accident involving vehicle no: SKC4018C/GBH5280J

DOA: 13/08/2019 At Along Macritchie viaduct twds Upp Thomson

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

*6 days*

Adged by Repairer  
Signature:  
Date:

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SKC4018C

To supply---

Description	Qty	Amount	
Rear bumper	1 <i>BH/cm</i>	482.00	✓
Rear bumper retainer-long @66.70	2 <i>D-1</i>	133.40	✓
Rear bumper retainer-small @29.40	2 <i>D-1</i>	52.80	✓
Rear bumper retainer-below taillamp @72.70	2 <i>sm</i>	145.40	✓
Rear bumper sponge	1 <i>CMA</i>	117.50	✓
Rear bumper bracket @82.80	2 <i>011 B1</i>	165.60	✓
Taillamp @281.90	2 <i>mg cm</i>	563.80	✓
Lid	1 <i>Ry</i>	754.30	✓
Lid-1.6 emblem	1 <i>Re</i>	32.10	✓
Lid-VVTI emblem	1 <i>Re</i>	38.40	✓
Lid-Altis emblem	1 <i>Re</i>	42.30	✓
Lid-corolla emblem	1 <i>Re</i>	44.10	✓
Lid lock	1 <i>D-1</i>	96.50	✓
Lid chrome handle	1 <i>CMA</i>	332.90	✓
Lid weather strip	1 <i>Dis 11A</i>	175.35	✓
Lid reflector @116.60	2 <i>Al Sem</i>	233.20	✓
End panel	1 <i>Ry</i>	581.20	✓
End panel top garnish	1 <i>mg D-1</i>	185.20	✓
Spare tyre panel	1 <i>R</i>	702.90	X
Parts		4,878.95	
Parts less 25%		1,219.74	
		3,659.21	
spare tyre board <i>CMA</i> ✓	1	348.10	✓

*87.68*

Reverse sensor  
To remove damaged parts and attachments.  
Cut n weld damaged panel.  
Straighten rear chassis where necessary.  
Repair/reshape damaged/dented areas.  
Replace/realign all parts into position.  
To spray paint

Shay 220.00 20052

1,300.00 8001  
1,200.00 10001

-----  
6,379.21

6640.29

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010731/KVD3N2

Date: 27/06/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29087305MKC
Claimant Vehicle No :	SKC4018C	Insured Vehicle No :	GBH5280J
Date of Loss:	13/06/2019	Nature of Claim:	TP
		Claim No:	596619

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKC4018C	Engine No:	1ZR111681
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104120664
Reg. Date:	22/08/2011 (Man. Year: 2011)	Odometer:	0 km
Colour:	Metallic Gold		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,140.29	3,290.68	849.61	20.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,800.00	700.00	28.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,640.29</b>	<b>5,090.68</b>	<b>1,549.61</b>	<b>23.34</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,050.00</b>		
<b>(S\$)</b>	6,640.29	4,050.00	2,590.29	39.01
<b>+ GST 7.00/7.00% (S\$)</b>	464.82	283.50	181.32	39.01
<b>Nett Amount (S\$)</b>	<b>7,105.11</b>	<b>4,333.50</b>	<b>2,771.61</b>	<b>39.01</b>

## INSPECTION

Date of Assignment:	18/06/2019	
Date Inspected:	18/06/2019 Inspected At:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 Singapore 575644
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2019)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKC4018C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent/Cracked	482.00 FL	*482.00 FL
2	2		*REAR BUMPER RETAINER-LONG	Distorted	133.40 FL	*133.40 FL
3	2		*REAR BUMPER RETAINER-SMALL	Distorted	52.80 FL	*52.80 FL
4	2		*REAR BUMPER RETAINER-BELOW TAILLAMP	Serviceable	145.40 FL	*- FL
5	1		*REAR BUMPER SPONGE	Cracked	117.50 FL	*117.50 FL
6	1		*REAR BUMPER BRACKET	O/s Bent	165.60 FL	*82.80 FL
7	2		*TAILLAMP	Mtg Cracked	563.80 FL	*563.80 FL
8	1		*LID	Bent	754.30 FL	*754.30 FL
9	1		*LID-1.6 EMBLEM	Necessary	32.10 FL	*32.10 FL
10	1		*LID-VVTI EMBLEM	Necessary	38.40 FL	*38.40 FL
11	1		*LID-ALTIS EMBLEM	Necessary	42.30 FL	*42.30 FL
12	1		*LID-COROLLA EMBLEM	Necessary	44.10 FL	*44.10 FL
13	1		*LID LOCK	Distorted	96.50 FL	*96.50 FL
14	1		*LID CHROME HANDLE	Cracked	332.90 FL	*332.90 FL
15	1		*LID REFLECTOR	N/s Cracked	233.20 FL	*116.60 FL
16	1		*END PANEL	Bent	581.20 FL	*581.20 FL
17	1		*END PANEL TOP GARNISH	Mtg Distorted	185.20 FL	*185.20 FL
18	1		*SPARE TYRE PANEL	Repair	702.90 FL	*- FL
19	1		*SPARE TYRE BOARD	Cracked	348.10 FL	*348.10 FL
20	1		*LID WEATHER STRIP (50%)	Distorted/Dented	131.52 FS	*87.68 FS
21	1		*REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,403.22</b>	<b>4,291.68</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,262.93</b>	<b>1,001.00</b>
<b>Total Parts (\$\$)</b>	<b>4,140.29</b>	<b>3,290.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.CUT N WELD DAMAGED PANEL.STRAIGHTEN REAR CHASSIS WHERE NECESSARY.REPAIR/RESHAPE DAMAGED/DENTED AREAS.REPLACE/REALIGN ALL PARTS INTO POSITION	New	1,300.00	800.00
2	TO SPRAY PAINT	New	1,200.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,500.00</b>	<b>1,800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >