

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTMSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807**Our File No:** CS/MSG19010741/KQD3E2**Date:** 01/06/2020**REFERENCE**

Insured/Claimant:	CHOO XIU HUI	Policy No:	28824089QMY	
Date of Loss:	30/05/2019	Nature of Claim:	OD	Claim No: 595344

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDK6776A		
Make & Model:	FORD MUSTANG, 2.3 (A)	Engine No:	G5286908H
Reg. Date:	15/09/2016 (Man. Year: 2016)	Chassis No:	1FA6P8TH9G5286908
Colour:	White	Odometer:	40955 km
Engine Capacity:	2261 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40Z R19	Rear Tyre Size:	255/40Z R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,193.00	17,105.00	11,088.00	39.33
Miscellaneous Items	338.00	110.00	228.00	67.46
Labour	1,915.00	1,835.00	80.00	4.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	30,446.00	19,050.00	11,396.00	37.43
- Excess (\$\$)	0.00	1,500.00	-1,500.00	
(\$\$)	30,446.00	17,550.00	12,896.00	42.36
+ GST 7.00/7.00% (\$\$)	2,131.22	1,228.50	902.72	42.36
Nett Amount (\$\$)	32,577.22	18,778.50	13,798.72	42.36

INSPECTION

Date of Assignment:	18/06/2019 Present Location:	K Kim Hin Auto Pte Ltd (HQ)
Date Inspected:	18/06/2019 Inspected At:	K Kim Hin Auto Pte Ltd (HQ)
		160 Sin Ming Drive #02-20, Sin Ming
		AutoCity
		Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Jun 2020)	
Parts:	N/A	FORD MUSTANG 2.3 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDK6776A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIRBAG MODULE (WCP)	Necessary	2,350.00 F	*2,350.00 F
2	1	NA	*BONNET (WCP)	Buckled	1,800.00 F	*1,800.00 F
3	1	NA	*BONNET CABLE (WCP)	Serviceable	150.00 F	*- F
4	1	NA	*BONNET INSULATION (WCP)	Serviceable	165.00 F	*- F
5	1	NA	*BONNET LOCK (WCP)	Distorted	100.00 F	*100.00 F
6	1	NA	*BONNET SAFETY LATCH (WCP)	Bent	65.00 F	*65.00 F
7	1	NA	*BONNET STAY (WCP)	Serviceable	110.00 F	*- F
8	1	NA	*CENTRE IMPACT SENSOR (WCP)	Serviceable	150.00 F	*- F
9	1	NA	*CONDENSER (WCP)	Bent	800.00 F	*800.00 F
10	1	NA	*CTR FRT AIR CHANNEL (WCP)	Serviceable	160.00 F	*- F
11	1	NA	*CTR UPP AIR CHANNEL (WCP)	Serviceable	130.00 F	*- F
12	1	NA	*ELECTRIC FAN CPL (WCP)	Serviceable	750.00 F	*- F
13	1	NA	*FR LWR BUMPER GRILLE (WCP)	Serviceable	165.00 F	*- F
14	1	NA	*FRONT AIR DEFLECTOR (WCP)	Serviceable	265.00 F	*- F
15	1	NA	*FRONT BONNET SEAL (WCP)	Serviceable	140.00 F	*- F
16	1	NA	*FRONT BUMPER CPL (WCP)	Buckled	930.00 F	*930.00 F
17	1	NA	*FRONT GRILLE (WCP)	Distorted / Dented	255.00 F	*255.00 F
18	1	NA	*FRONT SPOILER (WCP)	Serviceable	205.00 F	*- F
19	1	NA	*FRT BUMPER C-MEMBER (WCP)	Repair	750.00 F	*- F
20	1	NA	*FRT LOCK CARRIER (WCP)	Cracked	800.00 F	*800.00 F
21	1	NA	*FRT LWR GRILLE COVER (WCP)	Serviceable	64.00 F	*- F
22	1	NA	*FRT NO PLATE REINF (WCP)	Cracked	300.00 F	*300.00 F
23	1	NA	*GRILL BRACKET (WCP)	Serviceable	90.00 F	*- F
24	1	NA		Serviceable	200.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*HORN (WCP)			
25	1	NA	*INN BUMPER REINFORCE (WCP)	Bent	190.00 F	*190.00 F
26	1	NA	*KNEE AIRBAG (WCP)	Burst	2,200.00 F	*2,200.00 F
27	1	NA	*L/BONNET HINGE (WCP)	Distorted	255.00 F	*255.00 F
28	1	NA	*L/BONNET PYROELEMENT (WCP)	Necessary	360.00 F	*360.00 F
29	1	NA	*L/BUMPER GRILLE (WCP)	Dented	120.00 F	*120.00 F
30	1	NA	*L/CLIP (WCP)	Necessary	15.00 F	*15.00 F
31	1	NA	*L/CLIP (WCP)	Necessary	15.00 F	*15.00 F
32	1	NA	*L/F AIR DUCT (WCP)	Serviceable	100.00 F	*- F
33	1	NA	*L/F BONNET STOP (WCP)	Serviceable	30.00 F	*- F
34	1	NA	*L/F OUT BUMPER BRKT (WCP)	Repair	90.00 F	*- F
35	1	NA	*L/F SHOCK SENSOR (WCP)	Serviceable	150.00 F	*- F
36	1	NA	*L/F UPP AIRBAG SENS (WCP)	Serviceable	260.00 F	*- F
37	1	NA	*L/F WHEELHOUSE COVER (WCP)	Serviceable	98.00 F	*- F
38	1	NA	*L/F W-HOUSE FRT CVR (WCP)	Serviceable	95.00 F	*- F
39	1	NA	*L/F WING (WCP)	Buckled / Cracked	540.00 F	*540.00 F
40	1	NA	*L/F WING INSULATOR (WCP)	Serviceable	100.00 F	*- F
41	1	NA	*L/F WIPER ARM (WCP)	Serviceable	500.00 F	*- F
42	1	NA	*L/GAS DISCHARGE LAMP (WCP)	Serviceable	570.00 F	*- F
43	1	NA	*L/HEADLAMP W-HARNESS (WCP)	Serviceable	160.00 F	*- F
44	1	NA	*L/R AIR DUCT (WCP)	Serviceable	60.00 F	*- F
45	1	NA	*LEFT HEADLAMP ASSY (WCP)	Mtg Cracked	1,560.00 F	*1,560.00 F
46	1	NA	*LWR RAD GRILLE MLDG (WCP)	Serviceable	50.00 F	*- F
47	1	NA	*R/BONNET HINGE (WCP)	Distorted	255.00 F	*255.00 F
48	1	NA	*R/BONNET PYROELEMENT (WCP)	Serviceable	360.00 F	*- F
49	1	NA	*R/BUMPER GRILLE (WCP)	Serviceable	120.00 F	*- F
50	1	NA	*R/CLIP (WCP)	Necessary	15.00 F	*15.00 F
51	1	NA	*R/CLIP (WCP)	Necessary	15.00 F	*15.00 F
52	1	NA	*R/F AIR DUCT (WCP)	Cracked	150.00 F	*150.00 F
53	1	NA	*R/F BONNET STOP (WCP)	Serviceable	30.00 F	*- F
54	1	NA	*R/F OUT BUMPER BRKT (WCP)	Repair	90.00 F	*- F
55	1	NA	*R/F SHOCK SENSOR (WCP)	Serviceable	150.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1	NA	*R/F UPP AIRBAG SENS (WCP)	Serviceable	260.00 F	*- F
57	1	NA	*R/F WHEELHOUSE COVER (WCP)	Serviceable	98.00 F	*- F
58	1	NA	*R/F W-HOUSE FRT CVR (WCP)	Serviceable	95.00 F	*- F
59	1	NA	*R/F WING (WCP)	Buckled	540.00 F	*540.00 F
60	1	NA	*R/F WING INSULATOR (WCP)	Serviceable	100.00 F	*- F
61	1	NA	*R/F WIPER ARM (WCP)	Serviceable	430.00 F	*- F
62	1	NA	*R/GAS DISCHARGE LAMP (WCP)	Serviceable	570.00 F	*- F
63	1	NA	*R/HEADLAMP W-HARNESS (WCP)	Serviceable	160.00 F	*- F
64	1	NA	*R/R AIR DUCT (WCP)	Serviceable	60.00 F	*- F
65	1	NA	*RADIATOR (WCP)	Serviceable	1,750.00 F	*- F
66	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Mtg Cracked	1,560.00 F	*1,560.00 F
67	1	NA	*UPP RAD GRILLE MLDG (WCP)	Serviceable	50.00 F	*- F
Supplementary #1						
68	1		*L/RAD-GRILLE BRACKET (WCP)	Bent	180.00 F	*180.00 F
69	1		*R/RAD-GRILLE BRACKET (WCP)	Bent	180.00 F	*180.00 F

F=Franchise part.

Sub Total (\$\$)	25,630.00	15,550.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	2,563.00	1,555.00
Total Parts (\$\$)	28,193.00	17,105.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AIR CON GAS (NECESSARY)	250.00	50.00
2	1	FRT NUMBER PLATE (CRACKED)	40.00	40.00
3	1	RADIATOR COOLANT (NECESSARY)	48.00	20.00
Sub Total (S\$)			338.00	110.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	780.00	780.00
2	Total Panel/Mechanical Labour	New	1,135.00	1,055.00
Gross Labour Cost (S\$)			1,915.00	1,835.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >