



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## General Details

Involving1 2018 MERCEDES V260 (SKS400Z)

Date of Loss17 June 2019

Time of Loss9.35

Loss DescriptionSKS400Z (INSD) C/W SHC8571E (TP)

Comment

## Workshop Details

Total Rebate Amount

87552

Nett Loss Amount\$169,448.00

Assigned WorkshopLKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion \*

20



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details



Vehicle Registration#	SKS400Z	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>09/04/2019</div> <div></div>
Mileage	<div>5924</div>	Age of Vehicle	0

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2018	<div>2018</div>
Make	MERCEDES	<div>MERCEDES BE</div>
		<div></div>

## Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	ANSARI S/O TANJORE MUTHUSAMI RETHINASAMI	<div></div>
Date of Birth	2 April 1955	<div>dd/mm/y</div> <div></div>

Model CATEGORY	V260 POLICY INFORMATION	V260 AVG L INFORMATION
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	WDF44781323546661	<input type="text" value="WDF4478132"/>
Engine No	274920E0258388	<input type="text" value="274920E0258"/>
Engine Capacity		<input type="text" value="1991"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="257000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Age	64	
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	42	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date	1 January 1977	<input type="text" value="dd/mm/y"/> 
License Expiration Date		<input type="text" value="dd/mm/y"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	7 JALAN PELANGI, 268324, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Male	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	S1104659B	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

18/06/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

600

Young/Inexperienced/  
Unnamed Driver  
Excess

0

## Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save







# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		RH/TAIL LAMP	Cracked	0	723.67	No					723.67	Reviewing
		0	1		REAR WINDSCREEN SOLAR HUPER OPTIK FILM	Serviceable	0	0	No					0	Deny
		0	1		TAILGATE	Bent	0	2027.43	No					2027.43	Reviewing
		0	1		TAILGATE CHROME MOULDING	Serviceable	0	0	No					0	Deny
		0	1		V260 MODEL PLATE	Necessary	0	46.59	No					46.59	Reviewing
		0	1		REAR WINDSCREEN SEAL	Serviceable	0	0	No					0	Deny
		0	1		REAR WINDSCREEN	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		REAR BUMPER	Cut	0	1237.21	No					1237.21	Reviewing
		0	1		RH/ REAR BUMPER MOUNTING RAIL	Serviceable	0	0	No					0	Deny
		0	1		RH/ REAR BUMPER REFLECTOR	Serviceable	0	0	No					0	Deny
		0	1		LH/ REAR BUMPER REFLECTOR	Serviceable	0	0	No					0	Deny
		0	2		REAR DISTANCE SENSOR	Serviceable	0	0	No					0	Deny
		0	2		SPACER RING	Serviceable	0	0	No					0	Deny
		0	1		REAR BUMPER REINFORCEMENT	Serviceable	0	0	No					0	Deny
		0	5		BLIND RIVET	Necessary	0	1.26	No					6.3	Reviewing
		0	4		NUT	Necessary	0	3.49	No					13.96	Reviewing
		0	1		MERCEDES STAR	Necessary	0	40.87	No					40.87	Reviewing
		0	4		RIVET NUT	Necessary	0	3.08	No					12.32	Reviewing

Labour













Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
------	----------	----------------------------	-----------	---------------------------	---------------------------	--------------------------	--------------------------	--------------------	---------

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
	 	0		DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	0	1920	0	0	Reviewing	
	 	0		RESPRAY TAILGATE & REAR BUMPER	0	1200	0	0	Reviewing	
	 	0		USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	0	480	0	0	Reviewing	
	 	0		CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	0	120	0	0	Reviewing	
	 	0		REMOVE & TRANSFER TAILGATE MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR	0	400	0	0	Reviewing	
	 	0		REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL	0	640	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00				Adjusted Claim Amount	\$8,268.35	
CATEGORY		ESTIMATE				ADJUSTED		
Spare Parts		\$0.00				\$4,108.35		
Labour		\$0.00				\$4,760.00		
Excess						-\$600.00		

Submit for Review