

ASS. REC. BY:

REF: CS/MSG/9010793/K9013112

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Keng Ong Thiam Beng of MSG Date/Time: 18-6-19 14:55 pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 6282K Insured: SLN 2250R

at Workshop m/s Chuan Ho Auto Tel: 90691935

of 160 Sin Ming Drive, #07-09

Policy No: 29082463 Claim No: 580943

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 30.12.2018

CA / REV / REP. / REV 24 HRS 196.2019

Date/Time: 18-6-19 3:01 pm H.O.D. Endorsement:

Person Contacted: Sharon Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SLB 6282K - X	
	SLN 2250R - X	
20/6/19 @ 2:43pm	revised to Keng Ong via messenger	

(08/11/13)

ASS. REC. BY: Kenneth

REF MS19

ASSIGNMENT

From: Date: 19/6/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLB 622K

at Workshop m/s Chuan HO Auto

at 160 sin ming Drive #07-09

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: After 200pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res: Yes or No

Lum Sum: 12.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLB 622K Yr Regn: 11, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 c.c. 1496

Colour: M.D. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 32475 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD Air / Rim or

Tyre Size: F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 30/12/18

D.O.I. 19/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/6 @ 520h Confirm CRK @ 80, 26/6

RECEIVED 20 JUN 2019

20/6/2019

Date/Time, File Pass to?

1) 20/6 11:00

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: MER-TP

Lump Sum / I.B.I. (\$ 520)

150

11

161

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Keny Ong Thiam Beng

Date: 20 Jun 2019

Preliminary Advice

Insured Vehicle No	: SLN2250R	Accident Date	: 30/12/2018
TP Vehicle No	: SLB6282K	Assignment Date	: 18/06/2019
Make	: MAZDA M3	Est. Duration of Repair	: 2.00
Date of Inspection	: 19/06/2019		
Inspection At	: CHUAN HO AUTO SERVICE (SIN MING) 160 SIN MING DRIVE, #07-09, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	700.00
Revised Amount	:S\$	520.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	520.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2019		18 Jun 2019 14:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	TANG KUM SHIN, ID: S13431321								
Vehicle Reg. No.:	SLB6282K	Date of Loss:	30/12/2018 18:00 - :59 [13 Months and 24 Days From TA Reg Date (Man Yr)]						
Claim Type:	TP / 580943	Policy/Cover Note No.:	29088463 (Comprehensive) Coverage: 02/07/2018 - 01/07/2019						
Vehicle Reg. No. (Insured):	SLN2250R	Policy No. (Claimant):							
		Excess:							
Repairer:	Chuan Ifo Auto Service (Sin Ming) 160 Sin Ming Drive, #07-09, Sin Ming AutoCity, 575722 Sin Ming - Tel: 91892365								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Keny Ong Thiam Beng - 6643 1309]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/06/2019]								
Driver/Custodian (Insured):	BRIAN NG GUAN MING (), NRIC: S7925643I, Tel: +6590687070 Email:								
Adj Asg. Remarks:	Car in 19/06/19, survey after 2pm. on WP. Please contact us ASAP if you cannot attend this assignment. SHARIN AGREE LKK TO SURVEY VEHICLE. LIABILITY: 100% CONTACT: SHARIN 9069 1985								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

CHUAN HO AUTO SERVICE
SIN MING AUTO CITY
160 SIN MING DRIVE #07-09
SINGAPORE 575722

Vehicle & Document Information

ESTIMATE : SLB 6282 K

Date: 19/06/2019

Vehicle No: SLB 6282 K

Make/Model: MAZDA 3

S/N	Description	Qty	Repairer's Est	Revised Est
1	PANEL BEATING ON RHR FENDER		\$ 1201	200.00
1	TO PUTTY, PRIMER, RE-SPRAY RHR FENDER AND RHR BUMPER		\$ 4001	500.00
Labour Total :			\$	700.00

CHUAN HO AUTO SERVICE



*Not with cash
Payment After Paint
2 days
\$ 520.00*

LUX Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010793/KQD3N2

Date: 21/06/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29088463
Claimant Vehicle No :	SLB6282K	Insured Vehicle No :	SLN2250R
Date of Loss:	30/12/2018	Nature of Claim:	TP
		Claim No:	580943

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB6282K	Engine No:	P520478597
Make & Model:	MAZDA M3, 1.6 (A)	Chassis No:	JM6BN22A8J0187706
Reg. Date:	06/11/2017 (Man. Year: 2017)	Odometer:	32475 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 9 mm	Rear Left Side:	Toyo 9 mm
Front Right Side:	Toyo 9 mm	Rear Right Side:	Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	520.00	180.00	25.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	700.00	520.00	180.00	25.71

INSPECTION

Date of Assignment:	18/06/2019	
Date Inspected:	19/06/2019	Inspected At: Chuan Ho Auto Service (Sin Ming) 160 Sin Ming Drive, #07-09, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 20 Jun 2019)
Parts:	143	MAZDA M3 1.6 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLB6282K)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON RHR FENDER.	New	200.00	120.00
2	TO PUTTY, PRIMER, RE-SPRAY RHR FENDER AND RHR BUMPER.	New	500.00	400.00
Gross Labour Cost (\$\$)			700.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >