



Case Details

Case Reference Number : TAX/06/19/2060
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB386G

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-7339-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 15/06/2019 01:55 PM
 Vehicle Age(In Months) : 56

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	SMRT Recommendation							Surveyor Approval				
			Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main		6505517	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	DEF
Standard	Main	BODY RH	6505557	FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	0	0	Check	
Standard	Main	Body	6505640	NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Check	
Standard	Main	UNDERCARRIAGE	6505553	FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check	
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	hee
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	nee
One Time Key In	Main			LENS & BODY,FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	nn
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Give	nn
One Time Key In	Main			BRACKET, FR TURN	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Give	nn
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give	nn
One Time Key In	Main		6505437	HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace	SCP
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	nn
Total Spare Part Cost									2,596.19	Surveyor Total				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				
Final Spare Part Cost									2,076.95	Final Sur Total				
												1,281.56	20	
												1,025.25		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	507.00	200	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
Total:			756.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
4	Main	TO WASH AND VACUUM	60.00	0	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			396.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,076.95	1,025.25
Total Labour Cost	507.00	200.00
Total Spray Painting	756.00	200.00
Other	396.00	20.00
Overall Total	3,735.95	1,445.25
Lump Sum Repair Option	☒	☒
Lump Sum Total	3,750.00	1,450.00
Surveyor Approved Amount		1,450.00
No of Repair Days*	4	2

Estimator Assesment(\$)

Surveyor Assesment(\$)

Remarks

L/S REPAIR, PHOTO AFTER PAINT.

Surveyor Name

Hwee jie

Signature



Save

Clear

Survey Date

18/06/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: