

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG19010830/ASD3E2

**Date:** 05/08/2020

### REFERENCE

Insured/Claimant:	LEE PUI LEE	Policy No:	
Date of Loss:	10/06/2019	Nature of Claim:	OD Claim No: 2456745660SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC2223L		
Make & Model:	AUDI Q2 SPORT, 1.4 TFSI COD S-TRONIC (A)	Engine No:	CZE835657
Reg. Date:	14/11/2018 (Man. Year: 2018)	Chassis No:	WAUZZZGA0JA119885
Colour:	White	Odometer:	8527 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,795.20	7,364.44	6,430.76	46.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,952.00	2,902.00	4,050.00	58.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,747.20</b>	<b>10,266.44</b>	<b>10,480.76</b>	<b>50.52</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	19,947.20	9,466.44	10,480.76	52.54
<b>+ GST 7.00/7.00% (S\$)</b>	1,396.30	662.65	733.65	52.54
<b>Nett Amount (S\$)</b>	<b>21,343.50</b>	<b>10,129.09</b>	<b>11,214.41</b>	<b>52.54</b>

### INSPECTION

Date of Assignment:	19/06/2019	
Date Inspected:	18/06/2019	Inspected At:
		Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,705.00 FS	*1,364.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	179.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Deformed	154.00 FS	*122.80 FS
5	1		*END CAP	Damaged	31.00 FS	*24.40 FS
6	1		*SPOILER	Deformed	273.00 FS	*218.00 FS
7	1		*CLOSING ELEMENT	Deformed	142.00 FS	*113.20 FS
8	1		*WHEEL SPOILER - RH	Not Necessary	31.00 FS	*- FS
9	1		*ADAPTER - RH	Not Necessary	38.00 FS	*- FS
10	1		*RADIATOR GRILLE	Not Necessary	1,301.00 FS	*- FS
11	1		*STRIKER PLATE	Not Necessary	114.00 FS	*- FS
12	1		*FOAM FILLER PIECE	Not Necessary	71.00 FS	*- FS
13	1		*FRONT BUMPER CARRIER	Not Necessary	625.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Cracked	91.00 FS	*72.56 FS
15	1		*GUIDE SECTION - RH	Not Necessary	32.00 FS	*- FS
16	1		*FRONT FENDER - RH	Not Necessary	1,047.00 FS	*- FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	36.00 FS	*- FS
18	1		*BRACKET - RH	Not Necessary	14.00 FS	*- FS
19	1		*BRACKET - RH	Not Necessary	43.00 FS	*- FS
20	1		*BRACKET - RH	Not Necessary	14.00 FS	*- FS
21	6		*POP RIVET	Not Necessary	18.00 FS	*- FS
22	1		*BRACE - RH	Not Necessary	29.00 FS	*- FS
23	1		*INSULATION FOR WING	Not Necessary	69.00 FS	*- FS
24	1		*WHEEL HOUSING LINER - UPPER	Not Necessary	33.00 FS	*- FS
25	1		*BRACKET	Not Necessary	21.00 FS	*- FS
26	1		*WHEEL HOUSING LINER - RH	Not Necessary	183.00 FS	*- FS
27	1		*WHEEL HOUSING ATTACHMENT PARTS	Not Necessary	56.00 FS	*- FS
28	1		*CAUTION STICKER	Necessary	13.00 FS	*9.76 FS
29	1		*A/C STICKER	Necessary	7.00 FS	*5.12 FS
30	1		*HEADLIGHT MOUNTING - RH	Not Necessary	107.00 FS	*- FS
31	1		*LED HEADLIGHT - RH	Cut	4,491.00 FS	*3,592.80 FS
32	1		*LIFT CYLINDER - RH	Not Necessary	128.00 FS	*- FS
33	1		*AIR GUIDE FOR RADIATOR	Not Necessary	27.00 FS	*- FS
34	1		*FRONT WHEEL COVER - LH	Necessary	294.00 FS	*234.80 FS
35	1		*FRONT WHEEL COVER - RH	Necessary	294.00 FS	*234.80 FS
36	1		*REAR BUMPER SPOILER	Deformed	259.00 FS	*207.20 FS
37	1		*REAR WHEEL ARCH COVER - LH	Necessary	156.00 FS	*124.40 FS
38	1		*REAR WHEEL ARCH COVER - RH	Necessary	156.00 FS	*124.40 FS
39	1		*FRONT NO. PLATE	Not Necessary	40.00 FS	*- FS
40	1		*SUNDRIES	Necessary	300.00 FS	*57.00 FS
41	1		*REAR BUMPER	Cracked	859.20 FS	*859.20 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **13,795.20**    **7,364.44**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	750.00
3	TO REMOVE AND REINSTALL REAR BUMPER	New	600.00	500.00
4	TO RESPRAY FRONT BUMPER, AND RHS FRONT FENDER	New	2,200.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO RESPRAY REAR BUMPER	New	1,200.00	550.00
<b>Gross Labour Cost (S\$)</b>			<b>6,952.00</b>	<b>2,902.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >