



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD HONDA VEZEL HYBRID-1.5 RS (A)
(SFJ395L)

Date of Loss

24 November 2018

Time of Loss

17.00

Loss Description

SJL2180T (INSD) HIT REAR OF SFJ395L (TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion *

20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SFJ395L

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

29/11/2017



Mileage

124053

Age of Vehicle

0

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2017

Make

TPVD HONDA

HONDA

Model

VEZEL HYBRID-
1.5 RS (A)

VEZEL HYBRID SENSIN

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

WONG KOK KWONG

Date of Birth

19 September 1961

dd/mm/y

Age

57

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No		RU31262608
Engine No		LEB5962625
Engine Capacity		1496
Sum Insured		0
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		
License Type		
License Issue Date		dd/mm/y 
License Expiration Date		dd/mm/y 
Address	640 JURONG WEST STREET 61, #13-06, 640640, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Unknown	
Identification #	S1479603G	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

27/06/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/60R16

Rear Tyre Size

215/60R16

Front left side

MICHELIN5mm

Rear left side

MICHELIN5mm

Front right side

MICHELIN5mm

Rear right side

MICHELIN5mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%		Salvage%	
Discount%	20	Settlement%	100

Paint Labour/Material Ratio

Paint Labour Ratio	20	Paint Material Ratio	80
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMC
		0	1		TAIL GATE	Replaced	0	1100	No		20			880	Reviewing	
		0	2		TAIL GATE HINGES	Serviceable	0	0	No		20			0	Deny	
		0	2		TAIL GATE ABSORBER	Serviceable	0	0	No		20			0	Deny	
		0	1		TAIL GATE LOCK	Replaced	0	195	No		20			156	Reviewing	
		0	1		TAIL GATE LOCK STRIKER	Replaced	0	24.7	No		20			19.76	Reviewing	
		0	1		TAIL GATE LOCK BUZZER	Replaced	0	85	No		20			68	Reviewing	
		0	1		TAIL GATE LOCK OUTER SENSOR	Replaced	0	198.7	No		20			158.96	Reviewing	
		0	1		TAIL GATE WEATHERSTRIP	Replaced	0	165	No		20			132	Reviewing	
		0	1		TAIL GATE INNER HANDLE HOLDER	Serviceable	0	0	No		20			0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMC
		0	1		TAIL GATE INNER TRIMBOARD	Replaced	0	295	No		20			236	Reviewing	
		0	8		TAIL GATE INNER TRIMBOARD CLIPS	Replaced	0	4.5	No		20			28.8	Reviewing	
		0	1		TAIL GATE BADGE - LOGO	Replaced	0	29	No		20			23.2	Reviewing	
		0	1		TAIL GATE "VEZEL" EMBLEM	Replaced	0	65	No		20			52	Reviewing	
		0	1		TAIL GATE "HYBRID" EMBLEM	Replaced	0	65	No		20			52	Reviewing	
		0	1		TAIL GATE GLASS MLDG	Replaced	0	120	No		20			96	Reviewing	
		0	14		TAIL GATE GLASS MLDG CLIPS	Serviceable	0	0	No		20			0	Deny	
		0	1		TAIL GATE GLASS INNER SEAL	Replaced	0	40	No		20			32	Reviewing	
		0	2		TAIL GATE REFLECTORS	Replaced	0	350	No		20			560	Reviewing	
		0	4		TAIL GATE REFLECTOR CLIPS	Serviceable	0	0	No		20			0	Deny	
		0	2		TAIL GATE REFLECTOR SEALANT	Serviceable	0	0	No		20			0	Deny	
		0	1		N/S TAILLAMP	Replaced	0	652	No		20			521.6	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMC
		0	1		N/S TAIL LAMP CLIPS	Serviceable	0	0	No		20			0	Deny	
		0	1		N/S TAIL LAMP SEALANT	Serviceable	0	0	No		20			0	Deny	
		0	1		REAR BUMPER FASCIA	Replaced	0	762	No		20			609.6	Reviewing	
		0	2		REAR SIDE BUMPERS	Replaced	0	235	No		20			376	Reviewing	
		0	10		REAR BUMPER CLIPS	Replaced	0	3.9	No		20			31.2	Reviewing	
		0	2		REAR BUMPER SIDE RETAINER	Replaced	0	38	No		20			60.8	Reviewing	
		0	2		REAR BUMPER SIDE ATTACHMENT	Replaced	0	31	No		20			49.6	Reviewing	
		0	2		REAR BUMPER REFLECTORS	Serviceable	0	0	No		20			0	Deny	
		0	1		REAR END PANEL	Replaced	0	580	No		20			464	Reviewing	
		0	1		REAR END PANEL TOP TRIM	Replaced	0	100	No		20			80	Reviewing	
		0	4		REAR END PANEL TOP TRIM CLIPS	Serviceable	0	0	No		20			0	Deny	
		0	2		REAR END SIDE EXTENSION PANEL	Repair	0	0	No		20			0	Deny	
		0	1		N/S REAR FENDER INNER TRIM BOARD	Replaced	0	395	No		20			316	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMC
		0	8		N/S REAR FENDER INNER TRIM BOARD CLIPS	Replaced	0	5	No		20			32	Reviewing	
		0	1		REAR FLOOR PANEL UNDER GARNISH COVER	Serviceable	0	0	No		20			0	Deny	
		0	1		TOOLS TRAY SPONGE	Replaced	0	215	No		20			172	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMC
		0		TOWING CHARGES	0	60	0	0	Reviewing		
		0		TO REMOVE / REFIT TAIL GATE GLASS TO ASSIST REPAIRS	0	120	0	0	Reviewing		
		0		TO REMOVE / REFIT LUGGAGE TRIMS & GARNISH TO ASSIST REPAIRS	0	80	0	0	Reviewing		
		0		TO MOUNT VEHICLE ON "CAR-O-LINER" BENCH TO ASSIST CHASSIS ALIGNMENT	0	0	0	0	Deny		
		0		LABOUR CHARGES TO REPAIR, PANEL BEAT AND STRAIGHTEN DAMAGED PARTS AND REPLACE THE ABOVE - MENTIONED PARTS	0	700	0	0	Reviewing		
		0		TO REMOVE / TRANSFER TAIL GATE FITTINGS	0	80	0	0	Reviewing		
		0		TO REPLACE REVERSE SENSORS	0	50	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMC
		0		TO CHECK WIRING FUNCTIONS	0	30	0	0	Reviewing		
		0		TO RESET ECU	0	0	0	0	Deny		
		0		TO PUTTY, APPLY PRIMER & SPRAY - PAINT THE AFFECTED AREAS	0	960	0	0	Reviewing		
		0		TO APPLY RUST- PROOFING ON REPAIRED / REPLACED PANELS	0	80	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add Approve Deny Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 6 DAYS	Reviewing	0		
		0	TAIL GATE GLASS SEALANT	Reviewing	40	REPLACED	
		0	TAIL GATE REFLECTOR BLACK STICKER - 2PCS	Deny	0	NOT FITTED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
 	0	TAIL LAMP BLACK STICKER - 2PCS	Deny		0	NOT FITTED	
 	0	REAR NUMBER PLATE	Deny		0	NOT NECESSARY	
 	0	REAR NUMBER PLATE CASING	Deny		0	NOT NECESSARY	
 	0	REAR BUMPER TOP CHROME	Deny		0	NOT NECESSARY	
 	0	REVERSE SENSORS W CONTROL UNIT	Reviewing		200	REPLACED	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00				Adjusted Claim Amount		\$7,607.52
CATEGORY		ESTIMATE		ADJUSTED				
Spare Parts		\$0.00		\$5,207.52				
Labour		\$0.00		\$2,160.00				
Miscellaneous		\$0.00		\$240.00				

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	FINAL LUMP SUM	Reviewing	6100		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00				Adjusted Claim Amount		\$6,100.00
CATEGORY		ESTIMATE		ADJUSTED				
Miscellaneous		\$0.00		\$6,100.00				

Submit for Review