

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Soh Li Ping

Date: 19 Jun 2019

Preliminary Advice

Vehicle No	: SKV83P	Accident Date	: 17/06/2019
Make	: MAZDA 6	Policy No.	: B29083884QMY
Assignment Date	: 19/06/2019	Excess	: S\$1,500.00
Date of Inspection	: 19/06/2019	Est. Duration of Repair	: 5 days
Inspection At	: Trans Eurokars Pte Ltd (HQ) 5 Ubi Close Singapore 408605		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,715.22
Revised Amount	:S\$	8,265.50
Check Items (Estimated)	:S\$	283.70
Total	:S\$	8,549.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	71,000.00
COE / PARF Rebate	:S\$	56,250.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,750.00

Remarks

- (X) The vehicle is economical for repair. According to the Jess (repairer), Owner didn't write down the story of how the accident happened in sketch plan. Just only drawing showed in the sketch plan. Based on our surveyor, the damages of the n/s front portion is consistent with the accident.
- () The above survey was conducted on a 'without prejudice' basis.