


MOTOR IMAGE ENTERPRISES PTE LTD
19, LORONG 8, TOA PAYOH, SINGAPORE 319255
MAIN LINE : (65) 6703 8333
FAX : (65) 6252 5655
SERVICE CENTRE TEL : 6703 8101/02
WEBSITE : www.motorimage.net

Work Order: R001401
 Name 2: ONG LEE SWEE
 Company: APT BLK 183 EDGEFIELD PLAINS
 License: SMK5148M
 Year: 19
 Technician: KUGAN
 Odometer: 3317
 Date: 3.7.19 8:53

Subaru : Impreza (Including WRX/STI, XV) : 2017-18 (GK/GT) : XV
4-Wheel Total Alignment



All diagnosis code

TEL:

FAX:

Employee in charge:

E-mail:

Date and time: 3/7/2019 9:23:28 AM

Vehicle: Impreza / XV

VIN: JF1GT7KL5KG062254

Model: 19MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Tire Pressure Monitor : 0 piece>

<Body Control : 0 piece>

<Airbag : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			00438	1064700	Current		
Past	B1921	Open in Rear P/T RH	00411	3800	ommo		

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

All diagnosis code

TEL:

FAX:

Employee in charge:

E-mail:

Date and time: 3/7/2019 9:26:25 AM

Vehicle: Impreza / XV

VIN: JF1GT7KL5KG062254

Model: 19MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Tire Pressure Monitor : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			00439	15900	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					