	ASS, REC. BY Shreupr: Prom (Person		ASSI of	GNMENT (O	ffice)	Date/	Fime: 5 5	opm@18/6/10
	Estimated Co.	at		Bill to:			30 30 10 30 4 10 10 10 10 10 10 10 10 10 10 10 10 10	
		3/TP RES / OD RES /	EVA/INV	MV/CS			clan ac	OMT
	To Inspect Ve	Manager Co.		HD 303K	Ins	ored:	SHA 06	111
	at Workshop			scerb	(4)	Tel:	62876	0000
	Policy No:		10. 3 4W	k st-63		IM . D	2424 25	11
				Clair	n No: D	1900:	3478 MF	4
	Sum Insured;			Ey	cess;			1
	Make of Veh: (Client's Record	n .				D.O.,	15/06	12019
	CA / REV	REP. / REV 24 HR. 17 19 19 19 19 19 19 19 19 19 19 19 19 19	s (up') _ Person Cor	itnoted: A	menda		D.D. Endomento E_IN / OUT	
	the state of the s		1 100	/		-		
	Date/Time	Action/Instruction	columnità i					
	Date/Time	Action/Instruction SHD 303K-0	The second secon		1063		don:	15/6/2019
	Date/Time	SHD303K-0	CALASMIO	10/0766	1063 1 Hub	-	OBA;	15/6/2019
ts.	Date/Time		CALASIMO - CEALAS	16/0766/ M1901076	6/Hpb=		BOOK	15/6/2019 15/6/19 enail.

ASSIGNMENT

From	Date: 19/6/19	Veh No:	S140 30	3/ Yr Regn. 0	2 16
Estimated Cost:	A HUMBER STANDARD TO THE PROPERTY OF	Type: M.Car	M.Cycle / Bus / Van /	Lorry / Taxi / Prime Mov	ver /
OD TP WS / TP RES / OD RES	/EVA/INV/MV	Truck	l Trailer or		
	SHD 303K	Make:	Renault	Cotitude 00	1895
	runscab	Colour N	. White the		Std / NI / NA
of No.2 AMK		Sp.Reading	37852;		Std / NI / NA
Insured:	-) 03	Eng/No:		-	
Policy No.		C/No:	VI=1AB	215AUC2	8 2364
Claims No.		Gen. Cond: 6	or / Fair / Poor / Bur	rnt	₩ 100 mm
Sum Insured:	Excess:	Steering: Inq	der / Jammed / Leake	d / Burnt or	
(Client's Record)		Brake: Ing	der / Jammed / Leake	d / Burnt or	
Make of Veh:		Modi: Mil	/ S/Rim / STD A/Rim	or	
		Tyre Size:	F: .	215/60R1	
(Policy Condition)			R: -		-
Remark: The veh had commence	d its N/S O/S	BS/DUN/E	XNOVA / GY / FS / LIZ	A / MIC / OHTSU / PIR /	SUMI/
repair at the time of ins	pection.	TOYOTYO	(O or	Gitt	
Bal, or Market Value:	~	Front	7	Rear	,
IDAC Accident Rport:	Consistent?: Yes or No	R/Bal.	5 mm	R/Bal.	mm
GIA / PR Seen:	Consistent?: Yes or No	L/Bal.	3 mm	L/Bal.	mm
Est. Repairs: 2 day	s Res.: Yes or No	D.O.A. 13	16/19	D.O.I. 20	16/19
Lum Sum: 20 %	3 Val.: Yes or No	'Survey held a	at		
CA / REV / REP. / 24 HR	s lwp?			S / N/S / U/C / Roofto	p or
	Vehicle: IN / OUT	0.00	s Rec		
Date: Person Cor	1.010-0149-011	The U/C	/ Chassis frame / Bo	ody Structure affected d	ue to collision
Date / Time Action / Instructi					
C# 28.	To 11mm1 401.82 Red	- 98%	2		
` + '	/		/		
	RECEIVED	1 9 JUL	2019		
	* =				
Emerand					
Date/Time, File Pass lo?	reli. Report	Days Of Rep		/ -	
1) Typis V:F	inal Report	Resurvey N	o. of Trip:	Survey Fee:	
Date/Time, File Return to?	A 4 4 4		10	Transportation:	
2) *	Add Fed	Account.	nsp (\$)3+PSSF	
Francis Comment	24	Contraction of the Contraction o	Aew (\$) Photo	
Enport Formst	1 0/-		1025 CF) Other	250
Lump : um (12) 13 640	1- 1/1	[: //Ais	and (\$		350
				707/4	

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D19003978MFSH

Date: 21 June 2019

Our Ref: CS/FCI19010875/Ksd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 303K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/06/2019 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	29,041.82	2.
Revised Estimate Amount	: <u>S\$</u>	9,000.00	
"Check" Items Amount	: <u>S\$</u>		
Total	: <u>S\$</u>		
Market Value	: <u>S\$</u>		
LTA Reimbursement Value	: <u>S\$</u>		
Nett Value	: <u>SS</u>		

Description of Damage:


The vehicle sustained damages at the o/s rear portion.



Comments/ Present Status:

Damages Consistent. Repair days: 2 days

Yours faithfully, Kenneth Kong Automotive Assessor



MS First Capital Insurance Limited to Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Notor Underwiting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

18-06-2019

Our Ref No. D19003978MFSH

Accident Date

15-06-2019

Claim Type. Third Party

Insured Vehicle

SHA0699J

Third Party Vehicle. SHD303K

Survey Location

NO. 2 ANG MO KIO STREET 63

Contact Person.

AMANDA TAY

Contact No.

62876666/0

Fax No. 62571330

Survey Type

WITHOUT PREJUDICE:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

TRANS-CAB AUTO SERVICES PTE LTD

Attention. NIL

Cc : TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

HENRY KAO

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent:

Friday, 19 July 2019 3:35 PM 'Shirley Hiew (LKK Auto)'

To:

'SUR'

Cc: Subject:

FW: TCS REF: AAD1906-153--Accident involving SHD 303K & SHA 699J on

15/06/2019

Attachments:

ESTIMATE MARKED.pdf

Hi Shirley

Amount confirmed \$640/- (b4 GST).

Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Thursday, 18 July, 2019 3:00 PM

To: 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: RE: TCS REF: AAD1906-153--Accident involving SHD 303K & SHA 699J on 15/06/2019

Dear Wai Yin.

Please confirm final fig \$ 640.00 @ 2 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Friday, 21 June 2019 3:19 PM

To:

'Henry Kao Cai Jie'; 'CWS Motor Claims'

Cc:

assignments; SUR

Subject:

RE: SURVEY ASSESSMENT - D19003978MFSH/1

Attachments:

SHD 303K - Preli Advise .pdf

Dear Henry,

Enclosed preliminary revised of vehicle SHD 303K.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Wednesday, 19 June 2019 12:40 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19003978MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Tuesday, 18 June 2019 5:50 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie

<HenryKao@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19003978MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

This email has been checked for viruses by AVG antivirus software.
www.avg.com

PARF/COE Rebate Enquiry

> Back to OneMotoring

/ehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD303K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002949
Chassis No.:	VF1ABL15AUC282364
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	04 Feb 2016
First Registration Date:	04 Feb 2016
Fransfer Count:	0
Actual ARF Paid:	\$19,998.00
ntended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Feb 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
OE Expiry Date:	03 Feb 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$43,040.00
COE Rebate Amount:	\$24,907.00
Total Rebate Amount:	\$39,905.00
Message	

The information contained herein is correct as at 17 Jun 2019

reaches its statutory lifespan (if applicable), whichever is earlier.

OK

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 303K

29 Juil 2019

Not Asthoras LASop & 6401

Vehicle No.:
Chassis No.:
VF1ABL15AUC282364
Vehicle Make:
RENAULT
Vehicle Model:
LATITUDE
Date of Accident:
Third Party Insurer:
Date of Registration:
FIRST CAPITAL
4/2/2016

	Date of Registration.		4/2/2010	
	PART			LIST
1	DOOR PANEL REAR RH		\$	√ 2,844.66 √
1	ROCKER PANEL INNER GARNISH RH		\$	A 466.51
1	ROCKER PANEL INNER RH		\$	7 1,024.79
1	ROCKER PANEL OUTER RH		\$	7 1,184.99
1	ROCKER PANEL CENTER RH		\$	N 990.25
1	BOOT REFLECTOR LAMP RH		\$	رر 493.35
1	FENDER PANEL REAR RH		\$	N 3,299.13
1	FENDER PANEL INNER TRIM REAR RH		\$	671.45
1	WHEELARCH REAR RH		\$	^ 543.47
1	BUMPER COVER REAR		\$	1,108.46
1	BUMPER LOWER REAR		\$	∫∽ 768.84
1	BUMPER BRACKET CTR REAR		\$	الم 113.47
1	BUMPER BRACKET SIDE RH REAR		\$	ار 135.97
1	BUMPER RETAINER RH REAR		\$	√s 44.99
1	BUMPER REFLECTOR RH		\$	√ _{43.61}
1	BUMPER BEAM REAR		\$	N 777.52
1	BUMPER BEAM BRACKET RH REAR		\$	n 225.95
1	TAILLAMP RH		\$	ر _{552.55}
1	TAILLAMP PANEL RH		\$	n 986.70
		TOTAL	\$	16,276.66
		10%	\$	1,627.67
			\$	14,649.00
		24		
	Special Nett		2	Nn
1	REAR DOOR STICKER '6555-3333'		\$	80.00
1	FENDER INNER TRIM CLIP RH		\$	Na 28.00
1	TAILLAMP CLIP RH		\$	5.00 X
1SET	FENDER WHEELARCH REAR RH CLIP		\$	35.00
2	REAR WINDSCREEN SEALANT		\$	~~ 80.00J

Trans-c	ab Auto Services Pte Ltd		AAD1906-153	
No. 2 Ang	Mo Kio Street 63 Singapore 569111			
Tel No. : 6	287 6666 Fax No.: 6257 1330			
CO./GST F	Reg. No. 201019626G			
SHD 3031	C			
1	WINDSCREEN MOULDING	\$	100.00)
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	1
1	REAR RIGHT TYRE	\$	300.00	
1	REAR RIGHT TYRE RIM	\$	380.00	0
1SET	PARKING AID	\$	700.00	Se
1SET	REAR BUMPER CLIP	\$	66.00	$\succ X$
1SET	BUMPER BRACKET CTR CLIP	\$	33.00	8
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	
1SET	BUMPER RETAINER CLIP RH RR	\$	20.00	
1SET	BUMPER LOWER REAR RIVET	\$	22.00	
1SET	BUMPER LOWER REAR CLIP	\$	66.00	
1	EXHAUST MOUNTING REAR	\$	17.82	
		TOTAL \$	2,042.82	
	тот	TAL PARTS \$	16,691.82	
	LABOUR			
	Panel beating, knocking and straightening th	6		
	3 3	C		
	necessary portion, remove and renewal of pa			near
			4,500.00	200
	necessary portion, remove and renewal of pa	rts, adjust \$	4,500.00	200
	necessary portion, remove and renewal of pa and realign the same	rts, adjust \$	4,500.00 ~~ 380.00	(
	necessary portion, remove and renewal of pa and realign the same Labour charge to mount and dismount vehicle	rts, adjust \$ le on jig \$	~~ 380.00	X
	necessary portion, remove and renewal of pa and realign the same Labour charge to mount and dismount vehicle bench, to facilitate repair.	rts, adjust \$ le on jig \$		X
	necessary portion, remove and renewal of parand realign the same Labour charge to mount and dismount vehicle bench, to facilitate repair. To remove and refit interior fittings, trimings,	rts, adjust \$ le on jig \$ garnish, \$	~~ 380.00 5 380.00	X
	necessary portion, remove and renewal of parand realign the same Labour charge to mount and dismount vehicle bench, to facilitate repair. To remove and refit interior fittings, trimings, fittings and other, to enable repair.	rts, adjust \$ le on jig \$ garnish, \$	~~ 380.00	X
	necessary portion, remove and renewal of parand realign the same Labour charge to mount and dismount vehicle bench, to facilitate repair. To remove and refit interior fittings, trimings, fittings and other, to enable repair. To check steering geometry and computer w	rts, adjust \$ le on jig \$ garnish, \$	~~ 380.00 5 380.00	x x x
	necessary portion, remove and renewal of parand realign the same Labour charge to mount and dismount vehicle bench, to facilitate repair. To remove and refit interior fittings, trimings, fittings and other, to enable repair. To check steering geometry and computer was alignment	rts, adjust \$ le on jig \$ garnish, \$ heel \$	380.00 4 380.00 5 220.00	x x x
	necessary portion, remove and renewal of parand realign the same Labour charge to mount and dismount vehicle bench, to facilitate repair. To remove and refit interior fittings, trimings, fittings and other, to enable repair. To check steering geometry and computer walignment To rust-proofing of the affected areas.	rts, adjust \$ le on jig \$ garnish, \$ heel \$	380.00 4 380.00 5 220.00	x x x x
	necessary portion, remove and renewal of parand realign the same Labour charge to mount and dismount vehicle bench, to facilitate repair. To remove and refit interior fittings, trimings, fittings and other, to enable repair. To check steering geometry and computer was alignment To rust-proofing of the affected areas. To transfer of rear windscreen fittings and computer was alignment.	rts, adjust \$ le on jig \$ garnish, \$ heel \$ snduct \$	380.00380.00220.00170.00	x x x x

Trans-cab Auto Services Pte Ltd

AAD1906-153

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666

Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 303K

LUMP SUM (REPAIR DAY)	2 day	
Over All Total	29,041.82	2
TOTAL	12,350.00	
and enhancement	\$ 5 380.00	X
To apply paint protection system (PPS) maintain		
To reinstall rear bumper parking sensor.	\$ ζ 170.00	Y
To transfer of Rear door fittings, attachment and perform water seepage test.	\$ 4 380.00	<
To Check Electrical Lighting Concerned.	\$ ५ 170.00	X
To transfer of tire, rim and on wheel balancing.	\$ امر 170.00	X
Putty and spray painting of the affected portion.	\$ 4,500.00	44
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$ ~~ 380.00	χ

the Repairer of the following:

• To resurvey before/after spray painting

- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation.
- . No illegal modification(s) is allowed



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	The same of the sa	
AS F	FIRST CAPITAL IN	ISURANCE LTD	Ref : CS/FCI1901087	75/Ksd3n2
36 R #16-	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 23-07-2019 Code: FCI2	
,		Policy Particula	rs :- THIRD PARTY CLAI	M
	Insured Veh.	SHA 699J	Veh. Inspected	SHD 303K
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19003978MFSH	Excess (\$)	0.00
	Assign From	HENRY KAO	Assign Date	18/06/2019
2.		Vehicle Pa	rticulars & Condition	
	Make & Model	RENAULT LATITUDE (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	VF1ABL15AUC282364	Colour	METALLIC WHITE / RED
	Odometer	378522	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cond	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	GITI	3 mm
	L/H Front Tyre	215/60 R16	GITI	3 mm
	R/H Rear Tyre	215/60 R16	GITI	6 mm
	L/H Rear Tyre	215/60 R16	GITI	6 mm
4.			ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	O/S REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gene	eral Information	
	Accident Date	15/06/2019	Inspection Date	20/06/2019
	Survey held at	TRANS-CAB AUTO SERVICE	ES PTE LTD	
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.	To the service of		Remarks	
	B)THE INSPECTION	NSISTENT TO ACCIDENT REP ON WAS CONDUCTED ON A"\ CE TO YOUR INSTRUCTIONS	MITHOUT PREJUDICE" BAS	SIS. SED REPAIRS.
5b.	100	Estima	ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Day	/s



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 303K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	8
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	1,184.99) h
1	ROCKER PANEL CENTER RH	TO REPAIR SEE LABOUR	990.25	0.
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	100
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	76
1	WHEELARCH REAR RH	SERVICEABLE	543.47	
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	8
1	BUMPER LOWER REAR	SERVICEABLE	768.84	03
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	55
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	7.5
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	05
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	TAILLAMP RH	SERVICEABLE	552.55	
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	8:
	LESS 10% DISCOUNT		-1,627.67	
			14,648.99	
	SPECIAL NETT ITEMS			
1	REAR DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	N N

Report Ref No. CS/FCI19010875/Ksd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	×
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	72
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	100
1	WINDSCREEN MOULDING (SN)	SERVICEABLE	100.00	352
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	SERVICEABLE	100.00	87
1	REAR RIGHT TYRE (SN)	SERVICEABLE	300.00	
1	REAR RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	SERVICEABLE	66.00	
1	SET BUMPER BRACKET CTR CLIP (SN)	SERVICEABLE	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	SERVICEABLE	10.00	
1	SET BUMPER RETAINER CLIP RH RR (SN)	SERVICEABLE	20.00	
1	SET BUMPER LOWER REAR RIVET (SN)	SERVICEABLE	22.00	
1	SET BUMPER LOWER REAR CLIP (SN)	SERVICEABLE	66.00	
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	8-
	W 1820		2,042.82	
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR PANEL REAR RH, ROCKER PANEL INNER RH, ROCKER PANEL OUTER RH, ROCKER PANEL CENTER RH, FENDER PANEL REAR RH, BUMPER COVER REAR, BUMPER BEAM BRACKET RH REAR AND TAILLAMP PANEL RH.		4,500.00	200.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	8-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	82

Report Ref No. CS/FCI19010875/Ksd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

640.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	8-
	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	8.
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	440.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	25
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	2-
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	69
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	
			12,350.00	640.00
	GRAND TOTAL		29,041.81	640.00

Report Ref No. CS/FCI19010875/Ksd3n2

RECOMMENDED COST OF REPAIRS

KONG SENG CHEONG

Licensed Appraiser

KSC