AXVI - [EK Leibren]



Repair Estimates

ESTEEM PERFORMANCE PTE LTD

rtopan Estimatos	OLG	11001		
				Not North
arts (a) Cost / List Price Items	\$	1,925.80		
Plus/Less25%_	\$	481.45		Resury BEpa
Total of Cost / List	\$	1,444.35		
(b) Nett Price Items				LKK Auto Consultants hence notify
Less				the Repairer of the following: • To resurvey before/after spray painting
				10 display damaged part(s) during recurrent
Total of Nett Item				Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed.
(c) Special Nett Items	\$	200.00		Supplementary tappies must be seen as a s
otal Parts Cost	\$	1,644.35	,	is subject to final approval from Insurance Compan Acknowledged by Repairer
abour	\$	1,790.00		Signature:
otal	\$	3,434.35		Sate.
Name of Surveyor			/	Kennens
Company	: _			2/ek
Survey conducted on	: _		24/61	Pat
Remarks By Surveyor				
(a) The repair of this vehicle is	authorized / is r	not authorized ur	ntil further not	ice.
(b) Recommended Days of Rep	pair :	0	2	_day(s)
(c) Resurvey	: Re	equired / Not Red	µi red	
(d) Excess	:\$		- 0	
(e) Signature of surveyor			Le	Date: 24/6/19

SLQ 4460 Y



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No.	:
Make & Model	:
Chassis No	

SLQ 4460 Y

TOYOTA PRIUS JTDKB3FU603561901 Submit By

Year Manufacture
Engine No.

JENNY

2017

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	Shon	1	\$200.00	S.N	
2	Rear bumper	Bu	1	\$497.50		_
3	Rear bumper clip	Na	10	\$40.00		_
4	Rear bumper side retainer LH	54	1	\$112.70		×
5	Rear bumper side retainer RH	54	1	\$112.70		X
6	Rear bumper reinforcement		1	\$398.90		7
7	Rear bumper lower garnish centre	Dulpy	1	\$582.60		
8	Rear bumper lower garnish LH	Sin	1	\$149.70		X
9	Rear bumper tow cover	Fe	1	\$31.70		X
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

	O	и	

Vehicle No.	: SLQ 4460 Y		Submit By	:	Carmen Lim	
Make & Model	: _	TOYOTA PRIUS	Year of Manufacture	:	2017	
S/No		Labour Description		Esima	ted Adjusted	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL)	\$600.00	2001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		90 4
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL)	\$600.00	2701
3	To check Wiring	\$50.00	15%
4	To remove & refit reverse sensor	\$120.00	501
5	To tuff coat.	\$150.00	X
6	To remove & refit spare tyre, spare tyre board, carpet trim	\$150.00	X
	to assist work load.		
7	To conduct water leakage tests to ensure proper air and sealing	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.