



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7347L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR (LH)	TO REPAIR SEE LABOUR	2,201.10	-
1	FRONT DOOR (LH)	BUCKLED	2,256.40	2,256.40
1	FRONT DOOR GEAR/REGULATOR (LH)	SERVICEABLE	250.60	-
1	FRONT DOOR MIRROR ASSY (LH)	BROKEN	670.00	670.00
1	FRONT DOOR POWER MOTOR,LH	SERVICEABLE	172.70	-
1	ROCKER PANEL OUTER GARNISH (LH)	CRACKED	341.40	341.40
1	REAR WHEEL HUP-CAP (LH)	GRAZED	107.10	107.10
1	FRONT WHEEL HUB CAP,LH	GRAZED	107.10	107.10
1	FRONT LH FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-1,221.28	-696.40
			4,885.12	2,785.60
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR TYRE (LH)(SN)	SERVICEABLE	216.00	-
1	FRONT FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
			971.00	705.00
<u>LABOUR</u>				
	PANEL BEATING.REPAIR REAR LH FENDER.INCLUSIVE OF THE REPAIR OF REAR DOOR (LH),FRONT LH FENDER AND REAR BUMPER.		850.00	600.00

Report Ref No. CS/EG19010904/K1a3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.		1,500.00	1,000.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	50.00
	TOWING CHARGE.		60.00	-
	TRANSFER OF DOOR.		160.00	50.00
	FOUR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			2,840.00	1,700.00
	GRAND TOTAL		8,696.12	5,190.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,050.00

Report Ref No. CS/EGI19010904/K1a3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.