

ASS. REC. BY:

REF: C3/FCT19010911/KS d3n2 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): CWS Joanne Yong of FEI Date/Time: 9.25am 20/6/19

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFV 6655J Insured: SHA 5407C

at Workshop m/s Hui Yong Motor Tel: 6451 5752

of 31K176 Sin Ming Drive # 04-02

Policy No: Claim No: D19004W7MFH

Sum Insured: Excess:

Make of Veh: D.O.A. 18/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS lwp)

H.O.D. Endorsement:

Date/Time: 10.05am 20/6/19

Person Contacted:

Bel

Vehicle IN: ☒ TP

Date/Time	Action/Instruction	
	SFV 6655J - CI/DAI/8006786/Zc	DOA: 6/4/2018
	SHA 5407C - C3/FCT/18000178/Urbn2	DOA: 28/12/17
27/06/19 @ 17:13 pm	revised PA to Joanne Yong v.a email.	

ASS. REC. BY:

REF: PC2 /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 87k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SRV 8655JYr Regn: 04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Shuttlec.c. 1496Colour: n. Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 51377

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP7

1208725

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/6/19D.O.A. 25/6/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / File pass to

317 L1Pm 83850d Confirmed

(B 6, 281-92 Red - 61%)

RECEIVED 5 JUL 2019

Date/Time, File Pass to?

05/07/19

1)

Tyrist

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair: 5Resurvey No. of Trlp: 1Survey Fee: 170Transportation: 50S + RS. \$ 50Fees: 19

Others: _____

TOTAL

289

Report Format :

Lump Sum / I.B.I: (\$

3,950/- 415

Add Fee: ☐

: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004007MFSH

Date: 27 June 2019

Our Ref: CS/FCI19010911/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SFV 6655J.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/06/2019 at the premises of M/s Hui Yang Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 10,231.92
Revised Estimate Amount	: S\$ 6,445.52
"Check" Items Amount	: S\$ 587.20
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-06-2019	Our Ref No. D19004007MFSH
Accident Date	18-06-2019	Claim Type. Third Party
Insured Vehicle	SHA5407C	Third Party Vehicle. SFV6655J
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 27 June 2019 5:13 PM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19004007MFSH/1
Attachments: SFV 6655J - Preli Advise .pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SFV 6655J.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 20 June 2019 10:07 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004007MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 20 June 2019 9:24 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong

<Joanneyong@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19004007MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Kp
辉 陽 汽 車 有 限 公 司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

Not Notarized

13/06/2019

Owner: MKM CAR LEASING PTE LTD

11 Sep @ 3200l 4-10-19
Recovery After Repair

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLV172D

1pc	rear tailgate	Rs	\$ 1,218.45	✓
1pc	rear tailgate outer garnish	Rs	\$ 371.25	X
1pc	rear tailgate "TOYOTA" logo	Rs	\$ 61.10	X
1pc	rear tailgate "PRIUS" emblem	Rs	\$ 63.90	✓
1pc	rear tailgate "HYBRID" emblem	Rs	\$ 61.10	✓
1set	rear tailgate windscreen glass moulding	Rs	\$ 182.28	✓
1pc	rear tailgate inner lock	Rs	\$ 374.45	X
1pc	rear tailgate inner rubber	Rs	\$ 381.90	X
1pc	rear tailgate inner garnish	Rs	\$ 781.90	X
1pc	rear LH taillamp	Rs	\$ 581.90	✓
2pcs	rear taillamp lower bracket @\$132.25	N/A CM	\$ 264.50	✓
1pc	rear bumper	Rs	\$ 981.90	✓
2pcs	rear bumper side retainer @\$132.45	N/A O/R	\$ 264.90	✓
2pcs	rear bumper side reflector @\$181.50	Rs	\$ 363.00	X
1pc	rear end panel	Rs	\$ 781.10	X
1pc	rear end panel outer sensor	Rs	\$ 260.00	X
1pc	rear end panel inner garnish	Rs	\$ 374.85	X
1pc	rear float panel	Rs	\$ 981.50	X
1pc	rear float panel garnish	Rs	\$ 585.20	✓
1pc	rear LH fender inner garnish	Rs	\$ 758.85	X
			\$ 9,694.03	
	less 25%		\$ 2,423.51	
			\$ 7,270.52	
1set	rear parking sensor	Shen s.nett	\$ 280.00	2005m
1set	rear number plate & casing	Shen s.nett	\$ 50.00	X
	remove & refix rear windscreen glass		\$ 120.00	✓
	sealant		\$ 80.00	405m
	tuffkote		\$ 120.00	30l
	wiring		\$ 80.00	20l
	spray painting		\$ 1,000.00	600l
	labour charges		\$ 1,000.00	500l
	Total		\$ 10,000.52	

LKK Auto Consultants hereby notify the repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Suppliers may demand must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



辉陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

18/06/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE -SFV6655J

1pc	rear tailgate	By \$	1,193.70	✓
1pc	rear tailgate "H" logo	Mr \$	58.00	✓
1pc	rear tailgate "SHUTTLE" emblem	Mr \$	55.00	✓
1pc	rear tailgate chrome	Mr \$	383.10	X
1pc	rear tailgate inner lock	Mr \$	289.40	✓
1pc	rear tailgate inner rubber	Dis 181 \$	188.50	✓
1pc	rear tailgate inner garnish	Mr \$	358.50	X
2pcs	rear taillamp lower bracket @\$89.50	Mr \$	179.00	X
1pc	rear bumper	Mr \$	1,150.60	✓
2pcs	rear bumper side retainer @\$38.50	Mr \$	77.00	X
2pcs	rear bumper refector @\$65.00	Mr \$	130.00	X
2pcs	rear bumper refector garnish @\$85.00	Mr \$	170.00	X
1pc	rear end panel	Mr \$	601.50	✓
1pc	rear end panel outer sensor	Mr \$	190.50	X
1pc	rear end panel inner sensor	Mr \$	185.00	X
1pc	rear end panel inner garnish	Mr \$	295.20	✓
1pc	rear end panel inner garnish cover	Mr \$	158.50	✓
2pcs	rear end panel side panel @\$385.50	Mr \$	771.00	X
2pcs	rear end panel side ganish @\$158.50	Mr \$	317.00	X
1pc	rear floor panel garnish box	Mr \$	495.80	X
2pcs	rear fender inner garnish @\$658.80	Mr \$	1,317.60	✓
			\$ 8,564.90	
less 20%			\$ 1,712.98	
			\$ 6,851.92	

1set	rear parking sensor	Sho s.nett \$	280.00	200sn
1set	rear windscreen glass moulding	Mr s.nett \$	120.00	✓
1set	rear number plate & casing	Mr s.nett \$	50.00	45sn

remove & refit rear windscreen glass	\$	150.00	120l
sealant	\$	80.00	40sn
wiring	\$	120.00	20l
tuffkote	\$	180.00	60l
spray painting	\$	1,200.00	700l
labour charges	\$	1,200.00	600l
Total	\$	10,231.92	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

MS First Capital
25/06/19
after 11am
LKK

Not Notarized
11pm 83950h
5days
Pricing After Pricing



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19010911/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 5407C	Veh. Inspected	SFV 6655J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004007MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	20/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71208725	Colour	METALLIC SILVER	
Odometer	91377	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/06/2019	Inspection Date	25/06/2019	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFV 6655J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BENT	1,193.70	1,193.70
1	REAR TAILGATE "H" LOGO	NECESSARY	58.00	58.00
1	REAR TAILGATE "SHUTTLE" EMBLEM	NECESSARY	55.00	55.00
1	REAR TAILGATE CHROME	SERVICEABLE	383.10	-
1	REAR TAILGATE INNER LOCK	DENTED	289.40	289.40
1	REAR TAILGATE INNER RUBBER	DISTORTED / DENTED	188.50	188.50
1	REAR TAILGATE INNER GARNISH	SERVICEABLE	358.50	-
2	REAR TAILLAMP LOWER BRACKET @\$89.50	SERVICEABLE	179.00	-
1	REAR BUMPER	BUCKLED	1,150.60	1,150.60
2	REAR BUMPER SIDE RETAINER @\$38.50	SERVICEABLE	77.00	-
2	REAR BUMPER REFLECTOR @\$65.00	SERVICEABLE	130.00	-
2	REAR BUMPER REFLECTOR GARNISH @\$85.00	SERVICEABLE	170.00	-
1	REAR END PANEL	BENT	601.50	601.50
1	REAR END PANEL OUTER SENSOR	SERVICEABLE	190.50	-
1	REAR END PANEL INNER SENSOR	SERVICEABLE	185.00	-
1	REAR END PANEL INNER GARNISH	MTG DISTORTED	295.20	295.20
1	REAR END PANEL INNER GARNISH COVER	SERVICEABLE	158.50	-
2	REAR END PANEL SIDE PANEL @\$385.50	TO REPAIR SEE LABOUR	771.00	-
2	REAR END PANEL SIDE GARNISH @\$158.50	SERVICEABLE	317.00	-
1	REAR FLOOR PANEL GARNISH BOX	TO REPAIR SEE LABOUR	495.80	-
2	REAR FENDER INNER GARNISH @\$658.80	SERVICEABLE	1,317.60	-
	LESS 20% DISCOUNT		-1,712.98	-766.38
			6,851.92	3,065.52
SPECIAL NETT ITEMS				
1	SET REAR PARKING SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR WINDSCREEN GLASS MOULDING (SN)	NECESSARY	120.00	120.00
1	SET REAR NUMBER PLATE & CASING (SN)	DENTED	50.00	45.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SEALANT (SN)	NECESSARY	80.00	40.00
			530.00	405.00
	LABOUR			
	REMOVE & REFIT REAR WINDSCREEN GLASS.		150.00	120.00
	WIRING.		120.00	20.00
	TUFFKOTE.		180.00	60.00
	SPRAY PAINTING.		1,200.00	700.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR END PANEL SIDE PANEL AND REAR FLOOR PANEL GARNISH BOX.		1,200.00	600.00
			2,850.00	1,500.00
GRAND TOTAL			10,231.92	4,970.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,950.00

Report Ref No. CS/FCI19010911/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.