

2/00/2009

ASS. REC. BY:

REF:

es/FCI19010916/Klqd3n2 Special Instruction:

Survey: Rdsut

ASSIGNMENT (Office)

CWS

From (Person): Serene Ler

of

FCIDate/Time: 19/6/19 @ 4:28pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

YP 3156J

Insured:

SHD 3269G

at Workshop m/s

ASM Automotive

Tel:

62650026

of

No. 13 pioneer sector 1

Policy No:

Claim No:

D19003996 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

10:30am @ 20/6/19

Person Contacted:

JacelynVehicle IN/OUT

Date/Time	Action/Instruction
	<u>YP 3156J-CC4/AXA16023230/Aha3s2 DUA: 1/12/16</u>
	<u>SHD 3269G-CC3/CT117022624/K/hb3y2 DUA: 26/11/2017</u>
<u>21/6/19 @ 10:50am</u>	<u>visited to Serene Ler by email.</u>
<u>23/7/19 @ 4:50am</u>	<u>Passes finalised us \$4400, 4 days.</u>
	<u>(Red \$ 8095, 65%.)</u>

REF:

9400m

ASSIGNMENT

From: Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **YP 3156J**
at Workshop m/s: **ASM AUTOMOTIVE**
of **13, Pioneer Sector 1**
Insured: **FCI**

Policy No:


Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **4** days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

YP 3156JYr Regn: **2016 / Jun**Type: M.Car / M.Cycle / Bus / Van / Car / Taxi / Prime Mover /

Truck / Trailer or

Make:

WOTRUCKSC.C. **7013**

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading:

111490

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JNCL0D0A6G4001549Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Ni / S/Rim / STD A/Rim or

Tyre Size:

F: **235/75R17.5**R: **D/D**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

7

mm

R/Bal.

7/7

mm

L/Bal.

7

mm

L/Bal.

7/7

mm

D.O.A.

11/06/19

D.O.I.

20/06/19

Survey held at

ASM AUTOMOTIVEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 JUL 2019

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.A. (\$

TP**4400**Days Of Repair: **4**

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

2x15 = 30**170 + 30****50****50****87****387**



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003996MFSH

Date: 21 June 2019

Our Ref: CS/FCI19010916/R1qd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. YP 3156J .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/06/2019 at the premises of M/s ASM AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,805.00</u> .
Revised Estimate Amount	: S\$ <u>1,855.00</u> .
"Check" Items Amount	: S\$ <u>5,500.00</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-06-2019	Our Ref No. D19003996MFSH
Accident Date	17-06-2019	Claim Type. Third Party
Insured Vehicle	SHD3269G	Third Party Vehicle. YP3156J
Survey Location	NO 13 PIONEER SECTOR 1	
Contact Person.	JACLYN LAI	
Contact No.	62650026/ 92368218	Fax No. 62656068
Survey Type	DIRECT SETTLEMENT: EST. COR - \$8805.00	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ASM AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: ASM Jaclyn <jaclynlai@asmauto.com.sg>
Sent: Tuesday, 23 July 2019 9:50 AM
To: Rasul (LKKAuto)
Cc: ASM Yandy
Subject: RE: TP claim: MS FCI --- YP3156 J (DOA: 17.06.19)

Dear Rasual,

COR confirmed.

Thank you

Best Regards,

Jaclyn Lai


Assistant Manager
Claims & Operation

ASM Automotive Services Pte Ltd

No. 13, Pioneer Sector 1, Singapore 628424.

Hp: 9236 8218 | DID: 6265 0026 | Fax: 6265 6068

Web: www.asmauto.com.sg



From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Tuesday, 23 July 2019 8:47 AM
To: ASM Jaclyn
Cc: ASM Yandy
Subject: RE: TP claim: MS FCI --- YP3156 J (DOA: 17.06.19)

Hi Jacklyn,

Finalised amount round up is \$ 4,400 / 4 days lump sum
Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 21 June 2019 10:50 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003996MFSH/1
Attachments: CSFCI19010916R1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of YP 3156J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 20 June 2019 12:21 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003996MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 19 June 2019 4:28 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003996MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : MS First Capital Insurance Ltd
ATTN : Motor Claim Department
TEL. NO. : 6507-3848
EMAIL : motor_claims@first-insurance.com.sg

CC : Cargotec Pte Ltd
ATTN : Ms. Susie / Christine

DATE : 19.06.2019

VEHICLE NO. : YP 3156 J
MODEL NO. : UD TRUCKS MKB8ELN5AA
CHASSIS NO. : JNCL0D0A6GU001549
ENGINE NO. : GH7209587
LTA REG DATE : 30.06.2016

CLAIM TYPE : Third Party - SHD 3269 G
D.O.A : 17.06.2019
CLAIM REF NO. : asm/AC19046/JL

Quotation for Accident Repair

S/N	SPARE PARTS (SPECIAL NETT)	QUANTITY	UNIT PRICE	AMOUNT
1	2000kg tailgate system without platform ? Xan	1	\$ 5,500.00	\$ 5,500.00
2	Rear cross member bt	1	\$ 450.00	\$ 450.00
3	Rear license plate bt	1	\$ 15.00	\$ 15.00
4	Rear license plate lamp cra	1	\$ 30.00	\$ 30.00
5	Rear license plate bracket bt	1	\$ 20.00	\$ 20.00
6	Reverse lamp cra	2	\$ 35.00	\$ 70.00
7	Reflective stickers (red & white) na	2	\$ 10.00	\$ 20.00

SUB-TOTAL : \$ 6,105.00


LABOUR CHARGES

- 1 To dismantle tailgate system and platform, replace tailgate system, refix platform and reinstallation. Perform load test with the new tailgate system. Remove and replace other damaged parts. (\$350 x 7 days) \$ ~~2,450.00~~ 1050
- 2 Touch-up paint \$ ~~250.00~~ 200

TOTAL LABOUR : \$ 2,700.00

GRAND TOTAL : \$ 8,805.00

Handwritten notes:
Resue
21/6/19
Hp 90010068
4 days
4/3
26/06/19 @ 1645
Resy after repair
12435



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : MS First Capital Insurance Ltd
ATTN : Motor Claim Department
TEL. NO. : 6507-3848
EMAIL : motor_claims@first-insurance.com.sg

CC : Cargotec Pte Ltd
ATTN : Ms. Susie / Christine

DATE : 19.06.2019

VEHICLE NO. : YP 3156 J
MODEL NO. : UD TRUCKS MKB8ELN5AA
CHASSIS NO. : JNCL0D0A6GU001549
ENGINE NO. : GH7209587
LTA REG DATE : 30.06.2016

CLAIM TYPE : Third Party - SHD 3269 G
D.O.A : 17.06.2019
CLAIM REF NO. : asm/AC19046/JL

Quotation for Accident Repair

S/N	SPARE PARTS (SPECIAL NETT)	QUANTITY	UNIT PRICE	AMOUNT
1	2000kg tailgate system without platform ?	1	\$ 5,500.00	\$ 5,500.00 X
2	Rear cross member <i>bt</i>	1	\$ 450.00	\$ 450.00
3	Rear license plate <i>bt</i>	1	\$ 15.00	\$ 15.00
4	Rear license plate lamp <i>cr</i>	1	\$ 30.00	\$ 30.00
5	Rear license plate bracket <i>bt</i>	1	\$ 20.00	\$ 20.00
6	Reverse lamp <i>cr</i>	2	\$ 35.00	\$ 70.00
7	Reflective stickers (red & white) <i>cr</i>	2	\$ 10.00	\$ 20.00

SUB-TOTAL :

\$ 6,105.00 *605*

LABOUR CHARGES

1 To dismantle tailgate system and platform, replace tailgate system, refix platform and reinstallation. Perform load test with the new tailgate system. Remove and replace other damaged parts. (\$350 x 7 days)

\$ ~~2,450.00~~
1050

2 Touch-up paint

\$ ~~250.00~~ *200*

TOTAL LABOUR :

\$ 2,700.00 *1250*

GRAND TOTAL :

\$ 8,805.00 *1855*

Rasme

Hp 90010068


4 days

48

20/06/19 @ 1645

Resy after repair

2/7 - pend finalization



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

DATE : 27.06.19

TO : MS First Capital Insurance Ltd
ATTN : Motor Claim Department
TEL. NO. : 6507-3848
EMAIL : motor_claims@first-insurance.com.sg

VEHICLE NO. : YP 3156 J
MODEL NO. : UD TRUCKS MKB8ELN5AA
CHASSIS NO. : JNCL0D0A6GU001549
ENGINE NO. : GH7209587
LTA REG DATE : 30.06.2016

CC : Cargotec Pte Ltd
ATTN : Ms. Susie / Christine

CLAIM TYPE : Third Party - SHD 3269 G
D.O.A : 17.06.2019
CLAIM REF NO. : asm/AC19046/JL

Quotation for Accident Repair - SUPPLEMENTARY

S/N	SPARE PARTS (SPECIAL NETT)	QUANTITY	UNIT PRICE	AMOUNT
1	Tilt cylinder complete set <i>1 cak</i>	2	\$ 1,500.00	\$ 3,000.00
2	Rear underun bumper with 2pcs bracket <i>bf</i>	1	\$ 650.00	\$ 650.00
SUB-TOTAL :				\$ 3,650.00
LABOUR CHARGES				
1	Refer first quotation			\$ -
TOTAL LABOUR :				\$ -
GRAND TOTAL :				<u>\$ 3,650.00</u>

Resurvey on 27/6/19 @ 1410hrs

1855
3650
5505
- 2090
\$ 4404
4400



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010916/R1qd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3269G	Veh. Inspected	YP 3156J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003996MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	19/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	UD TRUCKS	c.c	7013	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JNCL0D0A6GU001549	Colour	WHITE	
Odometer	111490	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/75 R17.5	HANKOOK	7 mm	
L/H Front Tyre	235/75 R17.5	HANKOOK	7 mm	
R/H Rear Tyre	235/75 R17.5 (D)	HANKOOK	7/7 mm	
L/H Rear Tyre	235/75 R17.5 (D)	HANKOOK	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/06/2019	Inspection Date	20/06/2019	
Survey held at	ASM AUTOMOTIVE SERVICES PTE LTD 13 PIONEER SECTOR 1 SINGAPORE 628424			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 3156J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	2000KG TAILGATE SYSTEM WITHOUT PLATFORM (SN)	NOT NECESSARY	5,500.00	-
1	REAR CROSS MEMBER (SN)	BENT	450.00	450.00
1	REAR LICENSE PLATE (SN)	BENT	15.00	15.00
1	REAR LICENSE PLATE LAMP (SN)	CRACKED	30.00	30.00
1	REAR LICENSE PLATE BRACKET (SN)	BENT	20.00	20.00
2	REVERSE LAMP @\$35.00 (SN)	CRACKED	70.00	70.00
2	REFLECTIVE STICKERS (RED & WHITE) @\$10.00 (SN)	NECESSARY	20.00	20.00
2	TILT CYLINDER COMPLETE SET @\$1500.00 (ADDITIONAL)(SN)	LEAK	3,000.00	3,000.00
1	REAR UNDERUN BUMPER WITH 2PCS BRACKET (ADDITIONAL)(SN)	BENT	650.00	650.00
			9,755.00	4,255.00
LABOUR				
TO DISMANTLE TAILGATE SYSTEM AND PLATFORM, REPLACE TAILGATE SYSTEM, REFIX PLATFORM AND REINSTALLATION. PERFORM LOAD TEST WITH THE NEW TAILGATE SYSTEM. REMOVE AND REPLACE OTHER DAMAGED PARTS. TOUCH-UP PAINT.			2,450.00	1,050.00
			250.00	200.00
			2,700.00	1,250.00
GRAND TOTAL			12,455.00	5,505.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,400.00

Report Ref No. CS/FCI19010916/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.