

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8456E

DATE 18/6/2019 17:09

MAKE :

MODEL : HYUNDAI i40


Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>hbl</i>			\$ 2,174.90
	Boot Lid Lock Upper <i>X su</i>			\$ 102.60
	Boot Lid Lock Lower <i>X su</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>- su</i>			\$ 28.70
	Boot Lid CRDI Plate <i>- su</i>			\$ 27.90
	Bootlid Moulding <i>- ct</i>			\$ 85.00
	Bootlid i40 Emblem <i>- su</i>			\$ 27.90
	Bootlid Lower Garnish <i>X su</i>			\$ 227.90
	Rear Bumper <i>hbl</i>			\$ 553.00
	Rear Bumper Reinforcement <i>X su</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X su</i>		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>- su</i>			\$ 22.00
	Rear Bumper Bracket <i>X su</i>		\$ 35.60	\$ 71.20
	Rear Bumper Sponge <i>X su</i>			\$ 103.50
	Rear Bumper Under Cover <i>- ct</i>			\$ 228.00
	Rear Panel <i>X su</i>			\$ 526.70
	Rear Panel Garnish <i>X su</i>			\$ 57.70
	Rear Panel Lower Panel <i>X su</i>			\$ 89.40
	SUB TOTAL			\$ 4,947.10
	LESS 20%			\$ 989.42
	DISCOUNTED TOTAL			\$ 3,957.68
	Boot Lid Comfort Logo & Tel No. Sticker <i>me</i>			\$ 30.00 Nett
	Boot Lid Advertisement Logo <i>- su</i>			\$ 100.00 Nett
	Rear Bumper Reverse Sensor <i>- shld</i>			\$ 135.70 Nett
	Rear Bumper Rubber Mat <i>- su</i>			\$ 50.00 Nett
	Rear Bumper Advertisement Logo <i>- su</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) <i>me</i>			\$ 200.00 Nett
	Labour Charge			\$ 565.70
	Panel Beating <i>Kali 11/19</i>			\$ 800.00 <i>6.00</i>
	Spray Painting Charge <i>19/6/19 11:15 L</i>			\$ 900.00 <i>20</i>
	Wiring Charge <i>3 R,</i>			\$ 50.00 <i>20</i>
	Tuff Kote <i>4s</i>			\$ 80.00 <i>30</i>
	Remove/Refix Reverse Sensor <i>After Repair p hbl</i>			\$ 60.00 <i>-</i>
	TOWING FEE			
	TOTAL LABOUR			\$ 1,880.00
	ESTIMATE TOTAL			\$ 6,403.38
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: 17.6.19 Time Received: 1800		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	4. Type of Towing: ☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up
2. ☐ New ☐ SPARK Kakis Name of Customer : Mr Seah Contact No. : 81828032 Vehicle No. : SHE 8456 E Make / Model / Colour : 140 Email :		5. Nature of Service: ☐ Jumpstart ☐ Recovery ☐ Change Tyre / Battery	6. Parts Replaced/Remarks:

7. Location: 85 Telok Kurau	8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Senoko ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others:	

10. Odometer Reading : Fuel Level : F 1/4 1/2 3/4 E	11. Radio / CD Player ☐ OK ☐ Faulty ☐ Not tested	 # : Cracked X : Dented / : Scratched O : Missing Signature of Customer
--	--	--

Job Attended 12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☐ GAO ☒ TZ ☐ YISHUN ☐ OTHERS TOWING Name of Driver : LIM Vehicle No. : GR55662 Time Dispatch : Time of Arrival : Time Completed :	
---	--

Cash Invoice Details (if applicable) 13. Cash Invoice No. :	
---	--

Customer Acknowledgement a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™. 17.6.19 1800 Date Time Signature of Customer	
--	--

14. WORKSHOP Name of Attending Staff/Guard Date & Time of Arrival Signature of Attending Staff/Guard	
--	--