

AIG / LKK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLQ 2132 H

Parts	(a) Cost / List Price Items	\$	<u>3,492.95</u>
	Plus/Less 25%	\$	<u>873.24</u>
	Total of Cost / List	\$	<u><u>2,619.71</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items		_____
Total Parts Cost		\$	<u><u>2,619.71</u></u>
Labour		\$	<u><u>2,120.00</u></u>
Total		\$	<u><u>4,739.71</u></u>

*Not Authorized
Resurvey By paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be returned and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
 Company : LKK
 Survey conducted on : 26/8/19 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 03 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : Sc Date: 26/8/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLQ 2132 H
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU903561682

Submit By : SERENCE
 Year Manufacture : 2017
 Engine No. : 2ZRS056884

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper <i>Bu/Pr</i>	1	\$497.50		✓
2	Rear bumper clip <i>Pr</i>	10	\$40.00		✓
3	Rear bumper side retainer LH <i>Pr</i>	1	\$112.70		X
4	Rear bumper side retainer RH <i>Pr</i>	1	\$112.70		X
5	Rear bumper reinforcement <i>R</i>	1	\$398.90		X
6	Rear bumper lower garnish centre <i>Pr/Pr</i>	1	\$582.60		✓
7	Rear bumper lower garnish RH <i>Pr/Pr</i>	1	\$149.70		✓
8	Rear bumper tow cover <i>Pr</i>	1	\$31.70		X
9	Rear bumper under cover <i>Pr</i>	1	\$355.20		X
10	Rear bumper under cover RH <i>Pr</i>	1	\$187.60		X
11	Rear bumper under cover clip <i>Pr</i>	4	\$14.00		X
12	Tail lamp RH - UPPER <i>gvc</i>	1	\$498.75		?X
13	Tail lamp RH - LOWER <i>gvc</i>	1	\$511.60		?X
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLQ 2132 H Submit By : SERENCE
 Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	2000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	3000
3	To tuff coat. <i>~</i>	\$50.00	X
4	TO Check wiring	\$50.00	150
5	To remove & refit reverse sensor	\$150.00	500
6	To conduct water leakage tests to ensure proper air and sealing <i>~</i>	\$120.00	X
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>~</i>	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.