

15/02/19

INS. CASE OWNER:

CC 3/CT11901

1008

Ed632

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

20/6/19

Date / Time:

20/6/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFV 1689U

Name of Insured:

NG JUN QUAN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

19/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SHD 6077E

INSRS:
WSP:
Tel:
Liability:
RMKS:Trans
CabINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
20/6/19	After call ltr to OI:	26/06/19 - JAWAY
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☒
26/7/19	After call ltr to OI:	☒
	Authorisation to Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	LTA / GIA:	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT Date/Time: 10/9/19		Confirm with: Ng Wei Yn	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27
Repair Cost: (w/631)	SS 7447.34		
Loss of Rental (LOR):	SS 566.82	(4.5 days) x \$125.96	
Loss of Use (LOU):	SS -	(S x days)	
Loss of Income (LOI):	SS -	(S x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LO ☐	[Tick only one]	
GIA/LTA Search	SS 7.45		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 8021.61	Global Sum SS: 8000.00	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS 8000.00	Name 1:	Trans-Cab Auto Services Pte Ltd
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

ASS. REC. BY:

REF: C721

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / File pass to

P/P - \$6960.13 (Red \$48476.15 / 872)

Veh No:

S140 3077E Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perkut Latitude c.c 19P5

Colour

M. White / Red

A/C: Insured / Std / NI / NA

Sp. Reading

132571

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 283375

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

P

mm

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

19/6/19

D.O.A.

20/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI19011008/Kdb3

Date: 21.06.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD5077E


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.06.2019 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	55,436.28
Revised Estimate Amount	: S\$	7,000.62
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.5 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5077E**AAD1906-182***Not Authored
Resony B4 pain*

20 JUL 2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 5077E

VF1ABL15AUC283375

RENAULT

LATITUDE

19.6.19

CHINA TAIPING

29/12/2017

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	BOOT REAR
14	1	BOOT FINISHER
15	1	BOOT WHEATERSTRIP
16	1	BOOT REFLECTOR LAMP LH
17	1	BOOT REFLECTOR LAMP RH
18	1	BOOT BADGE 'RENAULT'
19	1	BOOT BADGE
20	1	BOOT STRUT LH
21	1	BOOT STRUT RH
22	1	BOOT HINGE LH
23	1	BOOT HINGE RH
24	1	BOOT INNER TRIM
25	1	BOOT SWITCH
26	1	BOOT LOCK
27	1	BOOT LOCK CATCH
28	2	LICENCE PLATE LAMP
29	2	BOOT RUBBER PLUG

LIST

\$	<i>Be</i>	1,108.46	<i>✓</i>
\$	<i>Dir 1B</i>	768.84	<i>✓</i>
\$	<i>Dir</i>	113.47	<i>✓</i>
\$	<i>SL</i>	135.97	<i>✓</i>
\$	<i>SL</i>	44.99	<i>✓</i>
\$	<i>CM</i>	43.61	<i>✓</i>
\$	<i>SL</i>	135.97	<i>✓</i>
\$	<i>SL</i>	44.99	<i>✓</i>
\$	<i>SL</i>	43.61	<i>✓</i>
\$	<i>R</i>	777.52	<i>✓</i>
\$	<i>R</i>	225.95	<i>✓</i>
\$	<i>Dir</i>	225.95	<i>✓</i>
\$	<i>R</i>	2,872.68	<i>✓</i>
\$	<i>SL</i>	470.06	<i>✓</i>
\$	<i>SL</i>	323.05	<i>✓</i>
\$	<i>SL</i>	493.35	<i>✓</i>
\$	<i>SL</i>	493.35	<i>✓</i>
\$	<i>SL</i>	225.36	<i>✓</i>
\$	<i>SL</i>	225.36	<i>✓</i>
\$	<i>SL</i>	276.08	<i>X</i>
\$	<i>SL</i>	276.08	
\$	<i>R</i>	367.84	
\$	<i>R</i>	367.84	
\$	<i>SL</i>	586.45	
\$	<i>SL</i>	168.13	
\$	<i>R</i>	202.67	
\$	<i>R</i>	74.40	
\$	<i>SL</i>	50.52	<i>X</i>
\$	<i>SL</i>	221.81	

Trans-cab Auto Services Pte Ltd**AAD1906-182**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5077E

30	1	FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45	}
31	1	FENDER PANEL REAR RH	\$	R	3,299.13	
32	1	WHEELARCH REAR RH	\$	SL	543.47	
33	1	FENDER PANEL REAR LH	\$	R	3,299.13	
34	1	FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45	
35	1	WHEELARCH REAR LH	\$	SL	543.47	
36	1	TAILLAMP RH	\$	SL	552.55	
37	1	TAILLAMP PANEL RH	\$	R	986.70	
38	1	TAILLAMP LH	\$	SL	552.55	
39	1	TAILLAMP PANEL LH	\$	R	986.70	
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	SL	404.56	
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
43	1	SPARE WHEEL PANEL TRIM	\$	SL	612.21	
44	1	EXHAUST REAR	\$	R	7,489.05	
45	1	EXHAUST CAP REAR	\$	R	230.49	
46	1	FUEL FLAP	\$	SL	343.57	
TOTAL			\$		36,212.51	
10%			\$		3,621.25	
			\$		32,591.26	

Special Nett

1	1SET	PARKING AID	\$	SL	700.00	X
2	1SET	REAR BUMPER CLIP	\$	SL	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	SL	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	SL	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	SL	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	SL	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	SL	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	SL	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	SL	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	SL	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	SL	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	SL	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	SL	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	SL	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	SL	35.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	SL	385.00	X

Trans-cab Auto Services Pte Ltd

AAD1906-182

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5077E

17	1	SPARE TYRE	\$	SL	330.00	}	X
18	1	FENDER INNER TRIM CLIP RH	\$	nn	28.00		
19	1	TAILLAMP CLIP RH	\$	nn	5.00		
20	2	REAR WINDSCREEN SEALANT	\$	nn	80.00		
21	1	WINDSCREEN MOULDING	\$	nn	100.00		
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
23	1	TAILLAMP CLIP LH	\$	nn	5.00		
24	1	FENDER INNER TRIM CLIP LH	\$	nn	28.00		
25	1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00		
26	1	Rear left tyre	\$	SL	330.00		
27	1	Rear left tyre rim	\$	SL	380.00		
28	1	Rear right tyre	\$	SL	330.00		
29	1	Rear right tyre rim	\$	SL	380.00		
TOTAL			\$		3,645.02		

TOTAL PARTS	\$	36,236.28
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	4001
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	L 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	L 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1906-182**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5077E

To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	5 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	5 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	5 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	5 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00	X
TOTAL	\$	19,200.00	

Over All Total \$ 55,436.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before start spray painting
- To display damage (PART BY PART) Repair Days
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary material must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25 DAYS*2 1/2 days*

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD5077E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003271
Chassis No.:	VF1ABL15AUC283375
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2025
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	28 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$27,327.00
Total Rebate Amount:	\$42,325.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Jun 2019

OK

Shu Pei (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 25 June 2019 9:07 AM
To: Shu Pei (LKKAUTO)
Subject: RE: OUR REF: SNM19D202900/CHONGBS - Direct Settlement - Accident Involving SFV1689U (OI : CTI - TBA) AND SHD5077E (TP : LKK REF - CC3/CTI19011008/Kdb3) on 19.06.2019
Attachments: insured report.PDF

Dear Sir,

Pls find our insured report.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road
#16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lim Shu Min

Sent: Monday, 24 June, 2019 10:43 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>

Subject: OUR REF: SNM19D202900/CHONGBS - Direct Settlement - Accident Involving SFV1689U (OI : CTI - TBA) AND SHD5077E (TP : LKK REF - CC3/CTI19011008/Kdb3) on 19.06.2019

Dear Boon Sen,

Please assist & revert.

File with Officer-In-Charge – Chong Boon Sen - 63896171

Thank you

Lim Shu Min

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CT119011008/Kdb3s2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 24-09-2019		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFV 1689U	Veh. Inspected	SHD 5077E	
Policy No.	DMPCSN3074681800	Coverage (\$)	0.00	
Claim No.	SNM19D202900C02/9	Excess (\$)	0.00	
Assign From		Assign Date	20/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1ABL15AUC283375	Colour	METALLIC WHITE/RED	
Odometer	132571	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/06/2019	Inspection Date	20/06/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5077E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DISTORTED / BENT	768.84	768.84
1	BUMPER BRACKET CTR REAR	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	CRACKED	43.61	43.61
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	DISTORTED	225.95	225.95
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP	SERVICEABLE	343.57	-
	LESS 10% DISCOUNT		-3,621.23	-636.12
			32,591.26	5,725.13
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-

Report Ref No. CC3/CTI19011008/Kdb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELACRH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	SET FENDER WHEELACRH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	REAR LEFT TYRE (SN)	SERVICEABLE	330.00	-
1	REAR LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	REAR RIGHT TYRE (SN)	SERVICEABLE	330.00	-
1	REAR RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
			3,645.02	225.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		7,500.00	440.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL REAR RH, FENDER PANEL REAR LH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, OUTER PANEL REAR (END PANEL), SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		7,500.00	400.00
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00

Report Ref No. CC3/CTI19011008/Kdb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			19,200.00	1,010.00
GRAND TOTAL			55,436.28	6,960.13
RECOMMENDED COST OF REPAIRS				6,960.13

Report Ref No. CC3/CTI19011008/Kdb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.