

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19011010/UDS3N2

Date: 20/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SLJ137U **Insured Vehicle No :** SLS1050G

Date of Loss: 20/06/2019 Nature of Claim: TP Claim No: 4840441980SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ137U	Engine No:	PY20793663
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN (A)	Chassis No:	JM6GJ1032G0242396
Reg. Date:	25/11/2016 (Man. Year: 2016)	Odometer:	39374 km
Colour:	Grey		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,834.69	1,248.45	586.24	31.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	650.00	900.00	58.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,384.69	1,898.45	1,486.24	43.91
+ GST 7.00/7.00% (\$\$)	236.93	132.89	104.04	43.91
Nett Amount (\$\$)	3,621.62	2,031.34	1,590.28	43.91
+ Car Rental (3.0 x S\$120.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		2,393.34		

INSPECTION

Date of Assignment: 17/07/2019

Date Inspected: 17/07/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E.,
#01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,266.60 F	*1,076.61 F
2	1		*REAR BUMPER TOWING COVER RH	Missing	24.90 F	*9.00 F
3	1		*REAR BUMPER REFLECTOR RH	Not Necessary	53.00 F	*- F
4	2		*REAR BUMPER CLIP	Not Necessary	7.40 F	*- F
5	1		*BOOTLID EMBLEM (NPA)	Not Necessary	0.00 F	*- F
6	1		*BOOTLID LOGO -MAZDA 6 (NPA)	Not Necessary	0.00 F	*- F
7	1		*REVERSE SENSOR	Serviceable	280.00 FS	*- FS
8	1		*END PANEL (NPA)	Repair	0.00 FS	*- FS
9	1		*BOOTLID (NPA)	Not Necessary	0.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	1,631.90	1,085.61
+ Margin on L,N Items 15.00/15.00% (S\$)	202.79	162.84
Total Parts (S\$)	1,834.69	1,248.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	500.00	200.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	700.00	400.00
3	ANTI-RUST COATING	New	200.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$\$)			1,550.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >