



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2010 LEXUS RX350 3.5 (SKE3659Z)
Date of Loss	17 June 2019
Time of Loss	18.20
Loss Description	SKE3659Z (INSD) C/W SKW3011Y (TP)
Comment	

Workshop Details

Total Rebate Amount	34481
Nett Loss Amount	\$8,519.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	SKE3659Z	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>25/06/2010</div> <div></div>
Mileage	<div>152886</div>	Age of Vehicle	8

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2010	<div>2010</div>
Make	LEXUS	<div>TOYOTA</div>
		<div></div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	LIM WEN LIN, DESIREE	<div></div>
Date of Birth	30 September 1995	<div>dd/mm/yy</div> <div></div>

Model CATEGORY	RX350 3.5 POLICY INFORMATION	LEXUS RX350 INFORMATION
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	JTJBK11A102007833	JTJBK11A1020C
Engine No	2GRJ280397	2GRJ280397
Engine Capacity		3456
Sum Insured	0	0
Market Value	0	43000

CATEGORY Age	FNOL INFORMATION 23	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	4	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date	1 January 2015	dd/mm/yy 
License Expiration Date		dd/mm/yy 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	68 HILLSIDE DRIVE #02-10, 549018, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text"/>
Gender	Female	<input type="text"/>
Marital status	Unknown	<input type="text"/>
Identification #	S9536822J	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

24/06/2019

Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts



















Add













Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		LEFT FRONT DOOR (WCP) (10%)	Bent	0	726	No					726	Reviewing
		0	1		L/F DOOR SEAL	Serviceable	0	0	No					0	Deny
		0	1		L/F MLDG RETAINER	Serviceable	0	0	No					0	Deny
		0	1		L/F DOOR MOULDING	Serviceable	0	0	No					0	Deny
		0	1		L/R DOOR (WCP) (10%)	Bent	0	704	No					704	Reviewing
		0	1		L/R LOWER DOOR HINGE	Repair	0	0	No					0	Deny
		0	1		L/R DOOR CHECK	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		L/R DOOR SEAL	Serviceable	0	0	No					0	Deny
		0	1		L/R WINDOW REGULATOR (WCP) (10%)	Damaged	0	154	No					154	Reviewing
		0	1		L/R WINDOW MOTOR (WCP) (10%)	Damaged	0	330	No					330	Reviewing
		0	1		L/R DOOR HANDLE BRKT	Serviceable	0	0	No					0	Deny
		0	1		L/R DOOR OUT HANDLE	Serviceable	0	0	No					0	Deny
		0	1		L/R HANDLE TRIM	Serviceable	0	0	No					0	Deny
		0	1		L/R DOOR LOCK (WCP) (10%)	Dented	0	396	No					396	Reviewing
		0	1		L/R DR LOCK STRIKER	Repair	0	0	No					0	Deny
		0	1		L/R MLDG RETAINER (WCP) (10%)	Dented	0	110	No					110	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		L/R DOOR MOULDING (WCP) (10%)	Dented	0	198	No					198	Reviewing
		0	1		L/R W- HOUSE FRT TRIM (WCP) (10%)	Cracked	0	66	No					66	Reviewing
		0	1		L/R WHEEL BEARING	Serviceable	0	0	No					0	Deny
		0	10		L/F DOOR RIVET (WCP) (10%)	Necessary	0	2.2	No					22	Reviewing
		0	10		L/R DOOR RIVET (WCP) (10%)	Necessary	0	2.2	No					22	Reviewing
		0	2		L/R DOOR HANDLE SEAL	Serviceable	0	0	No					0	Deny


Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		140.0 WU X 45.00 SGD/H	0	427.5	0	0	Reviewing	
		0		LABOUR COST 128.0 WU X 45.00 SGD/H	0	576	0	0	Reviewing	
		0		MATERIAL COST	0	244.69	0	0	Reviewing	