# **Accident Photo**





# T5 AUTO PTE. LTD.

160 Sin Ming Drive #07-18 Sin Ming Autocity Singapore 575722 Co Regn No.201326853C Tel/FAX:68521588 Email Address:t5auto@singnet.com.sg

# Invoice

Invoice To	
Hoon Boon Keng	
Blk 535 Ang Mo Kio Ave 5	
#05-4080	
Singapore 560535	
HP: 92711474	

Date	31-May-2019
Invoice	12488

Handled By

Jeff T/96191115

Referred By

Alvin Tng/96866219

(AT PERFORMANCE)

Qty	Description	Amo	ount
1	One unit SKA2103M TOYOTA ALTIS. Rent for 03 days Rental Period: 16 May 2019 To 18 May 2019 (Vehicle return @ 17:45 HRS) Rental Fee: \$100 X 03 days		300.00
tant Note: Hir	er has to top up Fuel to the same level as check out upon	Total	\$300.0

returning the Vehicle.

No refund will be given for fuel left in the vehicle.

Vehicle return during office hour only (9.00a.m. - 5.00p.m.)

No service on Public Holiday & Sunday.

# All Cheque should be crossed and make payable to "T5 AUTO PTE LTD".

For payment made via electronic transfer Bank: United Overseas Bank Limited

Account No.: 357-305-306-9

Bank Code: 7375 Branch Code: 018

Signed for and behalf

T5 Auto Pte Ltd

Authorised Signature

# T5 AUTO PTE LTD



# T5 AUTO PTE L1

Sin Ming Autocity #07-18 160 Sin Ming Drive Singapore 575722 RENTAL AGREEMENT
Tel / Fax: +65 6852 1588

BLK-13-SIN-MING INDUSTRIAL ESTATE SECTOR B #01-37-SINGAPORE 575657.

TEL / FAX : +65 6852 1588 EMAIL : t5auto@singnet.com.sg

Co. Regn. No.: 201326853C

No. 15132

NAME HOON BOON KENG ADDRESS BLU SIS ANG MO KIO A CONTACT (HP) 92711474	09-20)± 2 AV	N12 08	NRIC/ROC S		.9
ADDRESS OLU 525 ANG MO KIO A		DV12 080			
CONTACT (HP) 92711474		00	mione 2 004.	33	
		-	FAX		
	DRIVERISEAS				
	DRIVER'S PAR	TICULAR	TO CHEST AND		Part of the
NAME Hoon Boon Keng	35		NRIC/PERMIT S	78 269226	3
The state of the s	Avenue 5 #0	5-4080	Singapore	560535	
DRIVING EXPERIENCE 24/8/1946 27/	LICENSE NO. Z	782692	(4 DOB 13	Sept 19	76
	VEHICLE & C	HARGES		0.0000000000000000000000000000000000000	aries of
VEHICLE NO SKA DIOSM	MAKE & MODEL		Toyota	Altis	PRINCIPALITY
ENTAL PERIOD 03 days	CHARGES \$ 100 Pe	er dau	DEPOSIT	-	
PIDE NEW SITUOTE	TIME 1005 HRS		110685Km	FUEL LEVEL	F
icle return during office hour only. No servi I/WE DECLARE THAT THE ABOVE PARTICU I/WE HAVE READ AND UNDERSTOOD THE	LARS ARE TRUE AND	CORRECT IN E	VERY RESPECT AN RENTAL AGREEME	D ENT AND AGREE	: TO
IPANY'S STAMP VIIIRER'S SIGNATURE & DAT	TE: D-DENTS DENT S-SCRATCHES			FRONT	
ATEIN 18/05/19 TIME HH	INDICATE:	LEFT	TOP 00 (KM FL	REAR JELLEVEL F	RIGHT
HECKED BY	V	OSIT REFUND	-		
1					

			Date:	
REFERENCE				
Handling Insurer:	India International Insurance Pte Ltd	Policy No:		MCO
Claimant Vehicle No :	EA4367B	Insured Vehicle No :		SHC
Date of Loss:	15/05/2019	Nature of Claim:		TP
DESCRIPTION & IDENTIFIC	CATION OF VEHICLE			
Reg No:	EA4367B			
Make & Model:	MERCEDES-BEN	Z C180 KOMPRESSOR, 1.6 Kompressor (A)		E
Reg. Date:	10/11/2011 (Man.)	Year: 2011)		6
Colour	Silver			0
Engine Capacity:	1597 cc			
Market Value/New Car Price	: N/A			
Sum Insured (S\$):	Market Value/Nev	v Car Price		
CONDITION OF VEHICLE A	T THE TIME OF SURVEY			
General Condition:	Good	Steering (Serviceable):	Yes	Foot
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-
CONDITION OF TYRES				
Front Tyre Size:	245/40R17	Rear Tyre Size:		
Front Left Side:	Continental 6 mm	Rear Left Side:		
Front Right Side:	Continental 6 mm	Rear Right Side:		
The above values represent the ren	naining tyre treads depth			
COST OF CLAIMS	MARKET LIFE CONTRACTOR	Repairer's	A	djuster
Parts		0.00		0.0
Miscellaneous Items		0.00		0.0
Labour		0.00		0.0
Paintwork Labour		0.00		0.0
Towing	87	0.00		0.0
	Nett Amount (S\$)	0.00		0.0

18.1	-	-	-	~=	-	4.4
IIN	3	₽	_	CT.	15.2	N.

Date of Assignment

17/05/2019

Date Inspected:


17/05/2019

Inspected At:

160 SIN MING DRIVE #07-18/1: Repairer: A T Performance

Repairer: A

0.0 days



Best Regards,

Mekavathanan HOD Motor Claims Department India International Insurance Pte Ltd 64 Cecil Street, #04/#05 IOB Building, Singapore 049711 DID: 6347 6105 Fax: 6224 4174



This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

# Nivitha (LKK Auto)

From:

Do-Not-Reply <do-not-reply@merimen.com>

Sent:

Friday, 21 June 2019 5:00 PM

To:

sur@lkkauto.com; assignments@lkkauto.com

Subject:

Incoming New Document for EA4367B

This mail is associated with:

\*EA4367B (MCT19050449)

[SHC8473E]

TP

May 15 2019 12:00AM

[-]

A T Performance

The following new document(s) has been shared with you by India International Insurance for EA4367B:

- Letter of Demand from Third Party

This is an auto-generated email. Do not reply to this email.

Sent by : Sundari Nagarajan (India International Insurance Pte Ltd)



This email has been checked for viruses by AVG antivirus software. www.avg.com MCT19050449

RESERVES			
TPPD	PRESERVE	A	
TPPI .	PRESERVE		
UNINSURED LOSS	PRESERVE		
SUBRO	PRESERVE		
LPPN			
INVESTIGATION FEE			
SURVEY FEES	()	\$	
LEGAL FEES			
OTHERS			
FRAUD CHECK			
UPLOAD TO MERIMEN			
GRANT RIGHTS			



# KM AUTO ASSESSORS PTE. LTD.

Insurance Loss Assessors / Adjuster

47 Jalan Pemimpin #02-07 Halcyon 2 Singapore 577200

T 6448 8208

F 6442 9690

E kmautoassessors@gmail.com

Regn. No. 2009073407

INVOICE NO.

9/TP1058/P

Messrs.

HOON BOON KENG

BLK 535 ANG MO KIO AVENUE 5 #05-4080 S'PORE 560535

Date 24-May-19

/5/TP006/R	Particulars		Amount
	RE: EA 4367 B - MERCEDES BENZ C 180 KOMPRESSOR AU	то	
	SURVEY FEE (INCL. PHOTOS & TRANSPORT CHARGES)		\$650.00
SGD:	( SIX HUNDRED AND FIFTY ONLY )	TOTAL:	\$650.00



### KM AUTO ASSESSORS PTE. LTD.

Insurance Loss Assessors / Adjusters

47 Jalan Pemimpin #02-07 Halcyon 2 Singapore 577200

T 6448 8208

F 6442 9690

E kmautoassessors@gmail.com

Regn. No. 2009073407

## **AUTOMOBILE** INSPECTION REPORT 9/5/TP006/R NO.

To:	HOON BOON KENG								
	BLK 535 ANG MO KIO A	BLK 535 ANG MO KIO AVENUE 5 #05-4080 S'PORE 560535							
General Condition:	: Peer/Fair/Good/Excellent								
Reg. No.	EA 4367 B	Make/Model	MERCE	MERCEDES BENZ C 180 KOMPRESSOR AUTO				2011	
Engine No.	27191031348885	Chassis No.	WDD2	WDD2040452A618780			Colour	Metallic S	Silve
Condition of Tyres					Speedome	ter Reading - Km		113265	
Front N/S	G/YEAR 225/45R17	worn	40	%	Front O/S	G/YEAR 225/45R17	worn	40	%
Rear N/S	CONTINENTAL 225/45R17	worn	30	%	Rear O/S	CONTINENTAL 225/45R17	worn	30	%
As Requested By	YOURS	SELF			On	21-May-19		The Above \	Vehicle

Was Inspected At ( 21-May-19 ) A T PERFORMANCE 160 SIN MING DR #07-19 SIN MING AUTOCITY S'PORE 575722

And The Undermentioned Damage Was Noted:-

Boot lid assy, dented and bent, lock assy, bent, rear panel assy, bent, rear lamps assy. shifted, bumper assy, dented, bent and deformed, lower centre garnish bent and dislodged, fasteners snapped, reverse sensors distorted, fenders bent and distorted, boot floor panel assy, bent.

Photographs:-	80 Copies	were taken at time of inspecti	on and are attached .	
The Repairers estimate was for a total amount of		\$	11,425.58	
After adjustment the estimate was revised and agreed at		\$	9,464.02	

SPECIAL REMARKS

The Repairers were NOT AUTHORISED to proceed with the repairs.

Survey was carried out without prejudice.

The above were due to impact to the rear portion of the vehicle.

Alternatively, we recommend that repairs be carried out on a Lump Sum basis instead, @\$7,550/- Nett.

MICHAEL EE DIPA Eng., AMIRTE, AMSAE, AMSQE, AMIMI, MSAAA.

APPENDIX 'A'

TO REPORT NO: REGN. NO:

9/5/TP006/R EA 4367 B



# KM AUTO ASSESSORS PTE. LTD.

Insurance Loss Assessors / Adjuster 47 Jalan Pegsimpin

47 Jalan Persimpin #02-07 Tialcyon 2 \* Singapore 577200

T 6448 8208 F 6442 9690

E kmautoassessors@gmail.com

Regn. No. 2009073402

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
1 pce boot lid	1,658.60	dented & bent	/ 1,658.60
1 pce boot lid inner lock assy.	318.20	bent & jammed	X 318:20 N/V
1 pce boot lid emblem	48.25	necessary	48.25
1 pce boot lid "AMG" plate	58.00	necessary	/ 58.00
1 pce boot rubber	171.53		/171.53
	105.00	kinked, deformed - necessary	
1 pce rear panel inner garnish 2 pcs rear lamps assy. <	112730353	fasteners snapped	105.00
1 pce rear bumper fascia	1,260.00 2,322.30	shifted, distorted, fasteners snapped	1,260.00
1 pce rear bumper lower centre garnish	161.61	dented, bent, deformed	/ 161.61
1 pce rear bumper tow-hook cover	41.20	bent, deformed, fasteners snapped distorted, fastener snapped	41.20
2 pcs rear bumper side retainers	70.00		70.00
2 pcs rear bumper inner side carriers	32.00	fasteners snapped	32.00
		fasteners snapped dented & bent	1
1 pce rear bumper reinforcement	615.89		615.89
1 pce rear no. plate lamp garnish	53.00	fasteners snapped	× 53.00 ///
			6,915.58 505
		less 10%	691.56
	6,915.58		6,224.02
S.NETT			4549
1 set reverse sensors	350.00	distorted, s/circuited	350.00 250
	105-205-008-2		7 600
Remove boot lid fittings, check, renew	150.00		61
damaged fittings, transfer all fittings & new	150.00		80.00 60
poot lid assy. and refit.			
Remove necessary interior upholsterys and			
ittings to enable necessary repairs, check	200.00		120.00 60
and refit same.			
Remove lamps, necessary wirings and			
electrical fittings to enable necessary repairs,			
check, replace damaged parts, refit same,	60.00		30.00
est electrical-circuit.	V24501104080		
Renew reverse sensors, transfer same to new			9
pumper assy., refit, scan, program and test	150.00		80,00 (1)
ystem.			5900 00
√ ≥ pe	7.025.50		6.004.00
C/f Cotal Amount Revised	7,825.58		6,884.02
ump Sum Repairs Amount	\$		
t is estimated that the repairs will take		days to complete.	

APPENDIX 'A'

TO REPORT NO: REGN. NO:

9/5/TP006/R EA 4367 B



# KM AUTO ASSESSORS PTE. LTD.

Insurance Loss Assessors / Adjusters 47 Jalan Pemimpin

47 Jalan Pemimpin #02-07 Halcyon 2 Singapore 577200

T 6448 8208

F 6442 9690

E kmautoassessors@gmail.com

Regn. No. 200907340Z

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
b/f	7,825.58		6,884.02
Remove damaged parts, jack out, straighten up damaged body panels, repair body parts and fittings, whichever possible and necessary, replace necessary damaged parts, refit and align whichever parts necessary (incl. alignment of body structure).	1,200.00		800.00 6° 1,400.00 6° 100.00 6° 280.00 15
Paint replacement parts and repaint damaged sections in and outside.	1,800.00		1,400.00 6-
Rustproof replacement parts and touch-up damaged sections.	200.00		100.00 60
Conduct diagnostic programming and calibration.	400.00		280.00 15
TOTAL	11,425.58		
TOTAL	11,425.56	1298 67	9,464.02
		6399.57	
		20%: 5/00	
	1		
otal Amount Revised		0.464.00	
ump Sum Repairs Amount	\$ \$	9,464.02 7,550.00	
is estimated that the repairs will take	FIVE d	lays to complete.	

HIN TAT AUGUSTINE & PARTNERS

Page No. 2

Our Ref. TCL.GCN.ro.50328.19.at

Your Ref. SHC 8473E Date: 18 June 2019

The following supporting documents are enclosed herewith: -

Copy of Singapore Accident Statement by <u>EA 4367B</u>;

2. Copy of Certificate of Insurance from QBE Insurance (International) Limited;

3. Copy of Final Repair Bill from A T Performance;

4. Copy of Rental Invoice and Rental Agreement from T5 Auto Pte. Ltd;

Copy of LTA search result of SHC 8473E;

6. Copy of Survey Invoice & Survey Report from KM Auto Assessors Pte. Ltd.; and

7. 80 pcs of original photographs of motor vehicle no. EA 4367B.

Please note that you / your authorized driver and/or your insured driver should send to us an acknowledgement of receipt of this letter within fourteen (14) days of receipt of this letter, failing which our client will have no alternative but to commence proceedings against you / your authorized driver and/or your insured driver without further notice to you / your authorized driver and/or your insured driver.

Please note that if you / your authorized driver and/or insured driver have a counterclaim against our client arising out of the accident, you / your authorized driver and/or your insured driver are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Please note that our client's claim is in respect of her property damage claim and is strictly without prejudice to the uninsured losses and/or injury claim (if any).

Yours faithfully,

GONG CHIN NAM

Enc.

cc: client

By fax



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	ationale Des Experts En Autor	nobile
NDIA INTERNATIONAL INSURANCE PL Ref : CS3/III19008789/Gtd3s2-1		89/Gtd3s2-1	
64 CECIL STREET #05-02 IOB BUILDIN	IG SINGAPORE 049711	Date: 12-07-2019 Code: III2	
	Policy Particula	rs :- THIRD PARTY CLA	IM
Insured Veh.	SHC 8473E	Veh. Inspected	EA 4367B
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19050449	Excess (\$)	0.00
Assign From	STANLEY LAI	Assign Date	21/06/2019
	Vehicle Pa	rticulars & Condition	
Make & Mode	MERCEDES BENZ C180	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2040452A618780	Colour	SILVER
Odometer	113265	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
	Cond	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyr	245/40R17	CONTINENTAL	6 mm
L/H Front Tyre	245/40R17	CONTINENTAL	6 mm
R/H Rear Tyre	245/40R17	CONTINENTAL	6 mm
L/H Rear Tyre	245/40R17	CONTINENTAL	6 mm
	Descri	ption of Damages	
THE VEHICLE S	USTAINED DAMAGES AT THE F	REAR PORTION.	
DAMAGES SEE	DETAILS.		
	Gene	eral Information	
Accident Date	15/05/2019	Inspection Date	17/05/2019
Survey held a	160 SIN MING DRIVE# 07-18	3/19	
Repairer	A T PERFORMANCE		
a.		Remarks	
A)THE INSPECT B)IN ACCORDA	TION WAS CONDUCTED ON A"V NCE TO YOUR INSTRUCTIONS,	VITHOUT PREJUDICE" BAS WE HAVE NOT AUTHORIS	SIS. ED REPAIRS.
ib.	Estima	te Days of Repair	
ESTIMATED NO	RMAL PERIOD FOR REPAIR:	5 Working Day	/S



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EA 4367B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	DENTED / BENT	1,658.60	1,658.60
1	BOOT LID INNER LOCK ASSY	NOT NECESSARY	318.20	
1	BOOT LID EMBLEM	NECESSARY	48.25	48.25
1	BOOT LID "AMG" PLATE	NECESSARY	58.00	58.00
1	BOOT RUBBER	KINKED / DEFORMED / NECESSARY	171.53	171.53
1	REAR PANEL INNER GARNISH	FASTENERS SNAPPED	105.00	105.00
2	REAR LAMPS ASSY	N/S NOT NECESSARY / O/S CRACKED	1,260.00	630.00
1	REAR BUMPER FASCIA	DENTED / BENT / DEFORMED	2,322.30	1,463.00
1	REAR BUMPER LOWER CENTRE GARNISH	BENT / DEFORMED / FASTENERS SNAPPED	161.61	161.61
1	REAR BUMPER TOW - HOOK COVER	DISTORTED / FASTENER SNAPPED	41.20	41.20
2	REAR BUMPER SIDE RETAINERS	FASTENERS SNAPPED	70.00	70.00
2	REAR BUMPER INNER SIDE CARRIERS	FASTENERS SNAPPED	32.00	32.00
1	REAR BUMPER REINFORCEMENT	DENTED / BENT	615.89	615.89
1	REAR NO. PLATE LAMP GARNISH	NOT NECESSARY	53.00	5
	LESS 10% DISCOUNT		-	-505.51
			6,915.58	4,549.57
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSORS (SN)	DISTORTED / S/CIRCUITED	350.00	250.00
		process and the second second	350.00	250.00
	LABOUR			
	REMOVE BOOT LID FITTINGS, CHECK, RENEW DAMAGED FITTINGS, TRANSFER ALL FITTINGS & NEW BOOT LID ASSY AND REFIT.		150.00	60.00

Report Ref No. CS3/III19008789/Gtd3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE NECESSARY INTERIOR UPHOLSTERYS AND FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT SAME.		200.00	60.00
	REMOVE LAMPS, NECESSARY WIRINGS AND ELECTRICAL FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK, REPLACE DAMAGED PARTS, REFIT SAME, TEST ELECTRICAL-CIRCUIT.		60.00	30.00
	RENEW REVERSE SENSORS, TRANSFER SAME TO NEW BUMPER ASSY, REFIT, SCAN, PROGRAM AND TEST SYSTEM.		150.00	40.00
	REMOVE DAMAGED PARTS, JACK OUT, STRAIGHTEN UP DAMAGED BODY PANELS, REPAIR BODY PARTS AND FITTINGS, WHICHEVER POSSIBLE AND NECESSARY, REPLACE NECESSARY DAMAGED PARTS, REFIT AND ALIGN WHICHEVER PARTS NECESSARY (INCL. ALIGNMENT OF BODY STRUCTURE).		1,200.00	600.00
	PAINT REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS IN AND OUTSIDE.		1,800.00	600.00
	RUSTPROOF REPLACEMENT PARTS AND TOUCH-UP DAMAGED SECTIONS.		200.00	60.00
	CONDUCT DIAGNOSTIC PROGRAMMING AND CALIBRATION.		400.00	150.00
			4,160.00	1,600.00
	GRAND TOTAL		11,425.58	6,399.57

(TO ITS PRE-ACCIDENT CONDITION)	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	5,100.00
---------------------------------	--	----------

Report Ref No. CS3/III19008789/Gtd3s2-1

XING GUO QIANG

ADRIAN LING WAI PING

M.MATAI, AMSAE-A

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Automotive Assessor** 

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.