

ASS. REC. BY:

REF: CS/SM019011048/T19013

Special Instruction:

Survivor: TANGEN

ASSIGNMENT (Office)

From (Person): Ruth Chua Gel Tiang of SMD Date/Time: 24.6.19 9.38a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCU 8812A Insured: SKZ 31992

at Workshop m/s 96 motorport Tel: 67026996

of 62 Kaki Bukit Ave 6, The Ark @ KB

Policy No: D19MTPV0100074 Claim No: CMTD1902990

Sum Insured: Excess:

Make of Veh: D.O.A. 21.6.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 24.6.19 10.07am Person Contacted: Royce Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SCU 8812A - NA / INC 19011016 / 24 D.O.A. - 21/06/2019
	SKZ 31992 - X
25/6/19 @ 1.52pm	revised to Ruth Chua via Weimann.

minim
No
photo
upload

(08/11/13)

ASS. REC. BY:

REF SMD

ASSIGNMENT

From:

Date:

24.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SCU 8812A

at Workshop m/s

96 motorsports

of 62 Kaki Bukit Ave 6, The Ark @ KB

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Jude

Veh No:

SCU 8812A

Yr Regn:

2016, Apr. 1.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota / Honda

c.c.

1986

Colour:

Orange

A/C:

Insured / Std / NI / NA

Sp. Reading

112099

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZS4600066708

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

R/Bal.

mm

Rear

6

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

24/6/19 @ 24.5

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/11

Email w/s L/S \$4750, 5 days, confirm by Jude
Lred \$5671.36, 54%.

RECEIVED 13 NOV 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 13/11

Jude

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

Report Format:

MER-TI

Lump Sum / I.B.I. (\$

4750

350

11

361

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 25 Jun 2019

Preliminary Advice

Insured Vehicle No	: SKZ3199Z	Accident Date	: 21/06/2019
TP Vehicle No	: SCU8812A	Assignment Date	: 24/06/2019
Make	: TOYOTA HARRIER	Est. Duration of Repair	: 5.00
Date of Inspection	: 24/06/2019		
Inspection At	: 96 MOTORSPORTS PTE LTD (HQ) 62 KAKI BUKIT AVENUE 6, THE ARK@KB SINGAPORE 417893		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,421.36
Revised Amount	:S\$	5,862.43
Check Items (Estimated)	:S\$	763.35
Total	:S\$	6,625.78

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2019		24 Jun 2019 09:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KER YONG CHUAN , ID: S86241601, Tel: +6597457075, Email: RYANKER@LIVE.COM								
Main Claimant:	ONG KAIBIN KELVIN , ID: S8413600Z								
Vehicle Reg. No.:	SCU8812A	Date of Loss:	21/06/2019 07:00 - :59						
Claim Type:	TP / CMTD1902990	Policy/Cover Note No.:	D19MTPV01000717 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKZ3199Z	Policy No. (Claimant):							
		Excess:							
Repairer:	96 Motorsports Pte Ltd (HQ) 62 Kaki Bukit Avenue 6, The Ark@KB, 417893 Kaki Bukit - Tel: 6702 6996								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/07/2019]								
Driver/Custodian (Insured):	KER YONG CHUAN (32 / Male) , NRIC: S86241601, Tel: +6597457075 Email: RYANKER@LIVE.COM								
Adj Asg. Remarks:	WS: ROYCE PHUA 67026996								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3600Z
Vehicle Details	
Vehicle No.:	SCU8812A
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	Silver
Secondary Colour:	Red
Manufacturing Year:	2015
Engine No.:	3ZRB690391
Chassis No.:	ZSU600066798
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$29,168.00
Original Registration Date:	26 Apr 2016
First Registration Date:	26 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$27,836.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2026
PARF Rebate Amount:	\$20,877.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$47,510.00
COE Rebate Amount:	\$32,116.00
Total Rebate Amount:	\$52,993.00

The information contained herein is correct as at 25 Jun 2019

OK



96 MOTORSPORTS PTE LTD

64 Kaki Bukit Ave 6 Singapore (417893)

Email: estimator@96motorsports.com

Tel: 67026996/83118211

VEHICLE NUM:

MAKE & MODEL:

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

SCU 8812 A

TOTOTA HARRIER

ZSU60-0066798

ATTN:				
NO.	DESCRIPTION - PARTS	QTY	UNIT	ADJUSTED PRICE
1	TAIL GATE	1	\$ 1,521.50	6t
2	TAIL GATE BADGE	1	\$ 65.70	nee
3	TAIL GATE EMBLEM(HARRIER)	1	66..9	nee
4	TAIL GATE INNER LOCK	1	\$ 385 461.40	X un.
5	TAIL GATE LOCK CATCH	1	\$ 48.40	x un.
6	TAIL GATE WEATHERSTRIP	1	\$ 399.10 523.70	cut
7	TAIL GATE WINDSCREEN MOULDING	1	\$ 210.10 367.60	nee
8	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 246.80	nee
9	REAR BUMPER	1	\$ 1395.30 1,695.30	de
10	REAR BUMPER SIDE RETAINER L+R	2	\$ 262.80 131.40	14. de, RY-X un. 131.40
11	REAR BUMPER ATTACHMENT RETAINER L+R	2	\$ 137.40	? de 274.80
12	REAR BUMPER CLIP	1SET	\$ 35.00	nee
13	REAR BUMPER SPONGE	1	\$ 127.80	? cre
14	REAR BUMPER REFLECTOR L+R	2	\$ 226.8 113.40	1 ? cut 226.80
15	REAR BUMPER LOWER SPOILER	1	\$ 401.70	cut
16	END PANEL	1	\$ 921.30	Ry
17	END PANEL TOP TRIM	1	\$ 357.60	x un
18	END PANEL TOP TRIM CLIP	1SET	\$ 30.00	x un
19	REAR KEY ANTENNE SENSOR	1	\$ 177.80	? X un
20	REAR EXHAUST SILENSER	1	\$ 801.54	x un
21	REAR EXHAUST MOUNTING	2	\$ 170.8 85.40	x un
22	REAR EXHAUST GASKET	1	\$ 44.17	x un.
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25/0 5102.90 3827.18

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19011048/T1QD3

Date: 18/11/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01000717
Claimant Vehicle No :	SCU8812A	Insured Vehicle No :	SKZ3199Z
Date of Loss:	21/06/2019	Nature of Claim:	TP
		Claim No:	CMTD1902990

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCU8812A	Engine No:	3ZRB690391
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Chassis No:	ZSU600066798
Reg. Date:	26/04/2016 (Man. Year: 2015)	Odometer:	117099 km
Colour:	Orange		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,532.06	4,427.17	3,104.89	41.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,520.00	1,720.00	53.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,772.06	5,947.17	4,824.89	44.79
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	10,772.06	4,750.00	6,022.06	55.90
+ GST 7.00/7.00% (S\$)	754.04	332.50	421.54	55.90
Nett Amount (S\$)	11,526.10	5,082.50	6,443.60	55.90

INSPECTION

Date of Assignment:	24/06/2019	
Date Inspected:	24/06/2019	Inspected At:
		96 Motorsports Pte Ltd (HQ)
		62 Kaki Bukit Avenue 6, The Ark@KB
		Singapore 417893
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCU8812A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,521.50 FL	*1,521.50 FL
2	1		*TAIL GATE BADGE	Necessary	65.70 FL	*65.70 FL
3	1		*TAIL GATE EMBLEM (HARRIER)	Necessary	66.90 FL	*66.90 FL
4	1		*TAIL GATE INNER LOCK	Not Necessary	461.40 FL	*- FL
5	1		*TAIL GATE LOCK CATCH	Not Necessary	48.40 FL	*- FL
6	1		*TAIL GATE WEATHERSTRIP	Cut	523.70 FL	*399.10 FL
7	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	367.60 FL	*210.10 FL
8	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	246.80 FL	*246.80 FL
9	1		*REAR BUMPER	Deformed	1,695.30 FL	*1,395.30 FL
10	1		*REAR BUMPER SIDE RETAINER L+R	N/s Deformed/O/s Not Necessary	262.80 FL	*131.40 FL
11	2		*REAR BUMPER ATTACHMENT RETAINER L+R	Deformed	274.80 FL	*274.80 FL
12	1		*SET REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
13	1		*REAR BUMPER SPONGE	Cracked	127.80 FL	*127.80 FL
14	2		*REAR BUMPER REFLECTOR L+R	Cut	226.80 FL	*226.80 FL
15	1		*REAR BUMPER LOWER SPOILER	Cut	401.70 FL	*401.70 FL
16	1		*END PANEL	Repair	921.30 FL	*- FL
17	1		*END PANEL TOP TRIM	Not Necessary	357.60 FL	*- FL
18	1		*SET END PANEL TOP TRIM CLIP	Not Necessary	30.00 FL	*- FL
19	1		*REAR KEY ANTENNE SENSOR	Not Necessary	177.80 FL	*- FL
20	1		*REAR EXHAUST SILENSER	Not Necessary	801.54 FL	*- FL
21	2		*REAR EXHAUST MOUNTING	Not Necessary	170.80 FL	*- FL
22	1		*REAR EXHAUST GASKET	Not Necessary	44.17 FL	*- FL
23	1		*REAR REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
24	1		*BODY WRAP FOR ACCIDENT AREA (STICKER ORANGE)	Necessary	600.00 FS	*400.00 FS
25	1		*REAR NUMBER PLATE WITH BRACKET	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,739.41	5,702.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,207.35	1,275.73
Total Parts (\$\$)	7,532.06	4,427.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	New	1,400.00	700.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,200.00	700.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	30.00
4	TO R&R GATE MECH	New	120.00	60.00
5	TO R&R REVERSE SENSOR	New	150.00	30.00
6	TO R&R REAR EXHAUST	New	250.00	0.00
Gross Labour Cost (S\$)			3,240.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >