

ASS. REC. BY:

REF: CS/FCI 19011055/Krd372

Special Instruction:

Surveyor: Lonneth

ASSIGNMENT (Office)

CWS

From (Person):

Henry Koro

of

FCI

Date/Time:

21/6/19 @ 5.54pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To inspect Vehicle No:

SHD 339H

Insured:

SHC 0626J

at Workshop m/i

transcab

Tel:

62876666

of

No. 2 AMK st. 63

Policy No:

Claim No:

D19004061MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/06/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

9.20am @ 21/6/19

Person Contacted:

Candy

Vehicle: IN OUT

Date/Time

Action/Instruction

Estimate

SHD 339H; CS/FCI 19004019/Krd372 RA: 22/02/2019

SHC 0626J CCH/ASM 18003327/KINDS 2 D.O.A: 19/02/2018

25/6/19

Email preli revised to FCI

11/7/19

11 Lyr 84950L to Summit (Red 71,698.68, 9490



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004061MFSH

Our ref: CS/FCI19011055/Kvd3

Date : 25/6/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 339H


We thank for your instruction on 21/6/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/6/2019 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$76,648.68
Revised Estimate Amount	: S\$6,174.08
"Check" Items Amount	: S\$2,083.95
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	21-06-2019	Our Ref No. D19004061MFSH
Accident Date	19-06-2019	Claim Type. Third Party
Insured Vehicle	SHC0626J	Third Party Vehicle. SHD339H
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 25 June 2019 2:27 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004061MFSH/1, SHD 339H
Attachments: SHD 339H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 339H
Date of survey: 24/6/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 24 June 2019 9:28 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004061MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 21 June 2019 5:54 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004061MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 10 July 2019 5:30 PM
To: Veron Chen (LKKAUTO)
Subject: <Book Value> TCS REF: AAD1906-187--Accident involving SHC0626J & SHD0339H on 19.06.19

WITHOUT PREJUDICE

Dear Veron

Refer to our tele-conversation.

Book Value amount \$ 58,567.03.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 11 July 2019 3:48 PM
To: SUR; Ng Wai Yin
Cc: jasminetan@transcab.com.sg
Subject: SHD 339H-DOA: 19/6/2019
Attachments: MARKING.pdf

Dear Wai Yin,

WITHOUT PREJUDICE

Lump Sum \$4950 before GST @ 3 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD339H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002938
Chassis No.:	VF1ABL15AUC282743
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	22 Mar 2016
First Registration Date:	22 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	21 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,633.00
COE Rebate Amount:	\$23,545.00
Total Rebate Amount:	\$38,543.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Jun 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H**AAD1906-187***Not Authored
L/Sing \$4950t*

24 JUN 2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 339H

VF1ABL15AUC282743

RENAULT

LATITUDE

19.6.19

FIRST CAPITAL

22/3/2016

PART		LIST	
1	BUMPER COVER FRT	\$	R 1,259.42
1	BUMPER SPOILER FRT	\$	R 181.75
1	BUMPER ABSORBER FRT	\$	R 394.68
1	BUMPER RETAINER FRT LH	\$	R 151.41
1	BUMPER SUPPORT FRT	\$	R 123.88
1	BUMPER UNDERTRAY FRT	\$	R 472.83
1	BUMPER GRILLE LOWER FRT	\$	R 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	R 207.21
1	BUMPER BEAM FRT	\$	R 914.08
1	HEADLAMP LH	\$	mgm 1,184.43
1	HEADLAMP PANEL FRT LH	\$	R 152.15
1	FENDER PANEL FRT LH	\$	R 783.83
1	WHEELARCH FRT LH	\$	Dir 278.84
1	FENDER BRACKET LOWER LH	\$	R 15.79
1	FENDER INSULATOR LH	\$	R 130.84
1	FRONT BRACE PANEL	\$	R 177.22
1	RADIATOR GRILLE	\$	R 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	R 225.36
1	RADIATOR GRILLE FRAME	\$	R 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	R 615.90
1	FRAME FULL SUPPORT BRACKET	\$	R 89.79
1	BONNET	\$	R 1,941.63
1	BONNET INSULATOR	\$	R 405.73
1	BONNET STRUT LH	\$	R 88.61
1	BONNET STRUT RH	\$	R 88.61
1	BONNET HINGE LH	\$	R 348.31
1	BONNET HINGE RH	\$	R 348.31
1	BONNET LOCK	\$	R 305.48
1	BONNET CABLE	\$	R 119.19

Trans-cab Auto Services Pte Ltd**AAD1906-187**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

1	BONNET CABLE COVER	\$	S _h	161.03	}	X
1	BONNET SEAL OUTER	\$	S _h	92.36		
1	BONNET SEAL INNER	\$	S _h	157.28		
1	AIR CLEANER BOX	\$	S _h	464.20		
1	AIR CLEANER HOSE	\$	S _h	175.85		
1	AIR CLEANER LOWER	\$	S _h	271.26		
1	AUTO COMPUTER	\$	S _h	5,032.17		
1	INJECTION COMPUTER	\$	S _h	4,706.30		
1	RHD HYDRAULIC POWER(RQCK&PINION)	\$	S _h	5,154.52		
1	STEERING PUMP ELECTRIC L70Y	\$	S _h	2,306.90		
1	STEERING PINION RACK L70Y	\$	S _h	4,413.11	}	✓
1	DOOR PANEL FRT LH	\$	B _h	2,844.66		
1	DOOR HINGE UPPER LH	\$	h	261.28	}	X
1	DOOR HINGE LOWER LH	\$	h	300.55		
1	DOOR CHECK FRT LH	\$	S _h	194.77		
1	DOOR LOCK FRT LH	\$	h	908.75		
1	DOOR CATCH FRT LH	\$	S _h	131.23		
1	DOOR HANDLE OUTER FRT LH	\$	S _h	477.76		
1	DOOR HANDLE COVER FRT LH	\$	S _h	13.22		
1	DOOR HANDLE MODULE FRT LH	\$	S _h	133.60		
1	DOOR REGULATOR FRT LH	\$	h	505.19		
1	DOOR REGULATOR MOTOR FRT LH	\$	S _h	796.46		
1	DOOR REGULATOR GUIDE FRT LH	\$	S _h	120.97		
1	DOOR MOULDING FRONT LH	\$	S _h	176.82		
1	DOOR FINISHER INNER FRONT LH	\$	S _h	323.44		
1	DOOR FINISHER FRONT LH	\$	S _h	423.10		
1	DOOR CASING FRONT LH	\$	S _h	1,509.06		
1	DOOR BLIND FRONT LH	\$	S _h	741.80		
1	DOOR WHEATHESTRIP FRONT LH	\$	S _h	410.66		
1	DOOR SEAL FRONT LH	\$	S _h	162.02		
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	S _h	229.31		
1	DOOR WAIST SEAL OUTER FRONT LH	\$	S _h	334.69		
1	DOOR WAIST SEAL INNER FRONT LH	\$	S _h	115.64		
1	DOOR MIRROR ASSY LH	\$	S _h	1,483.40		
1	DOOR MIRROR GLASS LH	\$	S _h	148.20		
1	DOOR MIRROR BACK COVER LH	\$	S _h	218.46		
1	DOOR PANEL REAR LH	\$	h	2,844.66		
1	DOOR HARNESS WIRE LH	\$	S _h	2,670.00		

Trans-cab Auto Services Pte Ltd

AAD1906-187

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

1	LOWER ARM LH L70Y	\$	Sn	685.76	X
1	KNUCKLE ARM LH L70Y	\$	Sn	846.98	X
1	ABSORBER FRT LH L70Y	\$	Sn	360.54	X
1	DRIVESHAFT LH	\$	n	1,747.45	}
1	STABILIZER BAR FRT	\$	Sn	604.65	
1	ROCKER PANEL INNER GARNISH LH	\$	Sn	466.51	
1	ROCKER PANEL INNER LH	\$	n	1,024.79	
1	ROCKER PANEL OUTER LH	\$	n	1,184.99	
1	ROCKER PANEL CENTER LH	\$	n	990.25	
TOTAL		\$		63,660.19	
10%		\$		6,366.02	
		\$		57,294.17	

Special Nett

1	BUMPER CLIP FRT	\$	n	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	X
1	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1	WHEELARCH CLIP FRT LH	\$	nn	30.50	✓
1	FRONT LEFT TYRE	\$	Sn	300.00	}
1	FRONT LEFT TYRE RIM	\$	Sn	380.00	
1SET	Front licence plate with holder	\$	Sn	80.00	
1	WINDSCREEN SEALANT	\$	nn	253.80	
1	FRONT WINDSCREEN MOULDING	\$	nn	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	n	100.00	}
6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	
2	BONNET STRUT L70Y	\$	nn	88.61	
2	BONNET CABLE CLIP L70Y	\$	nn	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	}
1SET	RADIATOR GRILLE SCREW	\$	nn	16.00	
1	FRONT DOOR STICKER 'Trans-Cab'	\$	n	80.00	60sn
1	FRONT DOOR STICKER 'Classic'	\$	n	80.00	15sn
1	REAR DOOR STICKER '6555-3333'	\$	n	80.00	60sn
1	DOOR CHECK BOLT	\$	nn	22.69	X

Trans-cab Auto Services Pte Ltd**AAD1906-187**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

1	DOOR GUIDE SCREW	\$	na	10.85	} X
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT LH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
TOTAL		\$		2,064.51	
TOTAL PARTS		\$		59,358.68	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	500
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na	380.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na	380.00 X
To transfer of front windscreen fittings and conduct water seepage test.	\$	na	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00	600
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	na	440.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	na	380.00 X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1906-187

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

Putty and spray painting of the affected portion.	\$	6,000.00	66d
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2d
To rust-proofing of the affected areas.	\$	170.00	6d
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	6d
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
To check ABS brake efficiency, final checking and testing.	\$	nn 380.00	X
Towing Fees	\$	nn 150.00	X
TOTAL	\$	17,290.00	
Over All Total	\$	76,648.68	

LUMP SUM (REPAIR DAY)20 days
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19011055/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 626J	Veh. Inspected	SHD 339H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004061MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	21/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC282743	Colour	METALLIC WHITE / RED	
Odometer	355648	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	GITI	9 mm	
L/H Rear Tyre	215/60 R16	GITI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/06/2019	Inspection Date	24/06/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 339H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR ↗	1,259.42	-
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR ↗	914.08	-
1	HEADLAMP LH	MTG CRACKED	1,184.43	1,184.43 ✓
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR ↗	152.15	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83 ✓
1	WHEELARCH FRT LH	DISTORTED	278.84	278.84 ✓
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR ↗	177.22	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR ↗	89.79	-
1	BONNET	TO REPAIR SEE LABOUR ↗	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR ↗	348.31	-

Report Ref No. CS/FCI19011055/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE RH	TO REPAIR SEE LABOUR ✓	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR ✓	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	INJECTION COMPUTER	SERVICEABLE	4,706.30	-
1	RHD HYDRAULIC POWER (RACK & PINION)	SERVICEABLE	5,154.52	-
1	STEERING PUMP ELECTRIC L70Y	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK L70Y	SERVICEABLE	4,413.11	-
1	DOOR PANEL FRT LH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR ✓	261.28	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR ✓	300.55	-
1	DOOR CHECK FRT LH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT LH	TO REPAIR SEE LABOUR ✓	908.75	-
1	DOOR CATCH FRT LH	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT LH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT LH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT LH	TO REPAIR SEE LABOUR ✓	505.19	-
1	DOOR REGULATOR MOTOR FRT LH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT LH	SERVICEABLE	120.97	-
1	DOOR MOULDING FRONT LH	SERVICEABLE	176.82	-
1	DOOR FINISHER INNER FRONT LH	SERVICEABLE	323.44	-
1	DOOR FINISHER FRONT LH	SERVICEABLE	423.10	-

Report Ref No. CS/FCI19011055/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR CASING FRONT LH	SERVICEABLE	1,509.06	-
1	DOOR BLIND FRONT LH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP FRONT LH	SERVICEABLE	410.66	-
1	DOOR SEAL FRONT LH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL FRONT LH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER FRONT LH	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER FRONT LH	SERVICEABLE	115.64	-
1	DOOR MIRROR ASSY LH	SERVICEABLE	1,483.40	-
1	DOOR MIRROR GLASS LH	SERVICEABLE	148.20	-
1	DOOR MIRROR BACK COVER LH	SERVICEABLE	218.46	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HARNESS WIRE LH	SERVICEABLE	2,670.00	-
1	LOWER ARM LH L70Y	SERVICEABLE	685.76	-
1	KNUCKLE ARM LH L70Y	SERVICEABLE	846.98	-
1	ABSORBER FRT LH L70Y	SERVICEABLE	360.54	-
1	DRIVESHAFT LH	TO REPAIR SEE LABOUR	1,747.45	-
1	STABILIZER BAR FRT	SERVICEABLE	604.65	-
1	ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	1,184.99	-
1	ROCKER PANEL CENTER LH	TO REPAIR SEE LABOUR	990.25	-
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	-
	LESS 10% DISCOUNT		-6,366.02	-509.18
			57,294.19	4,582.58
	<u>SPECIAL NETT ITEMS</u>			
1	BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-

Report Ref No. CS/FCI19011055/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WHEELARCH CLIP FRT LH (SN)	NECESSARY	30.50	30.50
1	FRONT LEFT TYRE (SN)	SERVICEABLE	300.00	-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET STRUT L70Y (SN)	NOT NECESSARY	88.61	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN)	NOT NECESSARY	10.85	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CLASSIC" (SN)	NECESSARY	80.00	15.00
1	REAR DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT LH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
			2,064.48	231.50
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME. }		6,000.00	500.00

Report Ref No. CS/FCI19011055/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	INCLUSIVE OF THE REPAIR OF BUMPER COVER FRT,BUMPER BEAM FRT,HEADLAMP PANEL FRT LH,FRONT BRACE PANEL,FRAME FULL SUPPORT BRACKET,BONNET,BONNET HINGE LH,BONNET HINGR RH,BONNET LOCK,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR LOCK FRT LH,DOOR REGULATOR FRT LH,DOOR PANEL REAR LH,DRIVESHAFT LH,ROCKER PANEL INNER LH,ROCKER PANEL OUTER LH AND ROCKER PANEL CENTER LH. }		-	-
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19011055/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO CHECK ABS BRAKE EFFICIENCY,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TOWING FEES.	NOT NECESSARY	150.00	-
			17,290.00	1,360.00
	GRAND TOTAL		76,648.67	6,174.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,950.00

Report Ref No. CS/FCI19011055/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.