

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLT7432T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHAN HONG KHIANG RAYMOND

NRIC/Passport Number

S1391633J

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKK8773L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

JAMIYANPERJLEE MUNKHBAYAR

NRIC/Passport Number

S7160171D

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

Farrer Road towards Holland Road (near Farrer MRT)



C-SKK8773L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

I/We ^{BTE} declare the foregoing particulars are true in every respect.



Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 15/3/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



VEHICLE APPRAISAL REPORT

Our Reference: TP19-038023-TWL
 Your Reference: -
 Vehicle Number: SGK5725T

Date: 9-Apr-19

To: Kom Mum Kiet
 C/o T.W.LIM MOTOR WORKS,
 10 Anson Road #10-06
 International Plaza
 Singapore 079903

Assessment of Vehicle No: SGK5725T
 Date of Accident: 15-Mar-19
 Date of Inspection: 20-Mar-19

We have carried out a physical assessment of SGK5725T at M/s T.W.LIM Motor Works according to your instruction on 20-Mar-2019 and are pleased to submit our report herewith.

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGK5725T	Make:	DAIHATSU
Reg Year:	2006	Model:	TERIOS 1.5L
Colour:	Yellow	Engine No:	-
Type:	-	Chassis No:	JDAJ200G001002678
Type of Claim:	-	Odometer No:	- km
Market Value:	-	Engine Cap.:	1495 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition : Good	Steering : Serviceable	Engine Modification : NA
Paint work : Good	Handbrake : Serviceable	Pre-accident damage : NA
	Footbrake : Serviceable	

CONDITION OF TYRES

Front Left Size:	Michelin 215/65 R16 20%	Front Right Size:	Michelin 215/65 R16 20%
Rear Left Size:	Michelin 215/65 R16 20%	Rear Right Size:	Michelin 215/65 R16 20%

The above percentages represent the remaining life of the tyre treads

COST OF REPAIRS	Repairer's S\$	Adjuster's S\$	Difference S\$
Parts	13,471.74	13,471.74	0.00
Labour	6,500.00	5,680.00	820.00
Calculated Cost (S\$) :	19,971.74	19,151.74	820.00

Recommended Lump Sum Repair: SS15,200.00

Page - 1

Estimated Repair Period: 16 days


Repair Status: Surveyed on a "Without Prejudice" basis.

TP19-038023-TWL

SGK5725T

ON OF DAMAGE


of inspection, this vehicle sustained damages to the **Front and Rear** portion. Please see attached details.



SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated **16 working days** are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Ang Guea Kiang
Automotive Appraiser
MSAAA

Disclaimer

Pursuant to your instruction, we have **NOT AUTHORIZED** repair. The assessment was conducted on a "**Without Prejudice**" basis. If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **CA APPRAISER PTE LTD** for any reliance on this report by any third party.

Our Reference : TP19-038023-TWL

Your Reference : -

Vehicle Number : SGK5725T

S/N	QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
PARTS FRONTAL (LIST ITEMS)					
1	1	FRONT BUMPER FASCIA	TORN	798.00	560 / 798.00
2	1SET	FRONT BUMPER CLIP	NECESSARY	50.00	/ 50.00
3	1	FRONT BUMPER TOW COVER	MISSING	66.20	/ 66.20
4	1	FRONT BUMPER REINFORCEMENT	BENT	397.10	/ 397.10
5	1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	42.50	/ 42.50
6	1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	42.50	/ 42.50
7	1	HEAD LAMP ASSY LH	CRACKED	898.45	665 / 898.45
8	1	HEAD LAMP ASSY RH	CRACKED	898.45	665 / 898.45
9	1	FRONT SUPPORT PANEL ASSY	BENT	683.00	Repair X 683.00
10	1	FRONT BRACE PANEL	BENT	104.25	/ 104.25
11	1	FRT SUPPORT PANEL TOP BRACKET	BENT	52.30	/ 52.30
12	1	AIR CON CONDENSER	DENTED	640.80	NN / X 640.80
13	1	RADIATOR ASSY	DENTED	752.30	/ X 752.30
14	2	RADIATOR AIR GUIDE	CUT/DEFORMED	172.20	/ 172.20
15	1	BONNET	BUCKLED	699.45	/ 699.45
16	1	BONNET LOCK	BENT	100.40	/ 100.40
17	1	BONNET HINGE LH	BENT	65.30	Repair / X 65.30
18	1	BONNET HINGE RH	BENT	65.30	/ X 65.30
19	1	FRONT GRILLE	CUT	404.25	264 / 404.25
20	1	FRONT GRILLE EMBLEM	NECESSARY	48.50	/ 48.50
21	1	FRONT FENDER LH	REPAIR	-	-
22	1	FRONT FENDER RH	BUCKLED	688.15	Repair X 688.15
				7,669.40	7,669.40
				less 15%	15%
				1,150.41	1,150.41
Parts Frontal sub Total :				6,518.99	6,518.99

3929.4
15% : 3339.99

Our Reference : TP19-038023-TWL

Your Reference : -

Vehicle Number : SGK5725T

S/N	QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
<u>PARTS REAR (LIST ITEMS)</u>					
23	1	BACK DOOR	BUCKLED	1,400.80	/ 1,400.80
24	1	BACK DOOR HINGE UPPER	BENT	78.50	Repair X 78.50
25	1	BACK DOOR HINGE LOWER	BENT	78.50	X 78.50
26	1	BACK DOOR WEATHERSTRIP	DEFORMED	229.00	/ 229.00
27	1	BACK DOOR LOCK	BENT	309.10	/ 309.10
28	1	REAR WINDSCREEN MOULDING	NECESSARY	79.00	/ 79.00
29	1	REAR WINDSCREEN DAM	NECESSARY	80.00	/ 80.00
30	1	BACK DOOR EMBLEM 'LOGO'	NECESSARY	45.00	/ 45.00
31	1	BACK DOOR EMBLEM 'TERIOS'	NECESSARY	35.00	/ 35.00
32	1	BACK DOOR STICKER 'DAIHATSU'	NECESSARY	30.00	/ 30.00
33	1	REAR WIPER MOTOR	BENT	509.00	NNX 509.00
34	1	SPARE WHEEL HOLDER BRACKET	BENT	440.00	NNX 440.00
35	1	REAR BUMPER FASCIA	TORN	609.00	/ 609.00
36	1SET	REAR BUMPER CLIP	NECESSARY	50.00	/ 50.00
37	1	REAR BUMPER SIDE RETAINER LH	CRACKED	48.60	/ 48.60
38	1	REAR BUMPER SIDE RETAINER RH	DISTORTED	48.60	/ 48.60
39	1	REAR BUMPER REFLECTOR LH	CRACKED	66.25	/ 66.25
40	1	REAR BUMPRE REFLECTOR RH	CRACKED	66.25	NNX 66.25
41	1	REAR BUMPER TOW COVER	MISSING	51.20	36.2 / 51.20
42	1	REAR END PANEL	BUCKLED	480.20	/ 480.20
43	1	REAR END PANEL TOP GARNISH	DEFORMED	108.50	/ 108.50
44	1SET	RR END PANEL TOP GARNISH CLIP	NECESSARY	20.00	/ 20.00
45	1	REAR FLOOR PANEL	BUCKLED	470.00	Repair X 470.00
46	1	REAR FLOOR PANEL INSULATOR PAD	NECESSARY	300.00	300.00 200
47	1	TAILLAMP LH	CRACKED	528.55	315 / 528.55
48	1	TAIL LAMP RH	CRACKED	528.55	315 / 528.55

Our Reference : TP19-038023-TWL

Your Reference : -

Vehicle Number : SGK5725T

S/N	QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
<u>PARTS REAR (LIST ITEMS)</u>					
49	1	REAR FENDER LH	REPAIR	-	-
50	1	REAR FENDER INNER TRIM LH	DEFORMED	780.10	/ 780.10
51	1	REAR FENDER RH	REPAIR	-	-
52	1	REAR EXHAUST SILENCER	BENT	430.00	/ 430.00
				7,899.70	7,899.70
				less 15%	15%
				1,184.96	1,184.96
Parts Rear sub Total :				6,714.75	6,714.75
<u>SPECIAL NETT ITEMS (FRONTAL)</u>					
53	1	FRONT NUMBER PLATE	DENTED	50.00	40 50.00
54	1	RADIATOR COOLANT	NECESSARY	78.00	40 78.00
Special Nett Frontal Sub Total:				128.00	128.00
<u>SPECIAL NETT ITEMS (REAR)</u>					
55	1	REAR NUMBER PLATE	DENTED	50.00	40 50.00
56	1	REAR WINDSCREEN SEALANT	NECESSARY	60.00	50 60.00
Special Nett Rear Sub Total:				110.00	110.00
Total Parts:				13,471.74	13,471.74

5777.05
 13,471.74 - 7,899.70 = 5,572.04

170

Our Reference : TP19-038023-TWL
 Your Reference : -
 Vehicle Number : SGK5725T

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
<u>LABOUR FRONTAL</u>			
1	To remove & dismantle damaged parts to cut and chisel out attachment parts. To knock, straighten out dents where necessary, to weld refix readjust & reshape same. (frontal)	1,200.00	600 1,000.00
2	To respray painting on all affected parts, to supply paint material i.e sand paper, rubbing compound, thinner, paint, lacquer.etc. (frontal)	1,400.00	600 1,200.00
3	To check wirings and lightings. (frontal)	50.00	20 50.00
4	To remove-refit air con condenser, air con pipings/hoses and including vacuum and refill of air con gas.	120.00	60 120.00
5	To remove and install radiator and fan assy including pressure test, bleed cooling system and check for leak.	100.00	40 100.00
6	To supply and apply rust proofing treatment to affected panel. (frontal)	100.00	40 100.00
<u>LABOUR REAR</u>			
7	To remove & dismantle damaged parts to cut and chisel out attachment parts. To knock, straighten out dents where necessary, to weld refix readjust & reshape same. (Rear)	1,600.00	800 1,400.00
8	To respray painting on all affected parts, to supply paint material i.e sand paper, rubbing compound, thinner, paint, lacquer.etc. (Rear)	1,400.00	600 1,200.00
9	To supply and apply rust proofing treatment to affected panel. (rear)	100.00	40 100.00
10	To replace rear exhaust and straighten centre exhaust.	120.00	60 100.00

Our Reference : TP19-038023-TWL

Your Reference : -

Vehicle Number : SGK5725T

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
	<u>LABOUR REAR</u>		
11	To transfer to back door mechanism to new back door.	100.00	60 100.00
12	To check on rear wiring system, lamp socket wire for rear.	60.00	20 60.00
13	To remove and refix rear windscreen	150.00	100 150.00
	Labour Total :	6,500.00	5,680.00
	TOTAL (PARTS & LABOUR) :	19,971.74	19,151.74

Adjustment / Recommendations

Note : (For Lump Sum Repair)

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).

The final adjusted Lump Sum contract amount is S\$15,200.00

Under normal circumstances, the repair period would be about 16 working days.

11 460.48
20% 9100



INVOICE

To: Kom Mum Kiet
C/o T.W.LIM MOTOR WORKS,
10 Anson Road #10-06
International Plaza
Singapore 079903

Invoice No: TP19-0024
Your Ref: SGK5725T
Our Ref: TP19-038023-TWL
Date: 9-Apr-19

Description	Amount S\$
<u>PARTICULARS</u>	
Vehicle Registration No. : SGK5725T	
Date of Accident : 15-Mar-19	
Date of Inspection : 20-Mar-19	
SERVICES :	
Assessment with report (inclusive of transport charges and photographs etc)	\$ 518.00
Singapore Dollars Five Hundred And Eighteen Only	
Total Amount	\$ 518.00

We would appreciate your cheque crossed and made payable to:
CA APPRAISER PTE LTD

CA APPRAISER PTE LTD



VEHICLE APPRAISAL REPORT

Our Reference: **TP19-038023-TWL**
 Your Reference: **-**
 Vehicle Number: **SGK5725T**

Date: 9-Apr-19

To: Kom Mum Kiet
 C/o T.W.LIM MOTOR WORKS,
 10 Anson Road #10-06
 International Plaza
 Singapore 079903

Assessment of Vehicle No: **SGK5725T**
 Date of Accident: **15-Mar-19**
 Date of Inspection: **20-Mar-19**

We have carried out a physical assessment of **SGK5725T** at M/s T.W.LIM Motor Works according to your instruction on **20-Mar-2019** and are pleased to submit our report herewith.

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGK5725T	Make:	DAIHATSU
Reg Year:	2006	Model:	TERIOS 1.5L
Colour:	Yellow	Engine No:	-
Type:	-	Chassis No:	JDAJ200G001002678
Type of Claim:	-	Odometer No:	- km
Market Value:	-	Engine Cap.:	1495 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition : Good	Steering : Serviceable	Engine Modification : NA
Paint work : Good	Handbrake : Serviceable	Pre-accident damage : NA
	Footbrake : Serviceable	

CONDITION OF TYRES

Front Left Size:	Michelin 215/65 R16 20%	Front Right Size:	Michelin 215/65 R16 20%
Rear Left Size:	Michelin 215/65 R16 20%	Rear Right Size:	Michelin 215/65 R16 20%

The above percentages represent the remaining life of the tyre treads

COST OF REPAIRS		Repairer's S\$	Adjuster's S\$	Difference S\$
Parts		13,471.74	13,471.74	0.00
Labour		6,500.00	5,680.00	820.00
Calculated Cost (S\$) :		19,971.74	19,151.74	820.00

Recommended Lump Sum Repair: **S\$15,200.00**
 Estimated Repair Period: **16 days**
 Repair Status:


Page - 1

Surveyed on a "Without Prejudice" basis.

Our Reference: **TP19-038023-TWL**
Your Reference: -
Vehicle Number: **SGK5725T**

DESCRIPTION OF DAMAGE


At the time of inspection, this vehicle sustained damages to the **Front and Rear portion**. Please see attached scheduled details.



SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated **16 working days** are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Ang Guea Kiang
Automotive Appraiser
MSAAA

Disclaimer

Pursuant to your instruction, we have **NOT AUTHORIZED** repair. The assessment was conducted on a "**Without Prejudice**" basis. If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **CA APPRAISER PTE LTD** for any reliance on this report by any third party.

Our Reference : TP19-038023-TWL

Your Reference : -

Vehicle Number : SGK5725T

S/N	QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
		<u>PARTS FRONTAL (LIST ITEMS)</u>			
1	1	FRONT BUMPER FASCIA	TORN	798.00	798.00
2	1SET	FRONT BUMPER CLIP	NECESSARY	50.00	50.00
3	1	FRONT BUMPER TOW COVER	MISSING	66.20	66.20
4	1	FRONT BUMPER REINFORCEMENT	BENT	397.10	397.10
5	1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	42.50	42.50
6	1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	42.50	42.50
7	1	HEAD LAMP ASSY LH	CRACKED	898.45	898.45
8	1	HEAD LAMP ASSY RH	CRACKED	898.45	898.45
9	1	FRONT SUPPORT PANEL ASSY	BENT	683.00	683.00
10	1	FRONT BRACE PANEL	BENT	104.25	104.25
11	1	FRT SUPPORT PANEL TOP BRACKET	BENT	52.30	52.30
12	1	AIR CON CONDENSER	DENTED	640.80	640.80
13	1	RADIATOR ASSY	DENTED	752.30	752.30
14	2	RADIATOR AIR GUIDE	CUT/DEFORMED	172.20	172.20
15	1	BONNET	BUCKLED	699.45	699.45
16	1	BONNET LOCK	BENT	100.40	100.40
17	1	BONNET HINGE LH	BENT	65.30	65.30
18	1	BONNET HINGE RH	BENT	65.30	65.30
19	1	FRONT GRILLE	CUT	404.25	404.25
20	1	FRONT GRILLE EMBLEM	NECESSARY	48.50	48.50
21	1	FRONT FENDER LH	REPAIR	-	-
22	1	FRONT FENDER RH	BUCKLED	688.15	688.15
				7,669.40	7,669.40
				less 15%	15%
				1,150.41	1,150.41
Parts Frontal sub Total :				6,518.99	6,518.99

Our Reference : TP19-038023-TWL

Your Reference : -

Vehicle Number : SGK5725T

S/N	QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
		<u>PARTS REAR (LIST ITEMS)</u>			
23	1	BACK DOOR	BUCKLED	1,400.80	1,400.80
24	1	BACK DOOR HINGE UPPER	BENT	78.50	78.50
25	1	BACK DOOR HINGE LOWER	BENT	78.50	78.50
26	1	BACK DOOR WEATHERSTRIP	DEFORMED	229.00	229.00
27	1	BACK DOOR LOCK	BENT	309.10	309.10
28	1	REAR WINDSCREEN MOULDING	NECESSARY	79.00	79.00
29	1	REAR WINDSCREEN DAM	NECESSARY	80.00	80.00
30	1	BACK DOOR EMBLEM 'LOGO'	NECESSARY	45.00	45.00
31	1	BACK DOOR EMBLEM 'TERIOS'	NECESSARY	35.00	35.00
32	1	BACK DOOR STICKER 'DAIHATSU'	NECESSARY	30.00	30.00
33	1	REAR WIPER MOTOR	BENT	509.00	509.00
34	1	SPARE WHEEL HOLDER BRACKET	BENT	440.00	440.00
35	1	REAR BUMPER FASCIA	TORN	609.00	609.00
36	1SET	REAR BUMPER CLIP	NECESSARY	50.00	50.00
37	1	REAR BUMPER SIDE RETAINER LH	CRACKED	48.60	48.60
38	1	REAR BUMPER SIDE RETAINER RH	DISTORTED	48.60	48.60
39	1	REAR BUMPER REFLECTOR LH	CRACKED	66.25	66.25
40	1	REAR BUMPRE REFLECTOR RH	CRACKED	66.25	66.25
41	1	REAR BUMPER TOW COVER	MISSING	51.20	51.20
42	1	REAR END PANEL	BUCKLED	480.20	480.20
43	1	REAR END PANEL TOP GARNISH	DEFORMED	108.50	108.50
44	1SET	RR END PANEL TOP GARNISH CLIP	NECESSARY	20.00	20.00
45	1	REAR FLOOR PANEL	BUCKLED	470.00	470.00
46	1	REAR FLOOR PANEL INSULATOR PAD	NECESSARY	300.00	300.00
47	1	TAILLAMP LH	CRACKED	528.55	528.55
48	1	TAIL LAMP RH	CRACKED	528.55	528.55

Our Reference : TP19-038023-TWL

Your Reference : -

Vehicle Number : SGK5725T

S/N	QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
<u>PARTS REAR (LIST ITEMS)</u>					
49	1	REAR FENDER LH	REPAIR	-	-
50	1	REAR FENDER INNER TRIM LH	DEFORMED	780.10	780.10
51	1	REAR FENDER RH	REPAIR	-	-
52	1	REAR EXHAUST SILENCER	BENT	430.00	430.00
				7,899.70	7,899.70
				less 15% 1,184.96	15% 1,184.96
Parts Rear sub Total :				6,714.75	6,714.75
<u>SPECIAL NETT ITEMS (FRONTAL)</u>					
53	1	FRONT NUMBER PLATE	DENTED	50.00	50.00
54	1	RADIATOR COOLANT	NECESSARY	78.00	78.00
Special Nett Frontal Sub Total:				128.00	128.00
<u>SPECIAL NETT ITEMS (REAR)</u>					
55	1	REAR NUMBER PLATE	DENTED	50.00	50.00
56	1	REAR WINDSCREEN SEALANT	NECESSARY	60.00	60.00
Special Nett Rear Sub Total:				110.00	110.00
Total Parts:				13,471.74	13,471.74

Our Reference : **TP19-038023-TWL**
 Your Reference : -
 Vehicle Number : **SGK5725T**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
<u>LABOUR FRONTAL</u>			
1	To remove & dismantle damaged parts to cut and chisel out attachment parts. To knock, straighten out dents where necessary, to weld refix readjust & reshape same. (frontal)	1,200.00	1,000.00
2	To respray painting on all affected parts, to supply paint material i.e sand paper, rubbing compound, thinner, paint, lacquer.etc. (frontal)	1,400.00	1,200.00
3	To check wirings and lightings. (frontal)	50.00	50.00
4	To remove-refit air con condenser, air con pipings/hoses and including vacuum and refill of air con gas.	120.00	120.00
5	To remove and install radiator and fan assy including pressure test, bleed cooling system and check for leak.	100.00	100.00
6	To supply and apply rust proofing treatment to affected panel. (frontal)	100.00	100.00
<u>LABOUR REAR</u>			
7	To remove & dismantle damaged parts to cut and chisel out attachment parts. To knock, straighten out dents where necessary, to weld refix readjust & reshape same. (Rear)	1,600.00	1,400.00
8	To respray painting on all affected parts, to supply paint material i.e sand paper, rubbing compound, thinner, paint, lacquer.etc. (Rear)	1,400.00	1,200.00
9	To supply and apply rust proofing treatment to affected panel. (rear)	100.00	100.00
10	To replace rear exhaust and straighten centre exhaust.	120.00	100.00

Our Reference : **TP19-038023-TWL**

Your Reference : -

Vehicle Number : **SGK5725T**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT(S\$)
	<u>LABOUR REAR</u>		
11	To transfer to back door mechanism to new back door.	100.00	100.00
12	To check on rear wiring system, lamp socket wire for rear.	60.00	60.00
13	To remove and refix rear windscreen	150.00	150.00
	Labour Total :	6,500.00	5,680.00
	TOTAL (PARTS & LABOUR) :	19,971.74	19,151.74

Adjustment / Recommendations

Note : (For Lump Sum Repair)

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).

The final adjusted Lump Sum contract amount is **S\$15,200.00**

Under normal circumstances, the repair period would be about **16** working days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2019		19 Mar 2019 18:20 Edit Adj Rpt	S\$9,100.00 Edit Estimates	S\$9,100.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KOEN PETER RENE CARDON, ID: S2718831A		
Main Claimant:	KOM MUM KIET, ID: S6832907H		
Vehicle Reg. No.:	SGK5725T	Date of Loss:	15/03/2019 08:00 - :59 [150 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 587902	Policy/Cover Note No.:	28629631 (Comprehensive) Coverage: 07/07/2018 - 06/07/2019
Vehicle Reg. No. (Insured):	SKK8773L	Policy No. (Claimant):	
		Excess:	
Repairer:	T.w. Lim Motors Works (HQ) 160 Sin Ming Drive, #08-12 Sin Ming Autocity, 575722 Sin Ming - Tel: 97409067		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/06/2019]		
Driver/Custodian (Insured):	JAMIYANPERJLEE MUNKHBAYAR (), NRIC: S7160171D, Tel: +6597848280 Email:		
Adj Asg. Remarks:	Liability down. Contact Person: Lim Tau Wing / 9740 9067. On WP. Please let us know if can't attend. tks.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (21/06/2019): Report Send Back Alerts - SGK5725T (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)


Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






















Claim Documents
















































***SGK5725T (587902)**
[SKK8773L]
TP
KOM MUM KIET
Mar 15 2019 8:00AM
[KOEN PETER RENE CARDON]
T.w. Lim Motors Works






































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/03/19 14:31	Accident Statement From: SC - Reg. No: SKK8773L, Claimant: KOEN PETER RENE CARDON	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
34	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
35	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
38	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/03/19 15:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	25/03/19 15:26	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/03/19 15:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	25/03/19 15:26	General View	 Load JPG	<input checked="" type="checkbox"/>
43	25/03/19 15:26	General View	 Load JPG	<input checked="" type="checkbox"/>
44	25/03/19 15:26	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/03/19 15:26	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/03/19 15:26	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/03/19 15:26	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	26/04/19 17:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	26/04/19 17:02	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	26/04/19 17:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/03/19 14:33	SGK5725T GIA Rpt	 Load PDF	
2	19/03/19 14:34	SLT7432T GIA Rpt	 Load PDF	
3	19/03/19 14:34	SHC4705M GIA Rpt	 Load PDF	
4	19/03/19 14:36	PRI - Oracle Law	 Load PDF	
5	21/06/19 17:48	survey report	 Load PDF	
6	24/06/19 10:50	Survey Report with photos	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/07/19 10:37	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19005008/GSD3S2-1
Date: 03/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28629631

Claimant Vehicle No: SGK5725T

Insured Vehicle No: SKK8773L

Date of Loss: 15/03/2019

Nature of Claim: TP Claim No: 587902

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGK5725T**
Make & Model: DAIHATSU TERIOS, 1.5 2WD (M)
Reg. Date: 17/08/2006 (Man. Year: 2006)
Colour: Yellow
Engine Capacity: 1495 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1658313
Chassis No: JDAJ200G001002678
Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65R16 Rear Tyre Size: 215/65R16
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,471.73	8,368.04	5,103.69	37.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,500.00	3,040.00	3,460.00	53.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,971.73	11,408.04	8,563.69	42.88
Approved Total (Overridden) (S\$)		9,100.00		
Nett Amount (S\$)	19,971.73	9,100.00	10,871.73	54.44

INSPECTION

Date of Assignment: 19/03/2019

Date Inspected: 20/03/2019

Estimated Period of Repair: 9.0 days

Inspected At:

160 SIN MING DRIVE #08-12
Repairer: T.W. Lim Motors Works

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jul 2019)

Parts: M1-SUV DAIHATSU TERIOS 1.5 2WD (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGK5725T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Torn	798.00 FL	*560.00 FL
2	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
3	1		*FRONT BUMPER TOW COVER	Missing	66.20 FL	*66.20 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	397.10 FL	*397.10 FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	42.50 FL	*42.50 FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	42.50 FL	*42.50 FL
7	1		*HEAD LAMP ASSY LH	Cracked	898.45 FL	*665.00 FL
8	1		*HEAD LAMP ASSY RH	Cracked	898.45 FL	*665.00 FL
9	1		*FRONT SUPPORT PANEL ASSY	Repair	683.00 FL	*- FL
10	1		*FRONT BRACE PANEL	Bent	104.25 FL	*104.25 FL
11	1		*FRT SUPPORT PANEL TOP BRACKET	Bent	52.30 FL	*52.30 FL
12	1		*AIR CON CONDENSER	Not Necessary	640.80 FL	*- FL
13	1		*RADIATOR ASSY	Not Necessary	752.30 FL	*- FL
14	2		*RADIATOR AIR GUIDE	Cut / Deformed	172.20 FL	*172.20 FL
15	1		*BONNET	Buckled	699.45 FL	*699.45 FL
16	1		*BONNET LOCK	Bent	100.40 FL	*100.40 FL
17	1		*BONNET HINGE LH	Repair	65.30 FL	*- FL
18	1		*BONNET HINGE RH	Repair	65.30 FL	*- FL
19	1		*FRONT GRILLE	Cut	404.25 FL	*264.00 FL
20	1		*FRONT GRILLE EMBLEM	Necessary	48.50 FL	*48.50 FL
21	1		*FRONT FENDER LH (NPA)	Repair	0.00 FL	*- FL
22	1		*FRONT FENDER RH	Repair	688.15 FL	*- FL
23	1		*BACK DOOR	Buckled	1,400.80 FL	*1,400.80 FL
24	1		*BACK DOOR HINGE UPPER	Repair	78.50 FL	*- FL
25	1		*BACK DOOR HINGE LOWER	Repair	78.50 FL	*- FL
26	1		*BACK DOOR WEATHERSTRIP	Deformed	229.00 FL	*229.00 FL
27	1		*BACK DOOR LOCK	Bent	309.10 FL	*309.10 FL
28	1		*REAR WINDSCREEN MOULDING	Necessary	79.00 FL	*79.00 FL
29	1		*REAR WINDSCREEN DAM	Necessary	80.00 FL	*80.00 FL
30	1		*BACK DOOR EMBLEM LOGO	Necessary	45.00 FL	*45.00 FL
31	1		*BACK DOOR EMBLEM TERIOS	Necessary	35.00 FL	*35.00 FL
32	1		*BACK DOOR STICKER DAIHATSU	Necessary	30.00 FL	*30.00 FL
33	1		*REAR WIPER MOTOR	Not Necessary	509.00 FL	*- FL
34	1		*SPARE WHEEL HOLDER BRACKET	Not Necessary	440.00 FL	*- FL
35	1		*REAR BUMPER FASCIA	Torn	609.00 FL	*609.00 FL
36	1		*SET REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
37	1		*REAR BUMPER SIDE RETAINER LH	Cracked	48.60 FL	*48.60 FL
38	1		*REAR BUMPER SIDE RETAINER RH	Distorted	48.60 FL	*48.60 FL
39	1		*REAR BUMPER REFLECTOR LH	Cracked	66.25 FL	*66.25 FL
40	1		*REAR BUMPER REFLECTOR RH	Not Necessary	66.25 FL	*- FL
41	1		*REAR BUMPER TOW COVER	Missing	51.20 FL	*36.20 FL
42	1		*REAR END PANEL	Buckled	480.20 FL	*480.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR END PANEL TOP GARNISH	Deformed	108.50 FL	*108.50 FL
44	1		*SET RR END PANEL TOP GARNISH CLIP	Necessary	20.00 FL	*20.00 FL
45	1		*REAR FLOOR PANEL	Repair	470.00 FL	*- FL
46	1		*REAR FLOOR PANEL INSULATOR PAD	Necessary	300.00 FL	*200.00 FL
47	1		*TAILLAMP LH	Cracked	528.55 FL	*315.00 FL
48	1		*TAILLAMP RH	Cracked	528.55 FL	*315.00 FL
49	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
50	1		*REAR FENDER INNER TRIM LH	Deformed	780.10 FL	*780.10 FL
51	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
52	1		*REAR EXHAUST SILENCER	Bent	430.00 FL	*430.00 FL
53	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*40.00 FS
54	1		*RADIATOR COOLANT	Necessary	78.00 FS	*40.00 FS
55	1		*REAR NUMBER PLATE	Dented	50.00 FS	*40.00 FS
56	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,807.10	9,814.75
- List Item Discount on L Items 15.00/15.00% (\$\$)	2,335.37	1,446.71
Total Parts (\$\$)	13,471.73	8,368.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & DISMANTLE DAMAGED PARTS TO CUT AND CHISEL OUT ATTACHMENT PARTS. TO KNOCK, STRAIGHTEN OUT DENTS WHERE NECESSARY, TO WELD REFIX READJUST & RESHAPE SAME. (FRONTAL)	New	1,200.00	600.00
2	TO RESPRAY PAINTING ALL AFFECTED PARTS, TO SUPPLY PAINT MATERIAL I.E SAND PAPER, RUBBING COMPOUND, THINNER, PAINT, LACQUER. ETC. (FRONTAL)	New	1,400.00	600.00
3	TO CHECK WIRINGS AND LIGHTINGS. (FRONTAL)	New	50.00	20.00
4	TO REMOVE-REFIT AIR CON CONDENSER, AIR CON PIPINGS / HOSES AND INCLUDING VACUUM AND REFILL OF AIR CON GAS.	New	120.00	60.00
5	TO REMOVE AND INSTALL RADIATOR AND FAN ASSY INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM AND CHECK FOR LEAK.	New	100.00	40.00
6	TO SUPPLY AND APPLY RUST PROOFING TREATMENT TO AFFECTED PANEL. (FRONTAL)	New	100.00	40.00
7	TO REMOVE & DISMANTLE DAMAGED PARTS TO CUT AND CHISEL OUT ATTACHMENT PARTS. TO KNOCK, STRAIGHTEN OUT DENTS WHERE NECESSARY, TO WELD REFIX READJUST & RESHAPE SAME. (REAR)	New	1,600.00	800.00
8	TO RESPRAY PAINTING ON ALL AFFECTED PARTS, TO SUPPLY PAINT MATERIAL I.E SAND PAPER, RUBBING COMPOUND, THINNER, PAINT, LACQUER. ETC. (REAR)	New	1,400.00	600.00
9	TO SUPPLY AND APPLY RUST PROOFING TREATMENT TO AFFECTED PANEL. (REAR)	New	100.00	40.00
10	TO REPLACE REAR EXHAUST AND STRAIGHTEN CENTRE EXHAUST.	New	120.00	60.00
11	TO TRANSFER TO BACK DOOR MECHANISM TO NEW BACK DOOR.	New	100.00	60.00
12	TO CHECK ON REAR WIRING SYSTEM. LAMP SOCKET WIRE FOR REAR.	New	60.00	20.00
13	TO REMOVE AND REFIX REAR WINDSCREEN.	New	150.00	100.00
Gross Labour Cost (\$\$)			6,500.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >