



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2011 PEUGEOT 5008 1.6 TURBO (SKN1716H)

Date of Loss

21 June 2019

Time of Loss

11.10

Loss Description

SKN1716H (INSD) C/W SHA1158Y (TP)

Comment

Workshop Details

Total Rebate Amount

29718

Nett Loss Amount

\$4,282.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion *

20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details


Vehicle Registration#	SKN1716H	Purchase Date	<input type="text" value="dd/mm/yyyy"/>
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="15/02/2012"/>
Mileage	<input type="text" value="144331"/>	Age of Vehicle	7

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2011	<input type="text" value="2011"/>
Make	PEUGEOT	<input type="text" value="PEUGEOT"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	TAN TUAN ENG (CHEN DUANRONG)	<input type="text"/>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Model	5008 1.6 TURBO	5008 1.6 TURB
Type		
Type of Paint		
Chassis No	VF30E5FVABS335312	VF30E5FVABS
Engine No	10FJBW1373872	10FJBW13738
Engine Capacity		1598
Sum Insured	0	0
Market Value	0	34000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	10 February 1971	dd/mm/yy
Age	48	
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	18	
Driver License #		
License Type		
License Issue Date		dd/mm/yy

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<div>dd/mm/yy</div>
Address	23 CANBERRA DRIVE, #01-47, 768077, Singapore	<div></div>
Address type	Residential	<div>▼</div>
Gender	Male	<div>▼</div>
Marital status	Married	<div>▼</div>
Identification #	S7134659E	<div></div>



Assessment Details

Detailed Assessment

Inspection Date *

24/06/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/
Unnamed Driver
Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Age of Tyres

Front Tyre Size

205/55R16

Front left side

BLACKLION8mm

Front right side

BLACKLION8mm

Spare wheel

Rear Tyre Size

205/55R16

Rear left side

BLACKLION8mm

Rear right side

BLACKLION8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour



















Miscellaneous





















Summary



















Parts





















Add Approve Deny Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRONT UPPER BUMPER (WCP) (10%)	Buckled	0	583	No					583	Reviewing
		0	1		FRONT LOWER BUMPER (WCP) (10%)	Cracked	0	253	No					253	Reviewing
		0	1		L/F BUMPER COVER (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		R/F BUMPER COVER (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		FR LWR BUMPER GRILLE (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		FRT BUMPER GRILLE (WCP) (10%)	Cracked	0	165	No					165	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FR UPP BUMPER GRILLE (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		L/F BUMPER MOULDING (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		R/F BUMPER MOULDING (WCP) (10%)	Necessary	0	121	No					121	Reviewing
		0	1		C-MEMBER FRONT PART (WCP) (10%)	Repair	0	0	No					0	Deny
		0	1		FRONT BUMPER DAMPER (WCP) (10%)	Dented	0	93.5	No					93.5	Reviewing
		0	1		SET FT IMPACT DAMPER (WCP) (10%)	Dented	0	88	No					88	Reviewing
		0	1		FRT UPP BUMPER CARR (WCP) (10%)	Cracked	0	165	No					165	Reviewing
		0	1		FRONT LOWER CARRIER (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		FRT LWR AIR DEFLECT (WCP) (10%)	Dented	0	99	No					99	Reviewing













	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		BONNET (WCP) (10%)	Repair	0	0	No					0	Deny
		0	1		L/BONNET HINGE (WCP) (10%)	Repair	0	0	No					0	Deny
		0	1		R/BONNET HINGE (WCP) (10%)	Repair	0	0	No					0	Deny
		0	1		BONNET INSULATION (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		BONNET LOCK (WCP) (10%)	Damaged	0	49.5	No					49.5	Reviewing
		0	1		LEFT HEADLAMP ASSY (WCP) (10%)	Cracked	0	396	No					396	Reviewing
		0	1		RIGHT HEADLAMP ASSY (WCP) (10%)	Cracked	0	396	No					396	Reviewing
		0	1		L/F FOG LAMP (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		R/F FOG LAMP (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		R/F WING (WCP) (10%)	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		R/F WHEELHOUSE COVER (WCP) (10%)	Cracked	0	88	No					88	Reviewing
		0	1		FRONT PART (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		WASHER RESERVOIR (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		AIR CON CONDENSER (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		L/RADIATOR AIR GUIDE (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		R/RADIATOR AIR GUIDE (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		RADIATOR (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		FRT AIR GRILLE (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		LWR RADIATOR HOSE (WCP) (10%)	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		UPPER RADIATOR HOSE (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		ELECTRIC FAN (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		INTERCOOLER (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	10		INSULATOR CLIPS (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	6		FRT GRILLE CLIPS (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	2		SIDE RETAINERS (WCP) (10%)	Damaged	0	27.5	No					55	Reviewing
		0	15		BUMP CLIPS (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		BUMP TOW COVER RH (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	8		FEND COWL CLIP (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		FRONT SUPPORT TOP GARNISH (WCP) (10%)	Cracked	0	55	No					55	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
			0	1	FRONT FENDER SHIELD LH (WCP) (10%)	Cracked	0	88	No					88	Reviewing

Labour

Add	Approve	Deny	Submit All							
	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		AIR CON GAS	0	50	0	0	Reviewing	
		0		CHECK WIRING	0	20	0	0	Reviewing	
		0		RESET & DIAGNOSTIC	0	0	0	0	Deny	
		0		177.0 WU X 45.00 SGD/H	0	360	0	0	Reviewing	
		0		LABOUR COST 125.0 WU X 45.00 SGD/H	0	490.5	0	0	Reviewing	
		0		MATERIAL COST	0	269.88	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 5 DAYS	Reviewing		0	
<input type="checkbox"/>		0	NUMBER PLATE	Reviewing		35	BENT
<input type="checkbox"/>		0	RADIATOR COOLANT	Reviewing		20	NECESSARY



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$3,540.38

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$2,695.00
Labour	\$0.00	\$1,190.38
Miscellaneous	\$0.00	\$55.00
Excess		-\$400.00

Submit for Review