COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHA 3398H

MAKE :

DATE: 21.06.2019

: TOYOTA PRIUS PARTS DESCRIPTION	QTY	UNIT PRICE	AM	OUNT
REAR TRUNK LID LOGO(PRIUS) × 47			\$	52.90
REAR TRUNK LID LOGO(HYBRID) * 1			\$	52.90
REAR TRUNK LID LOGO(TOYOTA STAR) > 4			\$	47.00
REAR BUMPER Advant			\$	458.60
REAR BUMPER RE-INFORCEMENT &			\$	318.80
REAR BUMPER UNDER COVER			\$	552.60
REAR BUMPER SIDE RETAINER, RH			s	112.70
REAR BUMPER UNDER SIDE COVER (RH)			\$	232.00
REAR BUMPER TOWING COVER — 4			\$	82.70
REAR BUMPER CLIPS			\$	22.00
			\$	557.90
TAIL LAMP ASSY (UPPER) (RH)			\$	548.40
TAIL LAMP ASSY (LOWER) (RH)			S	836.70
REAR FENDER, RH			\$	134.20
REAR FENDER SHEILD (RH) ×			\$	165.10
REAR FENDER AIR DUCT			2	103.10
			6	4 174 5
SUB TOTAL			\$	4,174.50
LESS 20%		/	\$	834.90
DISCOUNTED TOTAL			5/	3,339.60
	-	notify		\
	/	France Rolling Charles Polyphing Leginery Charles Polyphing Leginery Charles Documentation Charles Documentati	16	/
	Julian	110, 00, 100	rce pasis	\
REAR TRUNK LID APPS STICKER X ~	Auto Consultan	ther styles durinfirmati Prei	S dand	108MY 40.00
REAR TRUNK LID COMFORT & TEL NO. STCIKER	Ante Bire, pelor	and part to a withoused	Marca Co	60.00
REAR BUMPER REVERSE SENSOR - 8000	TO resure play dans	are sur is on sile and the re	IRSUM.	135.7
REAR WINDSCREEN SEALANT X	· To dist price	3 - Uli alle alle	\$	46,0
	Third Hee	COLONIUS PAINTE BE UNE PROPERTY OF THE PROPERT		
	Subi	spied to ded by Repu	\$	281.7
4		1000		
LABOUR CHARGE Panel Beating Ca In 10thy 2/6/19				
LABOUR CHARGE)	Date:		400
Panel Beating 2/6/19	15184		\$	850.0
Spray Painting Charge			\$	750.0
Wiring Charge 2 %.			\$	590
Tuff Kote Remove/Refix Cushion & Upholstery Rear Remove/Refix Reverse Sensor			\$	50,0
Remove/Refix Cushion & Upholstery Rear	124 0/1		\$	1500
Remove/Refix Reverse Sensor	Pu		\$	80.0
Diagnosis & Resetting To Erase Fault Code			\$	4800
Town 5			4	60,
TOTAL LABOUR	2		\$	2,410.0
ESTIMATE TOTAL			\$	6,031.3
	5.			



member of COMFORTDELGRO





JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition 1. Date: 2 (94) 217 Time Received:	THE PROPERTY OF THE PARTY OF TH				
Date: 2 / A / / Time Received:	a value Turn	1.	Type of Towing:		
2. New SPARK Kakis Name of Customer : Mr Can Contact No. : 9(88 K.) 5	Taxi (CTPL/	CCPL)	Normal Tow King Dolly Flat Bed Crane-up		
Vehicle No. : SHA 3398H Make/Model/Colour: Prins. Email :	5. Nature of Servic Jumpstart Recovery Change Tyn		6. Parts Replaced/Remarks:		
7. Location: Block C84 Holescy A. 9. Preferred Workshop: Braddell Loyang Sin Ming Sungei Kadut Senoko Komoco (UBI / Leng Others:	Pandan Ubi Cycle & Carriage (P	8. Vehicle Tow - I Smoky Ex Overheati Brake Fau Starting P Accident Return Ta	chaust Wheel Jammed ng Steering Faulty ulty Alternator Faulty Problem Loss Power Engine Stalled		
	1/2 3/4 E	O / CD Player OK Faulty Not tested	PEON!		
Job Attended			THE STATE OF THE S		
12. Tow Truck / Recovery Van : VRS Name of Driver : Vehicle No. : Time Dispatch : Time of Arrival : Time Completed :	YN370 1 0430.		#: Cracked X: Dented /: Scatched O: Missin X Signature of Customer		
Cash Invoice Details (if applicable)					
13. Cash Invoice No. :					
Customer Acknowledgement					
a. I have been advised to remove all valuable items in cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my oc. Surcharge: Towing fee will be levied if the custome	own risk and SPARK Car Care™ will not be	held liable for such losses the repairs in SPARK Car	s.		
			Attending Staff/Guard		