

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9715U

DATE 21/6/2019

MAKE :

MODEL : HYUNDAI IONIQ G2

LKK-Kalvin

15

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>x repair</i>			\$ 459.40
	Rear Bumper Centre Moulding Assy <i>—</i>			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy <i>x</i>			\$ 47.50
	Rear Bumper Stay <i>x</i>			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) <i>x</i>		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips <i>x</i>			\$ 22.00
	SUB TOTAL			\$ 1,184.45
	LESS 20%			\$ 236.89
	DISCOUNTED TOTAL			\$ 947.56
	Rear No.Plane <i>—</i>			\$ 25.00
	Rear Bumper Rubber Mat <i>x</i>			\$ 50.00
	Reverse Sensor <i>x</i>			\$ 75.00
				<i>135.70</i>
				<i>Nett</i>
				<i>Nett</i>
				<i>Nett</i>
	Labour Charge			<i>200</i>
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>x</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>x</i>
	TOTAL LABOUR			\$ 870.00
	ESTIMATE TOTAL			\$ 1,892.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin LKK
21/6/19 1125L
2 hrs
PIP
After Repair LK

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.