

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19011128/UGA3Q2

**Date:** 27/04/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SJT8650Y	<b>Insured Vehicle No :</b>	SHB6234Y
Date of Loss: 06/06/2019	Nature of Claim: TP	Claim No: MCT19060291

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT8650Y	Engine No:	L15A71002035
Make & Model:	HONDA JAZZ, 1.5 (A)	Chassis No:	JHMGE88509S201677
Reg. Date:	04/11/2009 (Man. Year: 2008)	Odometer:	156957 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,849.36	385.52	1,463.84	79.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	450.00	1,250.00	73.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,549.36</b>	<b>835.52</b>	<b>2,713.84</b>	<b>76.46</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>600.00</b>		
<b>Nett Amount (\$\$)</b>	<b>3,549.36</b>	<b>600.00</b>	<b>2,949.36</b>	<b>83.10</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (\$\$)</b>		300.00		
<b>Nett Liability (\$\$)</b>		<b>900.00</b>		

### INSPECTION

Date of Assignment:	25/06/2019	
Date Inspected:	25/06/2019	Inspected At:
		VAC Auto Centre Pte Ltd (HQ)
		1 Kaki Bukit Ave 6 #02-11
		Singapore 417883
Estimated Period of Repair:	2.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2020)
<b>Parts:</b>	144	HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJT8650Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	841.60 FL	*- FL
2	1		*FRONT DOOR MIRROR ASSEMBLY RH	Cracked	481.90 FL	*481.90 FL
3	1		*FRONT FENDER RH	Repair	426.30 FL	*- FL
4	1		*FRONT HEALAMP RH	Not Necessary	561.90 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,311.70</b>	<b>481.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	462.34	96.38
<b>Total Parts (\$\$)</b>	<b>1,849.36</b>	<b>385.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL WIRING SYSTEMS	New	40.00	0.00
2	TO SPRAY UNDERCOATING	New	60.00	0.00
3	TO RESPRAY PAINTING & ETC	New	800.00	300.00
4	PANEL BEATING ,CUT ,WELD ,REMOVE AND REPLACING ABOVE PARTS	New	800.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,700.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >