



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003224
INV Date 16/04/2020
Reference CC6/CTI19011132/Aea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. GBC 2354B
Insured Veh. GBJ 2657R
Claim No. SNM19D202679
Policy No. DMCVSN3021291900
Accident Date 01/06/2019
Inspection Date 21/06/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19011132/Aea3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 16-04-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 2657R	Veh. Inspected	GBC 2354B	
Policy No.	DMCVSN3021291900	Coverage (\$)	0.00	
Claim No.	SNM19D202679	Excess (\$)	0.00	
Assign From		Assign Date	21/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN CADDY	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WV1ZZZ2KZCX011623	Colour	WHITE	
Odometer	120168	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODRICH	6 mm	
L/H Front Tyre	195/65 R15	GOODRICH	6 mm	
R/H Rear Tyre	195/65 R15	GOODRICH	6 mm	
L/H Rear Tyre	195/65 R15	GOODRICH	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2019	Inspection Date	21/06/2019	
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 2354B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	DENTED	1,689.00	1,330.00
1	BONNET LOCK	NOT NECESSARY	168.00	-
1	FRONT BUMPER	DEFORMED	1,201.00	880.00
2	FRONT BUMPER SIDE RETAINER @\$54.00	NECESSARY	108.00	108.00
1	FRONT BUMPER LOWER SIDE GRILLE	NOT NECESSARY	197.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	498.00	-
1	HORN	NOT NECESSARY	74.00	-
1	HEADLAMP RH	CRACKED	864.00	695.00
1	FRONT LOGO	NECESSARY	194.00	95.00
1	FRONT WIPER GARNISH SUPPORT RUBBER	NOT NECESSARY	58.00	-
1	FRONT SUPPORT PANEL	CRACKED	884.00	884.00
1	FRONT FENDER RH	NOT NECESSARY	845.00	-
1	FRONT FENDER INNER COWLING	NOT NECESSARY	154.00	-
1	FRONT BUMPER SPONGE	CRACKED	217.00	217.00
	LESS 5% DISCOUNT		-357.55	-
	LESS 10% DISCOUNT		-	-420.90
			6,793.45	3,788.10
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
10	FRONT BUMPER CLIPS @\$6.50 (SN)	NECESSARY	65.00	30.00
1	BONNET SEALANT (SN)	NOT NECESSARY	80.00	-
12	BONNET INSULATOR CLIP @\$6.50 (SN)	NOT NECESSARY	78.00	-
4	BONNET STOPPER @\$12.00 (SN)	NOT NECESSARY	48.00	-
9	FRONT FENDER INNER COWLING CLIP @\$6.50 (SN)	NOT NECESSARY	58.50	-
1	RADIATOR COOLANT (SN)	NECESSARY	60.00	40.00
			439.50	70.00
<u>LABOUR</u>				
	PANEL BEATING ,REMOVING AND REPLACING PARTS.		1,000.00	600.00
	SPRAY PAINTING TO AFFECTED AREA.		800.00	400.00
	TUFF COAT.	NOT NECESSARY	150.00	-

Report Ref No. CC6/CTI19011132/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHECK .		80.00	30.00
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS.		120.00	60.00
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.		80.00	60.00
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	80.00	-
	RESET ENGINE LIGHT .	NOT NECESSARY	350.00	-
			2,660.00	1,150.00
GRAND TOTAL			9,892.95	5,008.10

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00
---	--	--	--	-----------------

Report Ref No. CC6/CTI19011132/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.