

ASS. REC. BY:

REF: CS/CTI 19011149/R19d3n2

Special Instruction:

Surveyor:

Rusu

ASSIGNMENT (Office)

From (Person):

Tantun Leong

of

CTZ

Date/Time:

25.6.19 9.52

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 9032J

Insured:

XD 3015H

at Workshop m/s

sin sheng

Tel:

68639595

of

3 Tech Part Crescent

Policy No:

DMCRSA 14325718044

Claim No:

SNM19070 2927102

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22.6.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

25.6.19 11.36A.M

Person Contacted:

Susan

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	XD 3015H ✓
	GY 9032J : CCH/ASM18005331/TIR392
	US \$1800, 5 days (Red \$12665.13, 88%)


Ref: *Rahul*

REF: CTI

EXP: 2020/SEP 11/96N

ASSIGNMENT

From: *15.7.2019*
 Date: *15.7.2019*
 Estimate / Cost: *0*
 OD: *TP / WS / TP RES / OD RES / EVA / INV / MV*
 To Inspect Vehicle No: *64 90323*
 at Workshop n/s: *Sin Sheng Engineering*
 of: *3 Tech Park Crescent Tuas Tech Park*
 Insured:
 Policy No:
 Claims No:
 Sum Insured:
 Excess:
 (Client's Record)
 Make of Veh:



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *\$1,500*
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: *5* days Res.: Yes or No
 Lum Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS *"wup"*

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: *64 90323* Yr Reg: *2005 / 800*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: *MITSUBISHI FB 511* C.C: *2835*
 Colour: *RED* A/C: Insured / Std / NI / NA
 Sp. Reading: *611899* T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: *FB 511 BA 47864*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: *Nil* / S/Rim / STD A/Rim or
 Tyre Size: F: *195R15C*
 R: *185R13*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Ausone*

Front	Rear
R/Bal. <i>7</i> mm	R/Bal. <i>5/5</i> mm
L/Bal. <i>7</i> mm	L/Bal. <i>5/5</i> mm
D.O.A. <i>22/06/19</i>	D.O.I. <i>15/07/19</i>
Survey held at <i>SIN SHENG</i>	
Des. of Damages: <i>Front / Rear / O/S / N/S / U/C / Rooftop</i> or	

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rahul

Have you advise repairer repair limit?

RECEIVED 07 AUG 2019

[Signature]

19/7

Date/Time, File Pass to? ☐ : Preli. Report

1) *07/8/19* ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: *MER-TP*

Lump Sum / I.B.A. (\$ *1800*)

Survey Fee:

Transportation:

☐ S + RS, ☐ G

☐ Photos

☐ Others:

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jun 2019		25 Jun 2019 09:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS		[Created by insurer]		
Insured:				
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N			
Vehicle Reg. No.:	GY9032J	Date of Loss:	22/06/2019 15:00 - :59	
Claim Type:	TP / SNM19D202927C02	Policy/Cover Note No.:	DMCVSN14325718044	
Vehicle Reg. No. (Insured):	XD3015H	Policy No. (Claimant):	29090793	
		Excess:	S\$1,500.00	
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]			
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/07/2019]			
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail		
There are no mail for this case.				
ALL ASSOCIATED TASKS				
		View All	Search Tasks	Create New Task Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, 25 June 2019 9:40 AM
To: sinsheng engineering services; assignments@lkkauto.com
Subject: RE: SNM19D202927/TANKL - Accident Involving GY9032J with XD3015H on 22/06/2019

WITHOUT PREJUDICE

Dear Susan,

We refer to your email of 25.06.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]
Sent: Tuesday, 25 June, 2019 9:28 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: Re: SNM19D202927/TANKL - Accident Involving GY9032J with XD3015H on 22/06/2019

Hi Mr Tan,

We are selected Mr Xing Guo Qiang

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Susan
Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477

On Mon, 24 Jun 2019 at 17:53, Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com> wrote:

Without Prejudice

Dear Susan,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

Regards

Tan Kah Leong

Assistant Executive

Claims Department

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

1196N

Vehicle Details

Vehicle No.:

GY9032J

Vehicle to be Exported:

Yes

Intended Deregistration Date:

31 Dec 2019

Vehicle Make:

MITSUBISHI

Vehicle Model:

FB511BOJSRDE

Primary Colour:

White

Manufacturing Year:

2005

Engine No.:

4M40GX7432

Chassis No.:

FB511BA47864

Maximum Power Output:

-

Open Market Value:

\$18,518.00

Original Registration Date:

21 Sep 2005

First Registration Date:

21 Sep 2005

Transfer Count:

0

Actual ARF Paid:

\$926.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

20 Sep 2020

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

PQP Paid:

\$24,768.00

COE Rebate Amount:

\$3,577.00

Total Rebate Amount:

\$3,577.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 24 Jun 2019

OK

8500
3877
1923
~~1.8k~~
1.8k

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002903

Date : 15/07/2019
Vehicle Num. : GY9032J
Make/Model : MITSUBISHI FB 511-2005
Chassis/Eng# : FB511BA47864/4M40GX7432
Accident Date : 22/06/2019
Claim No. :
Reference : XD3015H
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT PANEL <i>bt</i>		2,142.57
2.	1	FRONT GRILLE <i>sea</i>		598.61
3.	1	MITSUBISHI LOGO <i>sea</i>		124.31
4.	1	FRONT BUMPER <i>de</i>		444.40
5.	2	BUMPER BRACKET <i>bt</i>	165.20	330.40
6.	<i>2 pc</i>	HEADLAMP <i>CH-sea</i>	632.93	1,265.86 X
7.	2	SIGNAL LAMP <i>sea</i>	263.09	526.18
8.	1	AIR-CON HEATER <i>?</i>		1,072.46
9.	1	BLOWER ASSY <i>?</i>		1,090.55
10.	1	AIR DUCT <i>?</i>		393.34
11.	1	WEATHERSTRIP, WINDSHIELD <i>sea</i>		500.83
List Total S\$:				8,489.51
25.00% Discount S\$:				2,122.38
				6,367.13
NETT ITEMS :				
1.	2	NUMBER PLATE <i>xan</i>	20.00	40.00
2.	2	REAR DOOR ASSY <i>repair</i>	1,500.00	3,000.00
3.	1	CONTAINER LOCK <i>xan</i>		450.00
4.	1	REAR STEP BRACKET <i>bt</i>		450.00
5.	2	RUBBER STOPPER <i>cut</i>	120.00	240.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002903

Date : 15/07/2019
Vehicle Num. : CY9032J
Make/Model : MITSUBISHI FB 511-2005
Chassis/Eng# : FB511BA47864/4M40GX7432
Accident Date : 22/06/2019
Claim No. :
Reference : XD3015H
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
6.	2	T LOCK <i>HA</i>		
7.	2	LOGO <i>na</i>		
3975.17 1107.00 1520.00 6602.17 20% 5281.73 Repair limit \$1,800				
1230 -10% 1107				
70.00 450.00				140.00 900.00
Nett Total S\$: 10.00% Discount S\$:				5,220.00 522.00
				4,698.00
LABOUR :				
TO REMOVE/REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS				120.00
TO REMOVE/REFIT DASHBOARD TO FACILITATE REPAIRS				280.00
TO DISMANTLE/REPLACE AIR-CON HEATER AND BLOWER TO TOP-UP GAS				150.00
TO PANEL BEAT/REPAIR FR /RR BODY				1,800.00
TO DISMANTLE/REPLACE THE ABOVEMENTIONED PARTS				850.00
SPRAY PAINTING				200.00
TO APPLY NEW LOGO				1520
LOSS OF USE : 12 DAYS @ \$ 120/DAY				3,400.00
Labour Total S\$:				
4/5 15/07/19 @ 1710 Ready after repair				
Total S\$:				14,465.13

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119011149/R1QD3N2

Date: 13/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN14325718044	
Claimant Vehicle No :	GY9032J	Insured Vehicle No :	XD3015H	
Date of Loss:	22/06/2019	Nature of Claim:	TP	Claim No: SNM19D202927C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY9032J	Engine No:	4M40GX7432
Make & Model:	MITSUBISHI FB511BOJSRDE, 2.8 D (M)	Chassis No:	FB511BA47864
Reg. Date:	21/09/2005 (Man. Year: 2005)	Odometer:	611899 km
Colour:	Red		
Engine Capacity:	2835 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	185R13 (D)
Front Left Side:	Austone 7 mm	Rear Left Side:	Austone 5/5 mm
Front Right Side:	Austone 7 mm	Rear Right Side:	Austone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,065.13	5,082.17	5,982.96	54.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,520.00	1,880.00	55.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,465.13	6,602.17	7,862.96	54.36
Approved Total (Overridden) (\$\$)		1,800.00		
(\$\$)	14,465.13	1,800.00	12,665.13	87.56
+ GST 7.00/7.00% (\$\$)	1,012.56	126.00	886.56	87.56
Nett Amount (\$\$)	15,477.69	1,926.00	13,551.69	87.56

INSPECTION

Date of Assignment:	25/06/2019	
Date Inspected:	15/07/2019	Inspected At: Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park Singapore 638129
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Aug 2019)	
Parts:	N/A	MITSUBISHI FB511BOJSRDE 2.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY9032J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Bent	2,142.57 FL	*2,142.57 FL
2	1		*FRONT GRILLE	Scratched	598.61 FL	*598.61 FL
3	1		*MITSUBISHI LOGO	Scratched	124.31 FL	*124.31 FL
4	1		*FRONT BUMPER	Deformed	444.40 FL	*444.40 FL
5	2		*BUMPER BRACKET	Bent	330.40 FL	*330.40 FL
6	1		*HEADLAMP	N/s Scratched	1,265.86 FL	*632.93 FL
7	2		*SIGNAL LAMP	Cracked	526.18 FL	*526.18 FL
8	1		*AIR-CON HEATER	Not Necessary	1,072.46 FL	*- FL
9	1		*BLOWER ASSY	Not Necessary	1,090.55 FL	*- FL
10	1		*AIR DUCT	Not Necessary	393.34 FL	*- FL
11	1		*WEATHERSTRIP,WINDSHIELD	Necessary	500.83 FL	*500.83 FL
12	2		*NUMBER PLATE	Not Necessary	40.00 FN	*- FN
13	2		*REAR DOOR ASSY	Repair	3,000.00 FN	*- FN
14	1		*CONTAINER LOCK	Not Necessary	450.00 FN	*- FN
15	1		*REAR STEP BRACKET	Bent	450.00 FN	*450.00 FN
16	2		*RUBBER STOPPER	Cut	240.00 FN	*240.00 FN
17	2		*T LOCK	Bent	140.00 FN	*140.00 FN
18	2		*LOGO	Necessary	900.00 FN	*400.00 FN

F=Franchise part, L=ListItemDisc, N=NettItemDisc.

Sub Total (S\$)	13,709.51	6,530.23
- List Item Discount on L Items 25.00/25.00% (S\$)	2,122.38	1,325.06
- Nett Item Discount on N Items 10.00/10.00% (S\$)	522.00	123.00
Total Parts (S\$)	11,065.13	5,082.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE/REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS	New	120.00	120.00
2	TO REMOVE/REFIT DASHBOARD TO FACILITATE REPAIRS	New	280.00	0.00
3	TO DISMANTLE/REPLACE AIR-CON HEATER AND BLOWER TO TOP-UP GAS	New	150.00	0.00
4	TO PANEL BEAT/REPAIR FR/RR BODY.TO DISMANTLE/REPLACE THE ABOVEMENTIONED PARTS	New	1,800.00	700.00
5	SPRAY PAINTING	New	850.00	600.00
6	TO APPLY NEW LOGO	New	200.00	100.00
Gross Labour Cost (\$\$)			3,400.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >