

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19011170/R1sd3s2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 10-07-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4090Y	Veh. Inspected	SHC 7793M
Policy No.		Coverage (\$)	0.00
Claim No.	D19004049MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	25/06/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA NF 2.0 A	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KMHET41VMDA834562	Colour	YELLOW
Odometer	650208	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	TRIANGLE	6 mm
L/H Front Tyre	215/60R16	TRIANGLE	6 mm
R/H Rear Tyre	215/60R16	TRIANGLE	6 mm
L/H Rear Tyre	215/60R16	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/06/2019	Inspection Date	25/06/2019
Survey held at	31 CORPORATION ROAD		
Repairer	DING AUTOMOTIVE PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7793M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	523.93	523.93
1	REAR BUMPER REINF	CRACKED	462.30	462.30
1	REAR BUMPER RETAINER LHS	SERVICEABLE	42.68	-
1	REAR BUMPER RETAINER RHS	SERVICEABLE	42.68	-
1	REAR BUMPER BRACKET LHS	BENT	79.75	79.75
1	REAR BUMPER BRACKET RHS	BENT	79.75	79.75
1	REAR BUMPER SPONGE	CRACKED	102.96	102.96
1	REAR BUMPER LWR EXT	SERVICEABLE	40.70	-
1	REAR BUMPER PROTECTOR LHS	SERVICEABLE	102.96	-
1	REAR BUMPER PROTECTOR RHS	SERVICEABLE	102.96	-
1	BOOTLID	BENT	1,139.00	1,139.00
1	BOOTLID EMBLEM - LOGO	NECESSARY	21.45	21.45
1	BOOTLID EMBLEM - HYUNDAI	NECESSARY	20.13	20.13
1	BOOTLID EMBLEM - SONATA	NECESSARY	40.92	40.92
1	BOOTLID MECHANISM	NECESSARY	25.13	25.13
1	BOOTLID HINGE LHS	SERVICEABLE	140.80	-
1	BOOTLID HINGE RHS	SERVICEABLE	140.80	-
1	BOOTLID LOCK	BENT	109.45	109.45
1	BOOTLID LOCK CATCH	SERVICEABLE	108.90	-
1	BOOTLID INSULATOR	SERVICEABLE	155.10	-
1	BOOTLID RUBBER BEADING	NECESSARY	91.30	91.30
1	REAR END PANEL	BENT	423.29	423.29
1	REAR END PANEL TOP GARNISH	DEFORMED	42.02	42.02
1	TAIL LAMP PANEL LHS	SERVICEABLE	267.30	-
1	TAIL LAMP PANEL RHS	SERVICEABLE	267.30	-
1	REPAIR SPARE TYRE PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	TAIL LAMP RHS	SERVICEABLE	323.40	-
	LESS 20% DISCOUNT		-979.40	-632.28
			3,917.56	2,529.10

Report Ref No. CS/FCI19011170/R1sd3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	230.00	200.00
1	REAR BUMPER ADS STICKER (SN)	NECESSARY	120.00	120.00
1	REAR BUMPER RUBBER PROTECTOR PAD (SN)	DEFORMED	120.00	50.00
1	BOOTLID STICKER - CAB BOOKING 65521111 (SN)	NECESSARY	85.00	60.00
1	BOOTLID STICKER - CITYCAB (SN)	NECESSARY	85.00	60.00
1	BOOTLID ADS STICKER (SN)	NECESSARY	120.00	80.00
1	SET BOOTLID INSULATION CLIPS (SN)	NECESSARY	35.00	35.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			895.00	675.00
	<u>LABOUR</u>			
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL.		1,000.00	700.00
	RUST PROOFING.		60.00	60.00
	REMOVE & REFIT SPARE TYRE & CARPET & SIDE TRIM & HOLDER SPONGE.		50.00	40.00
	ALIGNMENTS TAILGATE.	NOT NECESSARY	50.00	-
	REMOVE & REFIT BOOTLID COMPONENTS.		80.00	60.00
	REMOVE & RE-DRILL REVERSE SENSOR & ADJUSTMENT ANGLE.		30.00	30.00
	RESPRAY BOOT LID INNER & OUTER.		230.00	200.00
	RESPRAY REAR BUMPER.		200.00	180.00
	RESPRAY REAR END PANEL.		200.00	180.00
			1,900.00	1,450.00
	GRAND TOTAL		6,712.56	4,654.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00

Report Ref No. CS/FC119011170/R1sd3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.