

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19011196/T1EA3Q2

Date: 08/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100415846

Claimant
Vehicle No : SKU6139D **Insured Vehicle No :** SGS7788G

Date of Loss: 21/06/2019 Nature of Claim: TP Claim No: 0707653548SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU6139D	Engine No:	1ZRX514362
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104534011
Reg. Date:	05/08/2015 (Man. Year: 2015)	Odometer:	46386 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,851.62	2,244.79	2,606.83	53.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	1,320.00	800.00	37.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,971.62	3,564.79	3,406.83	48.87
Approved Total (Overridden) (S\$)		2,850.00		
Nett Amount (S\$)	6,971.62	2,850.00	4,121.62	59.12
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,457.45		

INSPECTION

Date of Assignment: 24/06/2019

Date Inspected: 24/06/2019 Inspected At:

Perfect Werkz (HQ)
NO. 25 KAKI BUKIT ROAD 4 #06-51
SYNERGY @ KB
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -LH	Bent	707.40 F	*707.40 FL
2	1		*FRONT FENDER INNER GARNISH -LH	Deformed	127.20 F	*127.20 FL
3	8		*FRONT FENDER INNER GARNISH CLIPS	Necessary	103.20 F	*103.20 FL
4	1		*FRONT L/H FENDER SIGNAL LAMP	Not Necessary	43.55 F	*- FL
5	1		*FRONT L/H DOOR INNER LOCK	Not Necessary	289.90 F	*- FL
6	1		*FRONT L/H DOOR INNER GEAR MOTOR ASSY	Not Necessary	372.40 F	*- FL
7	1		*REAR L/H DOOR	Bent	1,081.40 F	*1,081.40 FL
8	1		*REAR L/H SHOCK ABSORBER	Not Necessary	485.00 F	*- FL
9	1		*REAR L/H LOWER ARM	Not Necessary	287.72 F	*- FL
10	1		*REAR L/H KNUCKLE ARM	Necessary	281.85 F	*281.85 FL
11	1		*REAR L/H KNUCKLE ARM BEARING	Bent	212.00 F	*212.00 FL
12	1		*FRONT SPORT RIM -LH	Cut	480.00 F	*480.00 FL
13	1		*FRONT TYRE LH	Not Necessary	380.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,851.62	2,993.05
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	748.26

Total Parts (\$\$)	4,851.62	2,244.79
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL CUSHION	New	100.00	0.00
2	TO REMOVE & INSTALL LH FRONT DOOR	New	220.00	60.00
3	TUFF KOTE	New	120.00	30.00
4	TO WHEEL ALIGNMENT COMPUTER	New	120.00	80.00
5	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	280.00	120.00
6	TO CHECK WIRING SYSTEM	New	80.00	30.00
7	PANEL BEATING	New	600.00	500.00
8	SPRAY PAINTING	New	600.00	500.00
Gross Labour Cost (\$\$)			2,120.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >