



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

LIVESTAGE SHOWBIZ PRODUCTIONS LLP

25/06/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP ALG
Khanchan

Accident date: 25/06/2019

Estimated repair cost for vehicle no: GBF4609M TOYOTA HIACE DX 3.0 '16

CHASSIS NO: KDH2010203667

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front R/H Door <i>Repair</i>		\$1,217.45 <i>+</i>
2	1	Front R/H Door Sticker <i>New</i>		\$35.00 <i>✓</i>
3	1	Front R/H Door Pillar Outer <i>Dented</i>		\$631.40 <i>✓</i>
4	1	Front R/H Hub Cap <i>New</i>		\$180.00 <i>+</i>
5	1	R/H Center Sliding Door <i>Dented</i>		\$1,712.10 <i>✓</i>
6	1	Rear R/H Fender <i>Repair</i>		\$1,712.45 <i>+</i>
7	1	Rear R/H Hub Cap <i>hit</i>		\$180.00 <i>60 (SW)</i>

2378.50

S.N: 60

1783.87

Subtotal :-

\$5,668.40

Labour charges

To check wheel alignment computer

\$150.00 *80*

To check wiring

\$100.00 *30*

Tuff kote

\$150.00 *+*

Panel beating

1310 \$1,000.00 *500*

Spray painting

\$1,800.00 *700*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal:- \$3,200.00

Total:- \$8,868.40

2.5K

total 3153.87
y/s: 2.5K
04 Days