

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2545X

MAKE :

MODEL : HYUNDAI i40

DATE : 24.06.2019

TEL : 6542 5119

FAX : 6542 6039

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>Dented</i>			\$ 2,265.90	✓
	Bonnet Hinge (LH/RH) <i>6t</i>		\$ 41.00	\$ 82.00	✓
	Bonnet Insulator <i>NN</i>			\$ 196.50	X
	Bonnet Insulator Clips <i>NN</i>			\$ 8.40	X
	Radiator Grille <i>NN</i>			\$ 251.00	X
	Radiator Grille H Emblem <i>NN</i>			\$ 27.50	X
	Front Bumper Cover <i>broken</i>			\$ 544.50	✓
	Front Bumper Sponge <i>NN</i>			\$ 99.20	X
	Front Bumper Reinforcement <i>NN</i>			\$ 402.10	X
	Front Bumper Grille (RH) <i>distorted</i>			\$ 41.60	✓
	Front Bumper Bracket Top (RH) <i>NN</i>			\$ 22.40	X
	Front Bumper Bracket (RH) <i>broken</i>			\$ 24.60	✓
	Headlamp Support Top Cover <i>NN</i>			\$ 222.60	X
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40	✓
	Headlamp (RH) <i>broken</i>			\$ 1,388.00	✓
	Headlamp Halogen Bulb (RH) <i>NN</i>			\$ 14.40	X
	Radiator Expansion Tank <i>NN</i>			\$ 28.30	X
	Front Fender (RH) <i>Buc</i>			\$ 663.00	✓
	Front Fender Apron Panel (RH) <i>Dented</i>			\$ 637.00	✓
	Front Fender Shield (RH) <i>turn</i>			\$ 174.90	✓
	Front Door Mirror Assy (RH) <i>broken</i>			\$ 670.00	✓
	Rocker Panel Outer Garnish <i>NN</i>			\$ 341.40	X
	Front Pillar Upper Cover/Garnish <i>cut / 1st</i>			\$ 83.50	✓
	Front Windscreen Glass <i>broken</i>			\$ 1,017.80	✓
	Front Windscreen Moulding <i>NCC</i>			\$ 113.30	✓
	Front Windscreen Pillar Outer (RH) <i>Dented</i>			\$ 1,745.50	✓
	Wiper Container <i>damaged</i>			\$ 61.90	✓
	Wiper Container Motor <i>Down</i>			\$ 75.00	✓
	Front Wheel Rim (RH) <i>1st</i>			\$ 325.30	✓
	Front Wheel Hub Cap (RH) <i>distorted</i>			\$ 107.10	✓
	Front Wheel Bearing <i>Down</i>			\$ 540.50	✓
	Front Shock Absorber (Assy) (RH) <i>distorted</i>			\$ 342.20	✓
	Front Shock Absorber Mounting (RH) <i>NN</i>			\$ 108.80	X
	Front Drive Shaft (RH) <i>Down</i>			\$ 1,030.80	✓
	Rack & Pinion Assy <i>Down</i>			\$ 1,191.30	✓
	STG Tie End <i>distorted</i>			\$ 62.60	✓
	Stabilizer Bar <i>distorted</i>			\$ 252.30	✓
	Stabilizer Bar Bush (RH) <i>NN</i>			\$ 16.40	X
	Stabilizer Bar Link <i>distorted</i>			\$ 61.10	✓
	Stabilizer Bracket <i>NN</i>			\$ 24.00	X
	Front Suspension Lower Arm (RH) <i>1st</i>			\$ 529.30	✓
	Knuckle Arm (RH) <i>distorted</i>			\$ 552.00	✓
	Engine Under Cover <i>NN</i>			\$ 334.60	X
	Engine Crossmember <i>Dented</i>			\$ 2,094.40	✓
	ABS Sensor (RH) <i>NN</i>			\$ 234.00	X

SHC 2545X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	SUB TOTAL		17584.80	\$ 19,916.40
	LESS 20%			\$ 3,983.28
	DISCOUNTED TOTAL		14067.84	\$ 15,933.12
	Front Fender Advertisement Logo (RH) <i>NCC</i>			\$ 100.00 <i>Nett ✓</i>
	Front Door Comfort Logo (RH) <i>NCC</i>			\$ 75.00 <i>Nett ✓</i>
	Front Door Advertisement Logo (RH) <i>NCC</i>			\$ 100.00 <i>Nett ✓</i>
	Front Windscreen Sealant <i>NCC</i>			\$ 46.00 <i>Nett ✓</i>
	Front ERP Sticker <i>NCC</i>			\$ 26.00 <i>Nett ✓</i>
	Front Tyre (RH) <i>provided 50% depreciation</i>			\$ 216.00 <i>Nett ✓</i>
	Gearbox Assy <i>NH</i>		455.00	\$ 8,000.00 <i>Nett X</i>
				\$ 8,563.00
	Labour Charge			\$ 2,000.00 <i>1000/-</i>
	Panel Beating			\$ 1,750.00 <i>1000/-</i>
	Spray Painting Charge			\$ 50.00 <i>30/-</i>
	Wiring Charge			\$ 100.00 <i>40/-</i>
	Tuff Kote			\$ 50.00 <i>NH</i>
	Towing Charge			\$ 200.00 <i>150/-</i>
	Remove/Refix Undercarriage (FR)			\$ 120.00 <i>60/-</i>
	FRT Wheel Alignment			\$ 150.00 <i>NH</i>
	Remove/Refix Aircon & Re-fill Gas			\$ 450.00 <i>NH</i>
	Remove/Refix Gearbox			\$ 450.00 <i>240/- 150/-</i>
	Remove/Refix Dashboard			\$ 120.00 <i>80/-</i>
	Remove/Refix Front Windscreen Glass			\$ 90.00 <i>NH</i>
	Remove/Refix Cushion & Upholstery Front			\$ 200.00 <i>150/-</i>
	Re-set Frt ABS System			\$ 200.00
	Re-set Frt Power Window System			\$ 480.00
	Diagnostic & Resetting To Erase Fault Code			
	TOTAL LABOUR		2660.00	\$ 6,410.00
	ESTIMATE TOTAL			\$ 30,906.12
			17584.80	
			17182.84	
			4813700/-	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.